

INVOICE

BILL TO ROY SPALDING

ACTIVITY	QTY	RATE	AMOUNT
Labor REMOVED ALL NECESSARY COMPONENTS AND DISASSEMBLED ENGINE, CHECKED AND REPLACED LINERS, PISTONS, CLEANED CRANKSHAFT, REPLACED ROD AND MAIN BEARINGS, AND OIL PUMP. ASSEMBLED ENGINE, REPLACED TURBO, HEAD, INJECTORS, INJECTION PUMP. REPLACED FRONT ENGINE SEAL AND WATER PUMP. REPLACED OIL, FUEL AND COOLANT FILTERS, FILLED WITH OIL AND COOLANT. REMOVED AND REPLACED HOOD SHOCKS, INSTALLED FOUR LOCKING WASHERS ON HOOD HINGES, REMOVED AND REPLACED MFD DRIVE U-JOINTS. (7140 SER# JJA0012314) HRS 4076	1		
Labor:PARTS FRONT SEAL	1		
Labor:PARTS LOCKS	1		
Misc Supplies MISC SHOP SUPPLIES	1		
Services:Mileage SERVICE CALL MILEAGE	1		
Labor:PARTS ************************************	1		
Labor:PARTS ******* OHCS7150D-O OVERHAUL KIT *******	1		
Labor:PARTS ******* AMJ925644 CYLINDER HEAD ASSEMBLY *******	1		
Labor:PARTS ******* AMJ930338 OIL PUMP *******	1		

ACTIVITY	QTY	RATE	AMOUNT
Labor:PARTS ******** AMJ908507 INJECTOR ********	6		
Labor:PARTS ******** AM3524034 TURBO ********	1		
Labor:PARTS ******** AMJ802975 WATER PUMP *******	1		
Labor:PARTS ******** AMP7140-PES INJECTION PUMP ********	1		
Labor:PARTS ******** AM1280263C1 GAS STRUT DOOR ********	1		
Labor:PARTS ******** AM1968168C3 GAS CYLINDER HOOD ********	1		
described and the second secon	15 10 10 10 10 10 10 10 10 10 10 10 10 10	A	
THANK YOU FOR YOUR BUSINESS! EIN# 81-2961179	BALANCE DUE	\$6,	874.44