

	DOS:	4/16/2013
--	------	-----------

DOS:	4/16/2013
------	-----------

Vehicle	Make/Mod:	Dodge 3500	
	VIN:	3B6MF3668YM218259	
	Year:	2000	
	Miles:	136,946	
		<u>PRICE</u>	<u>AMOUNT</u>

		Year: 2000		
		Miles: 136,946		
<u>UNITS</u>	<u>PARTS</u>	<u>PRICE</u>	<u>AMOUNT</u>	
1	1 Truck Died and Wont Start Back. Find ECM Bad			
1	2 Installed Old ECM on it			
1	3 Had to Reprogrammed Old ECM to New Engine.			
		Subtotal=	\$300.00	

1	Labor is charged per hour. (Diagnostic is considered atleast 1 hour labor.)		
NOTES: ECM Numbers for ECM That's Programmed on Truck/ P/N 3946242. S/N 2054939. D/C 03/16/00. ESN 56701460. ECM Code J90303.05. Programmed To The Lastest Cailbration ECM Code J90303.07,			
		5.225%	Tax=
		TOTAL-	\$350.00

DOS: 1/14/2013

Vehicle Make/Mod:	Dodge 3500
VIN:	3B6MF3668YM218259
Year:	2000
Miles:	136,067

<u>UNITS</u>	<u>PARTS</u>	<u>PRICE</u>	<u>AMOUNT</u>
1	1 R&R Cummins Engine		
1	2 Renewed Low Pressure Fuel Pump NAPA (P74213)		
1	3 Renewed Water Pump Gasket (35525)		
1	4 Renewed T-Stat and Gasket (375-190)		
1	5 Renewed Front Timing Cover Gasket (TCS45994)		
1	6 Renewed Oil Pan Gasket (OS30694)(765-1224)		
1	7 Renewed Clutch NAPA (1105092)		
1	8 Had Flywheel Turned at NAPA (Shop Labor)		
3	9 Renewed Oil and Filter 15w-40 Rotella (1607)(56026)		
3	10 Flushed Cooling System (ZXC0-2)		
1	11 Renewed Fuel Filter (3585XE)		
1	12 Resealed Intake Manifold (MS95087)		
2	13 ATF +4 Power Steering Fluid (75-206)		
S			

20	Labor is charged per hour. (Diagnostic is considered atleast 1 hour labor.)
----	------------------------------------------------------------------------------------

NOTES: Customer Supplied Own Parts From NAPA.

5.225%

TOTAL-

\$1,000.00

1/14/2013 14:55

QUAN.		DESCRIPTION
1		29V Cummins
2		motor
3		
4		
5		
6		
7		replacement
8		motor for
9		DD Dodge 3500
10		county truck

TAX	
TOTAL	800 ⁰⁰