

Invoice

Date	Invoice #
1/23/2018	2018-0145

Bill To
BuiltWell Construction


Serviced by:	Ordered by	P.O. # / Project	Terms	Lease
Wade	Wade	(4) scissor lift tires	Due on receipt	

Serviced	Quantity	Description	Price/Rate	Amount
1/23/2018	4	pcs- 10/ 16.5 Carlisle Trac Tires Mounted		

for projects left after 14 days. There is a 90 warranty on materials & workmanship.

Sales Tax (8.75%)	
Total	\$658.15





SOLD TO
CASH SERVICE THANK YOU FOR YOUR B
SERVICE

SHIP TO
WADE MCCARDY

Sold By: [redacted] SN: [redacted] HR .0 W:00
Ship By: [redacted] PO #: WADE MCCARDY Date 6/25/18 WORK ORDER [redacted]
Tax #: [redacted] 8:27:28

Tax	D	Qty	Description	Price	Amount
LABOR CUSTOMER					
					** TOTAL LABOR CUSTOMER
PARTS MISC					
B		1	6270 AIR FILT	[redacted]	[redacted]
B		1	1348 OIL FILT	[redacted]	[redacted]
B		4	104 SPARK PLUG	[redacted]	[redacted]
B		1	3002 FUEL FILT	[redacted]	[redacted]
B		5	UNLEADED GAS	[redacted]	[redacted]
B		14	864632 OIL DEXTON	[redacted]	[redacted]
B		25	687621 ZIP TIES	[redacted]	[redacted]
B		1	121108 KIT	[redacted]	[redacted]
					** TOTAL PARTS MISC
SHOP INVOICE					
B		2	DAY 108067 COUPLING	[redacted]	[redacted]
B		26	DAY 1901213 HOSE	[redacted]	[redacted]
B		3	DAY 108075 COUPLING	[redacted]	[redacted]
B		2	DAY 108609 COUPLER	[redacted]	[redacted]
B		20	DAY 1901215M1 HOSE	[redacted]	[redacted]
B		3	DAY 108075 COUPLING	[redacted]	[redacted]
B		288	DAY 1901215M1 HOSE	[redacted]	[redacted]
B		1	DAY 108609 COUPLER	[redacted]	[redacted]
B		1	CAS 9611973 FILTER, FUE	[redacted]	[redacted]
B		1	CAS 73341710 10W30 GAL	[redacted]	[redacted]
B		4	DAY 108075 COUPLING	[redacted]	[redacted]
B		410	DAY 1901215M1 HOSE	[redacted]	[redacted]
B		149	DAY 1901213 HOSE	[redacted]	[redacted]
B		2	DAY 108067 COUPLING	[redacted]	[redacted]
					** TOTAL SHOP INVOICE
SHOP SUPP SALES					
B		5% EPA & SHOP MISA CHARGES		[redacted]	[redacted]
TRUCK RECEIPTS					
B		2 HAULING TWO TRIPS		[redacted]	[redacted]

NOTES
Skyjack SJ8831 came in for oil leaks and tune-up. Removed steering cylinder and installed new kit. Replaced numerous hydraulic hose that went all over the place. Serviced engine, replaced engine oil and filter, air and fuel filters. Replaced spark plugs and filled hydraulic tank with dextron oil. Ran machine and checked for leaks. two main lift cylinders still leaking.

Purchaser is engaged in farming or ranching and certifies that these parts or equipment will be used only in farming or ranching. No returns on electrical items. There is a \$20.00 service charge on all after hours calls.

** SUBTOTAL [redacted]

PAY THIS AMOUNT \$1907.67