

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: **1194156**

Invoice Date: 9/29/2015

Location: 8

Work Order Number:

Payment Type:

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Mob Phone:

Mob Phone:

Page: 1 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

//9500 CMBW334 Retail

CORRECTION:

01- Combine PerforMax Inspection (Walker)

3364 Engine Hours

2517 Separator Hours

PERFORM COMPLETE INSPECTION. ADJUST ALL CHAINS AND BELTS.
CHECK ALL FLUID LEVELS. RUN THE MACHINE BEFORE AND AFTER
REPAIRS.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
S4906	Service Promotion	1.00	0.00			N

Comments: Labor discount with winter inspection

Labor:

//9500 CMBWPU* Retail

CORRECTION:

02- Customer furnished transportation

\$100.00 Credit when customer brings equipment in & back for scheduled Winter Service versus PLP hauling.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
S4906	Service Promotion	1.00	0.00			N

Labor: \$0.00

Parts: \$0.00

OL&M: \$0.00

Mis

GEN-3 Retail

CORRECTION:

03- Feeder house, Recondition (Feeder house already removed)

REMOVE AND REPLACE THE FEEDER HOUSE CONVEYOR CHAIN. REMOVE AND REPLACE DRIVE SPROCKETS AND
BEARINGS ON TOP SHAFT. REMOVE AND INSTALL FRONT DRUM AND REPLACE BEARINGS, SHAFT, AND ARMS.
REMOVE THE UPPER PLASTIC WEAR STRIPS, WELD NUTS ON, AND INSTALL UPDATED STYLE WEAR STRIPS.
REMOVE AND REPLACE SLIP CLUTCH PARTS. ADJUST THE DRUM HEIGHT.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7783	SCREW					
24M7101	WASHER					

CONTINUED ON NEXT PAGE

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN	ALDERMAN CATTLE & GRAIN	Invoice Number: 1194156
		Invoice Date: 9/29/2015
		Location: 8
		Work Order Number:
		Payment Type:
Bus Phone	Bus Phone:	
Prv Phone:	Prv Phone:	
Mob Phone:	Mob Phone:	
		Page: 2 of 9
		Technician Number: T858

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9500	3364	H09500X661013	61796W	

GEN-3 Retail

45M7040	PIN FASTEN
AH126091	ARM
AH137630	CHAIN LINK
AH207777	CONVEYOR
H101677	JAW
H105590	HUB
H118583	CHAIN SPRO
H118776	SET SCREW
H123734	Shaft
H131087	BUSHING
H171960	STRIP
H99303	WASHER
JD10020	BALL BEARI
JD8551	ECCENTRIC
JD8552	BALL BEARI
JD9373X	AFTER MARKET JD9373

Labor**//9500 CMB29* Retail****CORRECTION:**

04- Concave and cylinder barS, Replace (INCLUDES FH R&R)

REMOVE AND INSTALL THE FEEDER HOUSE. REMOVE AND REPLACE CYLINDERS BARS AND CONCAVE. ADJUST CONCAVE TO LEVEL AND SET GAP BETWEEN BARS AND CONCAVE. ADJUST INDICATOR TO ZERO.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH120502	PLATE	1.00	222.00			N
AH150497	CONCAVE					N

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: 1194156

Invoice Date: 9/29/2015

Location: 8

Work Order Number: 185960

Payment Type:

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Mob Phone:

Mob Phone:

Page: 3 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

//9500 CMB29* Retail

AH151119 ANGLE

AH205119 RASP BAR

AH205120 RASP BAR

AH205781 KIT

H148021 HINGE

Labor:

//9500 CMBW371 Retail

CORRECTION:

05- Tailings elevator, Recondition

REMOVE AND INSTALL THE TAILINGS ELEVATOR. REMOVE AND REPLACE THE PADDLE CHAIN. REMOVE AND REPLACE THE TOP AND BOTTOM SPROCKETS, BEARINGS AND KEY. REMOVE AND REPLACE THE RUBBER PADDLES ON THE IMPELLER.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH131074	LINK CHAIN					
H131639	PADDLE					
H134603	CHAIN SPRO					
JD39103X	AFTER MARKET JD39103					
JD9313	BALL BEARI					

Labor:

GEN-6 Retail

CORRECTION:

06- Clean grain elevator, Recondition

REMOVE AND REPLACE THE ELEVATOR CHAIN AND SPROCKETS. REMOVE AND REPLACE BEARINGS ON THE LOWER AUGER. REMOVE AND REPLACE BEARINGS AND SHAFT ON THE TOP. CUT OUT A PATCH FOR THE LOWER ELEVATOR BOOT SIDE AND WELD INTO PLACE.

CONTINUED ON NEXT PAGE->

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN	ALDERMAN CATTLE & GRAIN	Invoice Number:	1194156	
		Invoice Date:	9/29/2015	
		Location:	8	
		Work Order Number:		
		Payment Type:		
Bus Phone: 620-257-3091	Bus Phone	Page:	4 of 9	
Prv Phone: 620-257-3091	Prv Phone:	Technician Number:	T858	
Mob Phone:	Mob Phone:			
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9500	3364	H09500X661013	61796W	

GEN-6 Retail

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
49M6480	SHAFT KEY					N
AH162441	LINK CHAIN					N
H133143	CHAIN SPRO					N
H135713	SHAFT					N
H177988	SPROCKET S					N
JD39102X	AFTER MARKET JD39102					N
JD39103X	AFTER MARKET JD39103					N

Labor:**//9500 CMBW12 Retail**

CORRECTION:

07- Feeder house primary drive belt, Replace

REMOVE AND REPLACE THE FEEDER HOUSE PRIMARY DRIVE BELT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH139436	BELT SET					
H129208	PIVOT					
H151952	V-BELT					

Labor:**//9500 CMBW41 Retail**

CORRECTION:

08- Straw chopper front drive belt, Replace

REMOVE AND REPLACE THE FRONT STRAW CHOPPER DRIVE BELT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: **1194156**

Invoice Date: 9/29/2015

Location: 8

Work Order Number:

Payment Type:

Bus Phone: 620-257-3091

Bus Phone: 620-257-3091

Prv Phone: 620-257-3091

Prv Phone: 620-257-3091

Mob Phone:

Mob Phone:

Page: 5 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

//9500 CMBW41 Retail

H125380

V-BELT

N

Labor:

//9500 CMBW40 Retail

CORRECTION:

09- Straw chopper countershaft drive, Recondition

REMOVE AND REPLACE THE STRAW CHOPPER JACKSHAFT BEARINGS, FLANGES AND SHAFT.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH139296X	AFTERMARKET VERSION OF AH139296					
AH163686	PRESSED FL					
H135410	PRESSED FL					
H137570	JACKSHAFT					

Labor:

//9500 CMBW266 Retail

CORRECTION:

10- Unloading auger vertical auger gear case, Recondition

REMOVE AND INSTALL THE UNLOADING AUGER DRIVE SUMP AND REPLACE BEARINGS, SHAFT, AND SEAL.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
24H1533	SHIM					
AH90963	SEAL					
AH96585	BALL BEARI					
H149361	LOCK NUT					
H215085	SHAFT					
H217963	SEALANT					

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: **1194156**

Invoice Date: 9/29/2015

Location: 8

Work Order Number:

Payment Type:

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Mob Phone:

Mob Phone:

Page: 6 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

//9500 CMBW266 Retail

JD8524

BALL BEARI

N

Labor:

//9500 CMBW483 Retail

CORRECTION:

11- Grain tank front cross auger, Replace bearings

REMOVE AND REPLACE THE FRONT CROSS AUGER BEARINGS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD39104X	BEARING					N

Labor:

//9500 CMBW130 Retail

CORRECTION:

12- Rotary screen countershaft bearings, Replace

REMOVE AND REPLACE THE ROTARY SCREEN DRIVE COUNTERSHAFT, BEARINGS, BRACKETS AND BELT. REPLACE THE SCREEN DRIVE PULLEY. REPLACE THE ROTARY SCREEN DOOR SEALS ON THE TOP AND BOTTOM.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH140495	BALL BEARI					N
H118719	HALF SHEAV					N
H123652	PRESSED FL					N
H134528	Countershaft					N
H145158	ROUND BELT					N
H146636	V-BELT					N
JD39102X	AFTER MARKET JD39102					N

Labor: \$

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: **1194156**

Invoice Date: 9/29/2015

Location: 8

Work Order Number:

Payment Type:

Bus Phone:

Bus Phone:

Prv Phone:

Prv Phone:

Mob Phone:

Mob Phone:

Page: 7 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

//9500 CMBW77 Retail

CORRECTION:

14- Radiator, R&R (Send in to radiator shop for repair)

REMOVE THE RADIATOR FOR REPAIR AND INSTALL AFTER REPAIRS. REMOVE ALL OLD SEALS AND INSTALL NEW SEALS AROUND RADIATOR.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH131965	ISOLATOR					N
AH140967	ISOLATOR					N
H134520	SEAL					N
H88769	ISOLATOR					N

Labor:

//9500 CMBW98 Retail

CORRECTION:

15- Drive chains, Replace

REMOVE AND REPLACE ALL DRIVE CHAINS AND ADJUST.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH126007S	DIAMOND 50 CHAIN W/ 124 PITCHES					N
AH126239	ROLLER CHA					N
AH126837S	AH126837 60H X 198					N
AH145029S	AH145029 60CHAIN X 218					N

Labor:

//9500 CMBW825 Retail

CORRECTION:

16- Engine electric fuel pump (by water seperator), R&R

CHECK THE FUEL PUMP VOLTAGE. FOUND THERE WAS 12 VOLTS TO THE PUMP AND GROUND. REMOVE AND REPLACE THE ELECTRIC FUEL PUMP

ALDERMAN CATTLE & GRAIN

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN	ALDERMAN CATTLE & GRAIN	Invoice Number: 1194156
Bus Phone:	Bus Phone:	Invoice Date: 9/29/2015
Prv Phone:	Prv Phone:	Location: 8
Mob Phone:	Mob Phone:	Work Order Number:
		Payment Type:
		Page: 8 of 9
		Technician Number: T858

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9500	3364	H09500X661013	61796W	

//9500 CMBW825 Retail

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH130127	PUMP					N
Labor:						

GEN-17 Retail

CORRECTION:

17- Cleaning fan outer drive sheave stuck on the shaft

THE OUTER FAN DRIVE SHEAVE WILL NOT MOVE ON SHAFT. INSTALL A PULLER AND REMOVE OUTER SHEAVE. CLEAN THE SHAFT AND CHECK FIT OF PULLEY. THE PULLEY WAS LOOSE ON THE SHAFT. INSTALLED A NEW SHEAVE AND BEARING.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH127496	PULLEY					N
AH229175	THROW-OUT					N
Labor:						

GEN-18 Retail

CORRECTION:

18- Cleaning fan speed adjust motor, Replace

CHECK THE FAN SPEED ADJUST OPERATION. FOUND THAT THE MOTOR WAS BAD. REMOVE AND REPLACE FAN SPEED ADJUST MOTOR.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
-------------	-------------	----------	------------	-----------	----------------	-----------

Invoice To Account No: 24070

Deliver To:

SERVICE INVOICE

ALDERMAN CATTLE & GRAIN

ALDERMAN CATTLE & GRAIN

Invoice Number: **1194156**

Invoice Date: 9/29/2015

Location: 8

Work Order Number: -----

Payment Type: -----

Bus Phone: -----

Bus Phone: -----

Prv Phone: -----

Prv Phone: -----

Mob Phone: -----

Mob Phone: -----

Page: 9 of 9

Technician Number: T858

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9500

3364

H09500X661013

61796W

GEN-18 Retail

KXE10059

ACTUATOR KIT

N

Labor: -----

INVOICE CONTAINS

Miscellaneous Charges:

Service Accessories

Finance Information

Customer PO No: -----

Tax Exempt No: -----

Advisor: -----

Labor:

Parts:

OL&M:

Misc:

Sales Tax: -----

Grand Total: **\$19,424.08**

J.D. Reconditioning → \$19,424.08

Add Radiator Repair → \$315.50

\$19,739.58

Ellinwood KS

8/27/2015

TERMS AND CONDITIONS

Repayment Terms: Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction.

The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice.

Up to 120 Days No Payments / No Interest Financing followed by the ANNUAL PERCENTAGE RATE (APR) applicable to your Account.

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Returned goods must be accompanied with this invoice. A 15% handling fee will be charged unless due to defective goods or our error. Goods cut to length or special order goods are not returnable. NO RETURNS OR REFUNDS AFTER 30 DAYS.

Received by: -----

Date: -----