

INVOICE

BILL TO

Darrell Teeter
Teeter Irrigation

RT 660 Astec

INVOICE # 1416**DATE** 11/04/2017**DUE DATE** 11/04/2017**TERMS** Due on receipt

DATE	ACTIVITY	HRS/QTY	RATE	AMOUNT
10/31/2017	Machine Astec RT660 Trencher SN: RT660X64259	1		
10/31/2017	Labor Drive to location, Remove and disassemble trencher lift cylinder. Clean up all parts and inspect for wear. Found the barrel and piston to have excessive wear. Hone out cylinder bore and clean up piston. Install new O-rings and seals, reassemble cylinder and reinstall on to machine. Test repair for leaks and drift down.	5		
10/31/2017	Misc Parts	1		

Customer PO 70281

BALANCE DUE

\$440.00

Thank YOU for your business

INVOICE

BILL TO

Darrell Teeter
Teeter Irrigation

INVOICE # 1379**DATE** 08/27/2017**DUE DATE** 08/27/2017**TERMS** Due on receipt

660 Astec

DATE	ACTIVITY	HRS/QTY	RATE	AMOUNT
07/28/2017	Machine Drive to location, remove chain from trencher. Remove all parts required to gain access to the planetary gear box. Disassemble gear box. install new oil seals and wear rings in gear box. reassemble all removed parts. Fill gearbox with oil. Install trencher chain and run unit to test function of repair.			
07/28/2017	Parts Brake Cleaner, Oil, Grease			
07/28/2017	Misc Parts (deleted)			

PAID

Customer P.O. number. 68305

PAYMENT
BALANCE DUE

639.98
\$0.00

Seals on Planetary

Thank YOU for your business