

Brake Pad

Parts

O&G Rotor - 2Y

Brake Caliper - LT

Brake Pads - LT

Part No

AAA54141DG

AAAC830

AAAMK01068

Qty

Price

Discount

Total

Parts

Parts

Duralast Battery - 3Y

Part No

AAA65-DL

Total

Labor
Parts
Hazmat*
Supplies*
Taxes

Invoice Total

\$4,714.54

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal.

Date	Method	Reference	Amount
10-31-2018	VISA	Paid 10/19/2018	
			Payment Totals
			Balance Due

Authorization

Original Estimate Total:

Authorization Method: ☐ email

☐ text

☐ phone

☐ fax

☐ in person

Date:

Contact Details:

Authorized By:

X

Customer Signature

Save replacement parts for inspection or return? (Core may apply)

☐ Yes

☐ No

Thank you for your business

Arizona Mobile Auto Repair
134 E. Broadway

INVOICE

11698

INVOICE

Northwest Fresh Potato LLC
Josh

Print Date: 06/06/2011
2005 Ford - Pickup F350 Super Duty

6.0L V8 VIN (P)

Lic #: 954CKI

Unit #

Vin #: 1FTWW31P35ED31123

Hat #

Odometer In: 150170

Odometer Out: 150289

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
---------------------------	-----	------	----------	-------------------	----------

Technicians: Warmley, Det. XXX SELECT Technician]

Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on new parts and labor is 1 year or 12,000 miles, whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original repair cost.

Labor:

Parts:

Sublet:

Sub:

Tax:

Total:

Bal Due: \$9,091.36

NATURE

By: _____

Date: _____

Time: _____

INVOICE

Southwest Fresh Potato LLC
Jorda, Josh

2005 Ford - Pickup F350 Super Duty
6.0L V8 VIN (P)
Lic # : 954CKI
Unit # :
Vin # : 1FTWW31P35ED
Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description
BULLET PROOF DIESEL KIT				20 PT COURTESY CHECK-UP Hoses, Fluids, Bulbs, Tires, Check Leaks then advise customer of in maintenance.
BULLET PROOF OIL COOLING Square				COMPLETE BULLET PROOF STUDS INSTALL- INSTALL BULLET PROOF OIL COOLING BULLET PROOF EGR COOLING NECESSARY PARTS INVOLVED COMPLETE BULLET PROOF CYLINDER HEADS, INSTALL SET, REINSTALL HEADS
HEAD STUDS, ARP				MACHINE SHOP- MAGNIFLUX HEADS FOR PRESSURE TEST CYLINDER INSTALL HARDENED VALVE VALVE JOB AND RESURFACING HEADS
CYLINDER HEAD GASKET - Super Duty, F350 Super Duty - 1 Right				FUEL FILTER - Remove & Duty, F350 Super Duty, V8, Diesel
ROCKER CARRIER GASKET				
FUEL INJECTOR O-RING KIT				
FUEL FILTER/REGULATOR RING SEAL KIT				
CON WASHER				
ENGINE OIL - 15W-40 Diesel Engine				
Life Gold Premium Anti-Freeze				
FILTERS				
ANTINE BELT				
MASS				
CONDENSOR				

Hazardous Materials

**** Taxes

< City Tax

< State Tax

Name JOSH JORDE

Year 2005 FORD TRUCK F350 1 TON W
6.0L AUTO

Address

VIN 1FTYH31F35ED31123

City

Lin # 854 CR1

St. No.

M. Phone

Estimate# 178415

Order #

Completion Date 08/06/2014 Time

Parts

Part #	Description
10A-FF1143	FUEL FILTER
4AAI-MT63	INTERSTATE MEGATHON 75 MO
43B-PCAD03	HEAVY-DUTY LONG LIFE COOLANT/DIESEL
44A-10610	ENGINE OIL MAG1 15W40
22A-7331	A/C R 134A FREON(PER OE)R114A
42A-10628	MAG 1 75W140 SYNTHETIC AXLE LUBE

Labor

000036 REMOVED CRACKED CYLINDER HEADS AND INSTALLED NEW HEADS AND
FUEL CONTAMINATING ENGINE OIL
000036 REPLACE A/C COMPRESSOR/CONDENSER/REC-DRIER/ORFICE TUBE/FLUSH AND
CLEAN SYSTEM---ORFICE TUBE WAS VERY DIRTY/PLUGGED/AND
DAMAGED---WE TRIED TO CLEAN THE CONDENSER BUT IT WOULD NOT CLEAN
UP---REPLACED DUE TO INTERNAL CONTAMINATION
000044 RESEALED REAR DIFFERENTIAL COVER AND REFILLED WITH FLUID
ROAD TESTED AND RECHECKED FOR LEAKS

Sublets

Shop Supplies

2/HEADS @ 1385.00 EA/2770.00, MISC GASKETS @ 254.33, IPR @
278.32, NOZZLE @ 264.39
ADD ON AIR LINE COMPRESSION FITTINGS
1/4C32-9H527 BRH INJECTOR(SECOND ONE REPLACED)
1/3C32 6584 AA GASKET
1/AC KIT, COMPRESSOR, REC DRIER, ORFICE TUBE, ORINGS, FLUSH, CAP
1/6C32-19712-BB A/C CONDENSER
2/3C32-19B594-AA/A/C CONDENSOR L BRACKETS/JOSH JORDE

Notes

500.00 EST FOR HEADGASKETS, 1500.00 TO REPAIR HEADS, 2500.00 TO
EPLACE HEADS IF NOT REPAIRABLE--3500.00 + 2500.00=6000.00
ESTIMATE (BATTERIES, IPR NOT INCLUDED IN ESTIMATE)
TER RRASSY IT SET A #3 CYL CODE WHICH WOULD RELATE TO THE
JECTOR, #5-#7 INJECTOR WERE REPLACED DUE TO OBVIOUS
LFUNCTION. CODES WERE CLEARED FOR FURTHER ROAD TEST IN THE
KT COUPLE OF DAYS.
OLD ORFICE TUBE IS IN A BAG IN THE CAB, BATTERY DRAW?
LITTLE ENGINE OIL IS LEAKING FROM REAR OF ENGINE

Invoice 1001243

Service Advisor: [REDACTED]

Technician: [REDACTED]

Date: 10-31-2018 1:22 PM

R/O: 1001234

Customer Josh Jorde (JORD001)

Vehicle 2005 Ford F-350 Super Duty XLT
6.0 DIESEL - white
1FTWW31P35ED31123

Miles In: 186,561
Miles Out: 186,561
License Plate: 9S4CK1 KS

Customer Issues and Advisories

Work Description

Injector #5 was stuck in cylinder head after many attempts to get injector out all had failed so we pulled cylinder head found injector tip swelled preventing it from coming out drove old injector out reinstalled head and finished job. Rear brakes were metal on metal on caliper had pistons pushed out replaced everything as needed.

Work Performed

Fuel Injector

Labor	Tech	Hrs	Price	Discount	Total
Replace - Fuel Injector - Both Sides					
Parts	Part No	Qty	Price	Discount	Total
Injector Rail Plug	AAA904-231				
Oil Stand Pipe - LT	AAA904-195				
Oil Line	AAA12LOC				
Fuel Injector	AAADT600002R				

Cylinder Head Gasket

Labor	Tech	Hrs	Price	Discount	Total
Replace - Cylinder Head Gasket - Left					
Parts	Part No	Qty	Price	Discount	Total
EGR Cooler - LT	AAA904-218				
Cylinder Head Gasket	AAA26375PT				

Cylinder Head Gasket SubTotal \$1,367.47

Labor

Labor	Tech	Hrs	Price	Discount	Total
Oil Change					
Parts	Part No	Qty	Price	Discount	Total
Oil Filter	AAA1832				
Qt Mystic 15w40	AAA719073				

Labor SubTotal

Brake Pad

Labor	Tech	Hrs	Price	Discount	Total
Replace - Brake Pad - Rear Pads - Without Dual Wheels					
Replace - Brake Pad - NOTE - To R&R Rotor, Add - Rear - Without Dual Wheels - Both Sides					

INVOICE

11699

Print Date : 06/06/2011

2005 Ford - Pickup F350 Super Duty

6.0L V8 VIN (P)

Lic # : 954CJG

Unit #

Vin # 1FTWW31P35ED31123

Hat #

Odometer In : 150170

Odometer Out : 150269

Extended Labor Description

Extended

Part Description

ROCKER ARM ASS

ROCKER ARM CLIPS

HPOP FITTING UPGRADE KIT

BOLTS

SPACER

CTS CONNECTOR

AIR FILTER

NEW WATER PUMP

CAM SENSOR

FAN CLUTCH WIRING HARNESS
SAVER

AC BLOWER MOTOR

BLOWER WHEEL

RESISTOR

Shop Supplies / Env Fee

[REDACTED]
Name: JOSH JORGE

Type: 2005 FORD TRUCK F350 1 TON
6.0L AUTO

Address:

VIN: 1FTW31P35ED31123

City:

Lin # 354 ORI

H. Phone:

H. Phone:

Odometer 178415

Open Date:

Completion Date 08/06/2014 Time

Laber:

Parts:

Sublet:

Waste:

Tax:

Total:

7610.18

I hereby authorize the above repair work to be done along with necessary materials. You may operate above vehicle for purposes of testing, inspection, or delivery at my risk. I am responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident beyond your control. All parts will remain the ownership of The North Shop Inc. until the responsibility will be assumed for plastic parts. Service charge will be added to all invoices. Any warranties on the products sold hereby are those made by the manufacturer. The seller (dealership) hereby expressly disclaims all warranties, either express or implied, including warranty of merchantability or fitness for a particular purpose, and neither assumes nor other person to assume for it any liability in connection with the sale of said products. All warranty repairs must be authorized by The North Shop Inc prior to work being started. Payment is due when vehicle is completed and delivered to the customer. The North Shop Inc reserves and all information herein at any time without prior notice.