

ARTS & ACCESSORIES

Q.O.	DESCRIPTION
25293	
C1	Oil
378941	T/C
5441	oil
FL1995	oil
C32	
2057CARM	engine
4TEL6655A	oil
4TEL6653B	oil
15W40	oil
UC7B	coolant
UTS6814	
34463	spark
34686	spark
2C38	
5310 NA	spring
	bracket
Mercury	fluid
engine	
freight	
TOTAL PARTS	

NAME <u>Clark Co. Fire District #1</u>		REPAIR ORDER NO.										
ADDRESS		DATE <u>6-23-16</u>										
TAG NO.		MECHANIC										
TYPE <u>2001 F350 7.3</u>	IDENTIFICATION NO. <u>1FDWT37F4/EB31324</u>	SPEEDOMETER READING <u>68275</u>										
<u>Engine runs rough, misses</u> <u>Replace engine with new</u> <u>complete assembly, see diagrams below,</u>												
<u>SPRINGS</u> <u>Turbo blades show signs of dirt injection</u> <u>blow into 6.8 - air comes out fill tube - cyl head</u> <u>puffs out of oil fill cap</u> <u>cyl 6 95 psi - cyl 8 - 150 psi</u> <u>#6 almost dead #8 weak (idle + 1800 RPM)</u>												
I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.		<table border="1"> <tr> <td>TOTAL LABOR</td> <td></td> </tr> <tr> <td>TOTAL PARTS</td> <td></td> </tr> <tr> <td>OUTSIDE LABOR</td> <td></td> </tr> <tr> <td>TAX</td> <td></td> </tr> <tr> <td>TOTAL</td> <td><u>13686.35</u></td> </tr> </table>	TOTAL LABOR		TOTAL PARTS		OUTSIDE LABOR		TAX		TOTAL	<u>13686.35</u>
TOTAL LABOR												
TOTAL PARTS												
OUTSIDE LABOR												
TAX												
TOTAL	<u>13686.35</u>											
SIGNED												

Thanks for your business.