

800004632

Time: 14:58

Date: 06/15/2019

Page: 1/1



Employee:
Sales Rep:
Accounting Day:

Y

OCR

Y

8000046328816061

	Description	Quantity	Price	Net	Total
	2001 Ford Truck F150 1/2 Ton - Pickup 5.4 L 330 CT				
213-3124D	RAY Alternator - Remanufactured -				
213-3124D	RAY Core Deposit				
213-3124D	RAY Core Deposit				

Delivery:

Attention: f150 alternator

Tax Exemption:

PO#:

Terms: WEEKLY PAY

Subtotal

Total

Customer Signature

ALL GOODS RETURNED MUST BE ACCOMPANIED BY THIS INVOICE

I agree to pay total amount
according to card issuer agreement.

THANK YOU MANHATTAN FOR
YOUR SUPPORT & BUSINESS!

CUSTOMER COPY

Customer:

Vehicle:

2001 Ford F-150 Lariat
Eng: 5.4L V8 (L) GAS FI

Repair Order:

Service Writer

Date In: 08/16/18 9:00AM

Replace Intake Manifold

Customer Concern: Manifold Leaking Coolant

Labor: **Description**
Remove and Replace Intake Manifold

Extended

Parts: **Description**
Dorman Intake Manifold

Price Ea.

Qty

Extended

1.0

3

Fees: **Description**
Shop Supplies Fee

Sold Price

Qty

Extended

Job Subtotal

Contact Log

Method	Tech	Message	Date	Time	Authorized
	DD	Initial contact.	08/16/2018	9:00 am	\$0.00