

ORDER WRITTEN

BY Joe

RECEIVED

2-10-15

PROMISED

QTY	PART NUMBER	DESCRIPTION	UNIT PRICE	AMOUNT
1	AT224845	used air cooler		
1	R122595	ring		
1	RE521420	L. Har		
1	RE227949	black heater		
1	R100569	gsk		
1	T182278	support		
1	AT209421	cable		
1	RE167207	sensor		
2	SPL70X	joint		
18	5	fuel line		
4	568218	oring		
1	86030524	gsk		
1	R72328	oring		
1	R123467	elbow		
1	T125627	paint		
1	R119653	adapter		
2	20# bolts	ends		
1	RE520930	sensor		

L. Soder

John Deere

MODEL 644J

SERIAL NO

DW644JX591851

MOTOR NO

RG6081H241229

WORK TO BE DONE

LUBRICATE	CHANGE OIL	FLUSH TRANS	FLUSH DIFF	CLEAN	PAINT	LABOR ONLY	MATERIAL ADDITIONAL	AMOUNT
-----------	------------	-------------	------------	-------	-------	------------	---------------------	--------

1 Repair engine (has excessive blowby & oil pressure drops @ high idle)

2 Replace air to air cooler

3 Replace bolt turbo

4 Replace vapor fuel lines

5 Replace drive line joints

6 Replace water pump

7 Install black heater

97 hrs service @ \$80

Customer Delivered

MILEAGE	OTHER MATERIALS	TOTAL SERVICE
	GALS FUEL @	TOTAL PARTS
	QTS OIL @	TOTAL OUTSIDE WORK
	LBS GREASE @	TOTAL OTHER MATERIALS
	Hardware	DYNAMOMETER
	75 gal 15W40	PICKUP & DELIVERY
	3 gal oil filter	SUBTOTAL
	Flt ch	TAX (WHERE APPLICABLE)
	TOTAL OTHER MATERIALS	GRAND TOTAL

12,484.95

Thank You

4826

IN U.S.A. FORM ROYAL 451A