

DATE	YEAR	MAKE	MODEL	VIN	STK/CUS	MILES IN	MILES OUT	TAG
07/08/19	11	FORD	F-250	1FT7X2BT9BEC63736	43534	192288	192284	1418
SERVICE DATE	NOTIFIED	SVC ADV	PROMISED DATE/TIME	LICENSE	RATE	PAYMENT	INV. DATE	
	07/10/19	14	07/08/19 01:45P			03	07/12/19	
R.O. NUMBER	TAX ID	HOME PHONE	BUSINESS PHONE					
46656				SILVER 2				

UDB Customer Type: R

===== REPAIR LINE 001 =====
 CUSTOMER STATES VEHICLE IS LEAKING OIL UNDERNEATH NEAR TURBO CHECK AND ADVISE
 VERIFIED CONCERN, FOUND OIL LINE ON TURBO LEAKING. REMOVED AIR INTAKE, CAC TUBE,
 UPPER & LOWER INTAKE, REMOVED OIL LINE & BOTH FITTINGS. INSTALLED NEW FITTINGS &
 LINE. DURING REPAIRS FOUND COOLANT FITTING LEAKING. REPLACED TURBO COOLANT LINE &
 FITTING. REASSEMBLED W/ NEW INTAKE GASKETS & EGR TO INTAKE GASKETS. FILLED COOLANT,
 CLEANED ENGINE. RETEST, PROBLEM SOLVED @ THIS TIME. COP; UNKNOWN.

Bill Code - C

UDB Repair Type: C

UDB Serv Dept: S

99 MISC

TOMMY MOORE

FD BC3Z /	6B689/A	TUBE ASY
FD BC3Z /	6A968/D	CONNECTOR
FD BC3Z /	6A968/C	CONNECTOR
FD BC3Z /	9E464/F	GASKET
FD BC3Z /	9439/A	GASKET -
FD BC3Z /	9439/B	GASKET -
FD BC3Z /	9439/C	GASKET -
FD BC3Z /	6A968/C	CONNECTOR
FD BC3Z /	9U469/A	TUBE - WA

LABOR AMOUNT	
PARTS AMOUNT	
MISC. SALES	
MATERIALS	
TOTAL CHARGE	
DEDUCTIBLE	
SALES TAX	
OTHER PAY	
CUSTOMER PAY	709.06