

FY9422	111-3012	Location: District 1-Topeka - Radio	OSCILLOSCOPE, DIGITAL STORAGE, TEKTRONIX, MDL. TDS540A, '94 SN: B010744, 4 channels, operates up to 500 MHz, NOT WORKING - SERVICEABLE, WILL NOT POWER UP, MISSING OSCILLOSCOPE PROBES
FY9422	111-4008	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670A, '95 SN: 496KVQ0026, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE, WILL NOT POWER UP, NO OSCILLOSCOPE PROBES
FY9422	511-1045	Location: District 1-Topeka - Radio	ANALYZER, Z METER CAPACITOR/INDUCTOR, SENCORE, MDL. LC53, '84 SN: 3558492M, NOT WORKING - SERVICEABLE
FY9422	511-3040	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670B, '01 SN: 496LBL0008, FDMA digital communications system analyzer, DISPLAY DOES NOT WORK
FY9422	511-3041	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670B, '03 SN: 496LDG0021, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE