

Bill To

Invoice

Date	Invoice #
6/4/2019	3499

Project	Mileage	Terms	P.O. No.
1990 Kenworth W900 Blk			

Item	Quantity	Description
HDT23525566VS	1	Detroit Series 60 Head w/Valves
HDT23525566VS -...	1	Detroit Series 60 Head - CORE
HDT23525566VS -...	-1	Detroit Series 60 Head - CORE
R23532592	1	Gasket/Cyl Kit
R23532592- CORE	1	Gasket - Cyl Kit - CORE
R23532592- CORE	-1	Gasket - Cyl Kit - CORE
R23505195	1	CAM DWLASM
R23505195-CORE	1	CAM DWLASM - CORE
R23505195-CORE	-1	CAM DWLASM - CORE
R5234945	6	EUI INJ 60
R5234945-CORE	6	EUI INJ 60 - CORE
R5234945-CORE	-6	EUI INJ 60 - CORE
23538247	6	Arm/RLR ASM
08929710	6	M--Shell Set
08929670	6	Shell Set
23535012	1	Thrustwasher Kit
23515470	6	M---Seal
23539103	1	Valve Cover Gasket - Detroit Series 60
23516969	1	Seal - Rear Main w/ Sleeve
23539104	1	Gasket, Oil Pan
08929425	4	Stud
11506101	4	Nut
08929529	1	Gasket
08929285	1	Gasket
7715-0002	2	4' X 6' Charge Air Hose
491506	4	HD Spring Loaded T-Bolt Clamp
X007785	1	5" Preformed Band Clamp
491330	1	Hose Clamp (2-1/4' X 3-1/8')
50-2610	1	#10 HD Silicone Hose Clamp
50-2420	1	#20 Heavy Duty Hose Clamp
HP4	1	4 to 6-1/8" Hi Torq Clamp
1106904	3	3/16 Hose
24704N604	2	JIC Female Swivel
5515-250	12	2.5" Coolant Hose/ Per Inch

Total

Phone #

Fax #

Bill To

Invoice

Date	Invoice #
6/4/2019	3499

Project	Mileage	Terms	P.O. No.
1990 Kenworth W900 Blk			

Item	Quantity	Description	Rate	Amount
A-6913	1	Shift Knob, Master Valve Assembly		
380608	1	3/8 X 1 USS GR8		
37-3906	1	3/8 Flat Washer		
37-4806	1	3/8" Lockwasher		
38-1032	2	5/8 X 3-1/2 Cap Screw		
37-3812	2	3/4 Flat Washer		
1460X4	1	1/4 Brass Sleeve		
DC-1	1	Cover Plate w/ Grommet		
Cenex 15W40 Oil	12.5	SuperLube TMS 15W40 Oil		
Delvac AntiFreeze ...	12	Gallon, Delvac Anti-Freeze 50/50 BLK		
75W90 Gear - Blk	2	75W90 Gear Oil - Gal		
1970	2	Oil Filter		
1749	1	Oil Filter		
Q21-6004	1	Sensor-Dual Speed/Tach		
Freight	1	Freight - Total Freight for all parts shipped		
Labor	50	Labor Charge		
Misc. Shop Supplies		Misc. Shop Supplies		
R23504966	1	Turbo S - 60T		
R23504966-CORE	1	Turbo S - 60T - CORE		
R23504966-CORE	-1	Turbo S - 60T - CORE		
TE11981LBH	1	Tie Rod End, RH 1.50"		
Labor	1	Labor Charge Replace bad tie rod on right hand side		
		126249 miles		
		Sales Tax		

Phone #		Fax #	
---------	--	-------	--