

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	11/20/2020
Invoice Date	02
Location:	
Work Order Number:	202907
Payment Type:	Account
Page:	1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/TBD Retail

Technician: T2900, T2116

COMPLAINT:

01 Use this job code when a job code needs to be created

Title:

CAUSE:

CORRECTION:

CHOPPER FLOOR WAS BROKEN, REPLACED FLOOR

CHOPPER TOP SHEET WAS BROKEN AND BENT, REPLACED TOP SHEET

CHOPPER LH LATCH FOR ACCESS DOOR WAS BENT AND BROKE, REPLACED LATCH

RH SIDE SHEET WAS BENT AND BROKEN, REPLACED SIDE SHEET

LH ROTOR SHEET WAS BENT AND BROKEN, REPLACED SHEET AND BEARING FOR ROTOR

RH AND LH CHUTE BRACKETS WERE BROKEN, REPLACED BRACKETS

TAIL BOARD WAS BENT AND BROKEN, REPLACED TAIL BOARD

3 VANES FOR TAIL BOARD WERE BROKEN, REPLACED 3 VANES, TRANSFERED REST TO NEW TAIL BOARD

BOTH TAIL BOARD MOUNT BUSHINGS/BOLTS WERE BROKEN, REPLACED BUSHINGS

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
11M7059	COTTER PIN	1.00			N
24H1341	WASHER	1.00			N
AH163595	BEARING	1.00			N
AH214452	FLOOR	1.00			N
AH217814	Sheet	1.00			N
AH218277	Bracket	1.00			N
AH218278	Bracket	1.00			N
AH218472	Deflector	1.00			N
AH223985	Adjuster	1.00			N
AXE23606	Actuator	1.00			N
B28970	COMPRESSIO	1.00			N

CONTINUED ON NEXT PAGE->

Invoice To Account No:

Deliver To:

SERVICE INVOICE

		Invoice Number:	
		Invoice Date	11/20/2020
		Location:	02
		Work Order Number:	202907
		Payment Type:	Account
		Page:	2 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720598	

H136179	PIN	1.00	N
H174305	BRACKET	1.00	N
H204973	Sheet	1.00	N
H209928	SHEET	1.00	N
H209929	Sheet	1.00	N
H213638	BUSHING	2.00	N
H214957	BOLT	2.00	N
H215050	SHEET	1.00	N
HXE36443	VANE	1.00	N
HXE36445	Vane	2.00	N
JD9201	ECCENTRIC	1.00	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u> <u>Extended Price</u> <u>Taxed Ind</u>
FRT AGEX	AG EXEMPT PARTS FRT	1.00	N

Miscellaneous Charges:

Service Accessories

Labor:	
Parts:	
OL&M:	
Misc:	
Sales Tax:	
Total:	\$6,110.73

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number: 1322272
 Invoice Date: 11/16/2020
 Location: 02
 Work Order Number: 202839
 Payment Type: Finance

Page: 1 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS Retail

Technician: T2116,T2900

COMPLAINT:

03 STS COMBINE INSPECTION

CORRECTION:

Checked all engine belts
 Checked all safety points
 Checked tire pressure and wear
 Checked all filters
 Checked cooling systems
 Inspected and test ran machine
 Checked steering systems
 Checked augering systems
 Fluids pulled and sent to lab for scan
 Cleaned- up to 5 hours

/SICOSTS2 Retail

Technician: T2116,T2900

COMPLAINT:

07 FEEDER HOUSE AREA REPAIRS

CORRECTION:

FRONT BOTTOM SHAFT (REVERSER SHAFT) O-RING WAS LEAKING WHERE SHAFT GOES INTO REVERSER, PULLED SHAFT AND INSTALLED NEW O-RING

RH DRIVE CHAIN WAS WORN OUT, REPLACED CHAIN

CONVEYOR CHAIN GUIDES (3) WORN THROUGH, REPLACED GUIDES

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7186	BOLT	3.00				N
19M8499	CAP SCREW	1.00				N
24M7178	WASHER	9.00				N

Invoice To Account No:

Deliver To:

SERVICE INVOICE

	Invoice Number:	1322272
	Invoice Date:	11/16/2020
	Location:	02
	Work Order Number:	202839
	Payment Type:	Finance
	Page:	2 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS2 Retail

Technician: T2116,T2900

AH206862	ROLLER CHA	1.00	N
AH217633	LINK CHAIN	1.00	N
AH220541	CHAIN CONNECTOR	3.00	N
H156100	BUSHING	2.00	N
H156101	WASHER	2.00	N
H171960	STRIP	3.00	N
H206978	LABEL	1.00	N
H223849	RING	1.00	N
HXE118760	LOCK NUT	1.00	N
M120229	Bushing	1.00	N
M84309	PUSH NUT	8.00	Y
T61327	O-RING	1.00	N
Miscellaneous	Description	Quantity	List Price
FRT AGEX	AG EXEMPT PARTS FRT	1.00	Net Price
			Extended Price
			Taxed Ind
			N

/SICOSTS3 Retail

Technician: T2116,T2900

COMPLAINT:

08 FEED ACCELERATOR REPAIRS

CORRECTION:

CLEANED OUT

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	1322272
Invoice Date:	11/16/2020
Location:	02
Work Order Number:	202839
Payment Type:	Finance

Page: 3 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS4 Retail

Technician: T2116,T2900

COMPLAINT:

09 LEFT HAND SIDE REPAIRS

CORRECTION:

CLEANED OUT INSIDE OF MACHINE

CHOPPER STATIONARY KNIVES DULL AND BROKE OFF, REPLACED KNIVES

CHOPPER HAMMERS WORN WAY DOWN, REPLACED HAMMERS

CHOPPER JACKSHAFT SHAFT WAS FROZEN IN PIVOT POINT AND DAMAGED, REMOVED SHAFT, REPLACED SHAFT AND BOLTS

LOWER CHOPPER BELT IDLERS WERE OUT, REPLACED IDLERS

REEL PUMP BELT (LOWER FH DRIVE) ADJUST PIVOT WAS WORN OUT REPLACED PIVOT

UNLOADING DRIVE CHAIN WAS WORN OUT AND BUSHING DESTROYED, REPLACED CHAIN AND BUSHING

LH GULL WING DOOR WOULD NOT STAY OPEN, REPLACED BOTH SHOCKS

UNLOADING DRIVE BELT SET IDLER OUT, REPLACED IDLER

DISCHARGE BEATER BELT ADJUST PIVOT WORN OUT, REPLACED PIVOT

BOTH CHOPPER LOCKUP PINS WERE BENT, REPLACED PINS

CHANGED PRIMARY COUNTERSHAFT GEARCASE OIL

GREASED MACHINE

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7023	COTTER PIN	2.00				N
19M7793	SCREW	1.00				N
19M7824	SCREW	1.00				N
24H1139	WASHER	2.00				N
24M7338	WASHER	1.00				N

Invoice To Account No:

Deliver To:

SERVICE INVOICE

	Invoice Number:	1322272
	Invoice Date:	11/16/2020
	Location:	02
	Work Order Number:	202839
	Payment Type:	Finance
	Page:	4 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS4 Retail

Technician: T2116,T2900

AH128597	GAS OPERAT	1.00	N
AH161392	GAS OPERAT	1.00	N
AH204389	IDLER	1.00	N
AH205909	KIT	6.00	N
AH205910	KIT	2.00	N
AH211639	PULLEY	2.00	N
AXE53952	Roller Chain	1.00	N
H129207	PIVOT	1.00	N
H129208	PIVOT	1.00	N
H155973	SCREW	1.00	N
H165584	PIN	2.00	N
H201324	Weld Pin	1.00	N
H215004	BLADE	15.00	N
H235564	V-BELT	1.00	N
M113254	COMPRESSIO	2.00	Y

/SICOSTS5 Retail

Technician: T2116,T2900

COMPLAINT:

10 RIGHT HAND SIDE REPAIRS

CORRECTION:

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	1322272
Invoice Date:	11/16/2020
Location:	02
Work Order Number:	202839
Payment Type:	Finance

Page: 5 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS5 Retail

Technician: T2116,T2900

UPPER TAILINGS DRIVE CHAIN WORN OUT, REPLACED CHAIN

TAILINGS SENSORS FAILING, REPLACED BOTH SENSORS

CLEAN GRAN AND TAILINGS PADDLE CHAINS LOOSE, ADJUSTED CHAINS

TAILINGS DRIVE BELT ADJUST PIVOT WORN OUT, REPLACED PIVOT

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AE23539	Link Chain	1.00				N
AH158581	MODULE	1.00				N
AH214415	MODULE	1.00				N
H129207	PIVOT	1.00				N

/SICOSTS6 Retail

Technician: T2116,T2900

COMPLAINT:

11 ENGINE COMPARTMENT REPAIRS

CORRECTION:

ALL 3 PROPELLER BEARINGS WERE OUT, REPLACED BEARINGS

HYDRO DISPLACEMENT CONTROL VALVE WAS LEAKING, INSTALLED NEW SEALS

CHANGED ENG OIL AND FILTER

CHANGED ENG GEARCASE AND HYDRAULIC OIL

CHANGED ALL 3 HYDRAULIC FILTERS

CHANGED BOTH FUEL FILTERS

CHANGED BOTH ENG AIR FILTERS

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	1322272
Invoice Date:	11/16/2020
Location:	02
Work Order Number:	202639
Payment Type:	Finance
Page:	6 of 8

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOST\$6 Retail

Technician: T2116,T2900

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
57M7146	FUSE	4.00				N
AH128449	HYDRAULIC FILTER	3.00				N
AH204389	IDLER	1.00				N
AH212294	FILTER ELE	1.00				N
AH212295	FILTER ELE	1.00				N
H235564	V-BELT	-1.00				N
JD29980	BALL BEARI	3.00				N
N376361	GASKET	1.00				N
RE509672	FILTER ELE	1.00				N
RE525523	FILTER ELE	1.00				N
Miscellaneous						
ENGINE OIL PER QT	15/40 PLUS 50 ENG OIL PER QT	32.00				N

/SICOST\$7 Retail

Technician: T2116,T2900

COMPLAINT:

12 GRAIN TANK SECTION REPAIRS

CORRECTION:

CLEANED OUT GRAIN TANK

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	1322272
Invoice Date:	11/16/2020
Location:	02
Work Order Number:	202839
Payment Type:	Finance

Page: **7 of 8**

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9760	5305	H09760S720598	S720589	

/SICOSTS8 Retail

Technician: T2116,T2900

COMPLAINT:

13 CAB SECTION REPAIRS

CORRECTION:

A/C DRAIN HOSE WAS LEAKING, REPLACED HOSE

RH HAZARD LIGHT (FRONT) BULB WAS BLOWN, REPLACED BULB

BOTH REAR AMBER HAZARD LIGHT BULBS WERE BLOWN, REPLACED BULBS

FEED AND DISCHARGE FLOOD LIGHTS WERE NOT WORKING, REPLACED FUSE F9 IN ENG COMPARTMENT RELAY BO>

CHANGED BOTH CAB AIR FILTERS

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH115833	AIR FILTER	1.00				N
H133384	BULB	3.00				N
H159636	TUBE	1.00				N

Invoice To Account No:

Deliver To:

SERVICE INVOICE

Invoice Number:	1322272
Invoice Date:	11/16/2020
Location:	02
Work Order Number:	202839
Payment Type:	Finance

Page: 8 of 8

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9760

5305

H09760S720598

S720589

/SICOSTS8 Retail

Technician: T2116,T2900

H220870

AIR FILTER

1.00

I N

Miscellaneous Charges:

Service Accessories

Finance Information

Labor:

Parts:

OL&M:

Misc:

Sales Tax:

Grand Total: \$10,079.56

*** DOCUMENT COPY ***

Documents may come from the Winner store, for any billing concerns please contact your location service manager.