SERVICE INVOICE

WO170029851 INVOICE NUMBER: Invoice Date:

PSO/WO

09-22-15 COE EAA OT

lodel erial#	\$25,544.07
Make	AA
Model	C-15
Serial#	0NXS08459
Equip No	57
Machine ID	
Meter Reading	923158.0

TE17328

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
0001960	CK #25335 APP #3085	08-19-15	998	T	17	4
0001000	011,000			Unit Price		Extension

4 1U-5517 DISC S 24 3S-2093 TIE S 1 5H-1504 WASHER S 153 5P-0765 CM-HOSE STK N 1 6I-4421 PLATE SPACER N 1 2 6K-0806 TIE S 2 7N-1961 BOLT S 1 7X-2539 BOLT N 6 8S-9191 BOLT S 2 113-5304 SEAL N 7 124-1855 BOLT 12PT S 2 136-4877 CAT ELC 50/50 1GL S 10 2913866X 15W40 DEO(ULS) 1GLS 1 5546-8 TOTAL PARTS SEG. 01 F/R LE	Quantity	Item	Description	Unit P	rice Extension
F/R LE	153 122 2166 2772 1110	3S-2093 5H-1504 5P-0765 6I-4421 6K-0806 7N-1961 7X-2539 8S-9191 113-5304 124-1855 136-4877 238-8648 2913866X	TIE S WASHER S CM-HOSE STK N PLATE SPACER N TIE S BOLT S BOLT N BOLT S SEAL N BOLT 12PT S SPLICE WIRE S CAT ELC 50/50 1GL S 15W40 DEO(ULS) 1GLS		
			TOTAL PARTS	SEG. 01 F/R LE	
			SEGMENT 01 TOTAL	-7	

OVERHAUL ENGINE CAT CERTIFIED ENGINE REBUI

CUSTOMER COMPLAINT: CHECK FOR OIL LEAK REPAIR PROCESS COMMENTS: INSPECT OIL LEAK AT FRONT OF ENGINE. APPEARS TO BE COMING FROM CAM THRUST PLATE SEAL OR OIL PLUG ON FRONT OF HEAD.DIFFICULT TO LOCATE.LEAK IS COMING FROM BEHIND FRONT COVER AREA IN FRONT OF HEAD.ADVISE OF FINDINGS.GOT OKAY TO TEAR DOWN FURTHER TO LOCATE SOURCE OF LEAK.STEAM OFF ENGINE AND UNDER HOOD BEST AS POSSIBLE. HOOK UP ET AND CAPTURE ALL ECM INFO. SEND IT TO SIMS.RUN CYLINDER CUTOUT TEST ON UNIT. SHOWING #3 WEAK ON TEST.INJECTOR TEST SHOWED ALL OKAY.PULL BOTH OIL SOAKED V-BELTS, PEANUT COVER.HAD TO GRIND OUT 2 BOLTS FOR REMOVAL. PIN TIME ENGINE, PULL CAM GEAR

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice. If we did not meet your expectations, please call 866.2WARREN.

SERVICE INVOICE

INVOICE NUMBER: Invoice Date:

WO170029851 09-22-15

Due

\$25,544.07

Make	AA
Model	C-15
Serial #	0NXS08459
Equip No	57

Machine ID

Meter Reading 923158.0

TE17328 **PSO/WO**

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
0001960	CK #25335 APP #3085	08-19-15	998	T	17	4
Quantity	Item	Description		Unit Price		Extension

AND THRUST PLATE. INSPECT AND FOUND OIL GALLEY PLUG INTACT.SUSPECTING FRONT STRUCTURE LEAKING.ADVISE OF FINDINGS. WAS TOLD THAT UNIT USES 1 GAL OIL EVERY 200 MILES.HAS CONDENSATE AND OIL DRIPPING FROM BLOWBY TUBE.RECCOMEND OVERHAULING AND RESEALING FRONT STRUCTURE.GOT APPROVAL FOR REPAIRS.DRAIN OIL AND COOLANT.REMOVE FAN AND SHROUD. SUPPORT HOOH AND LEAN RADIATOR FORWARD.PULL OIL PAN, RAISE AND SUPPORT FRONT OF ENGINE.REMOVE ALL NEEDED ACC'S AND PULL FRONT COVER. PULL GEAR TRAIN AND REMOVED BACK PLATE.CONFIRMED OIL LEAKING AT SEAL ON TOP FRONT OF BLOCK AT OIL RIFLE.STEAM CLEAN ALL RELATED PARTS FOR REASSEMBLY.

Item

Quantity

2.00-

1.00

1 1	OR-2112	CORE AS OIL N	Ī
1 -		CORE DEPOSIT N	I
1-		CORE RETURN N	J
1 1	OR-9925	KIT ENG OVER N	1
1 -	OK 3323	CORE DEPOSIT N	1
1-		CORE RETURN N	1
1 2	20-1206	HOSE AS	3
	21-7384	HOSE AS	3
	48-3681	KIT-GASKET-F	1

SEG. 02

TOTAL LABOR SEG. 02 FREE 3 YR OPT

SEG. 0: TOTAL MISC CHGS SEGMENT 02 TOTAL

SUPPLIES FEE

TOTAL PARTS

ENVIROMENTAL FEE

4 YR OPT COVERAG

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice. If we did not meet your expectations, please call 866.2WARREN.

SERVICE	INVOICE
INVOICE NUMBER: Invoice Date:	WO170029851 09-22-15
Due	\$25,544.07
Make	AA
Model	C-15
Serial #	0NXS08459
Equip No	57
Machine ID	
Meter Reading	923158.0
PSOWO	TE17328

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
0001960	CK #25335 APP #3085	08-19-15	998	Т	17	4
Quantity	Item	Description		Unit Price	9	Extension

OKLAHOMA STATE TAX TULSA CITY/TULSA TAX TULSA COUNTY TAX

C O D INVOICE COPY

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

Parts Labor Misc.

Tax \$25,544.07 TOTAL

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice. If we did not meet your expectations, please call 866.2WARREN.

Terms of Payment: Unless specific terms of payment are stated above, which shall be the governing terms hereof, this invoice shall otherwise be due and payable in full 30 days from the invoice date.

Performance under this invoice along with jurisdiction and venue shall be in Tulsa County, Oklahoma. Return parts must be accompanied by the packing list or this invoice. Refer to packing list for parts return policy. ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE. Acceptance of goods or services constitutes acceptance of the Warren Cat Standard Terms and Conditions which are incorporated by reference and available at http://www.warrencat.com/terms-conditions or upon request.

SERVICE INVOICE

WO170029851 INVOICE NUMBER: 09-22-15 Invoice Date: Due \$25,544,07 AA Make C-15 Model 0NXS08459 Serial # 57 Equip No Machine ID 923158.0 Meter Reading TE17328

PSO/WO

Customer#	PO#	Doc Date	Salesman	Division	Store	Terms
0001960	CK #25335 APP #3085	08-19-15	998	Т	17	4
Quantity	Item	Description		Unit Price	•	Extension

TROUBLESHOOT ENGINE

CUSTOMER COMPLAINT: CHECK FOR COOLANT LEAK REPAIR PROCESS COMMENTS: BRING IN SHOP AND CHECK OVER UNIT.LOW COOLANT LIGHT ON START UP.SURGE TALK ALMOST EMPTY.TURN ON HEATER VALVES, HOOK UP AND PRESSURE TEST COOLING SYSTEM. FOUND MAIN LEAK ON HEATER HOSE THAT WAS LAYING AGAINST PIPE BEHIND TURBO.PER DAWN, TO REPIAR COOLANT LEAK. DRAIN VERY WEAK AND WATER DELUTED COOLANT.HEATER SHUT-OFF VALVE WONT CLOSE.REMOVE, REROUTE, AND HOOK UP HEATER HOSE.ZIP TIE WHERE NEEDED.FILL WITH NEW COOLANT.START UP, RUN AND CHECK OPERATION.NO MORE LEAKS AT TIME.GOT APPROVAL FOR PLATINUM O/H.STARTED TEARING DOWN FOR REBUILD. TEAR DOWN COMPLETE, CLEAN AND INSPECT ALL PARTS PER GUIDELINES. CHECK CRANKSHAFT, CAM, ALL GEARS AND RELATED COMPONENTS. CLEAN BLOCK DECK, ALL BOLTS HOLES AND CHECK COUNTER BORES.REPLACE MAIN BEARINGS AND THRUST.INSTALL CYLINDER PACKS, REPLACED SPACER PLATE DUE TO EROSION.SET UP CHECK AND RECORD LINER PROJECTION. INSTALL AND TORQUE ALL HEAD BOLTS.RECORD TRIM FILES, INSTALL AND TORQUE ALL INJECTORS.SET ENGINE TIMING AND BUILD TOP END.SET OVERHEAD.BUILD FRONT, AND BOTH SIDES.REMOVE, SET UP AND DRILL OUT BROKEN BOLT FROM A/C MOUNTING BRACKET.DRILL AND INSTALL HELI-COIL.REMPLACE CUSTOMER SUPPLIED ALT; AND BELTS.SECURE OIL PAN.CHANGE OIL AND FUEL FILTERS.FILL WITH COOLANT AND OIL.HOOK UP BATTERIES.UNIT WONT START.UNHOOK BATTERIES AND CHERCK STARTER.BOTH B+ AND GROUNDS WERE LOOSE. TIGHTEN AS NEEDED. HOOK UP BATTERIES, PRIME AND START.RUN UNIT AND CHECK OPERATION.ALL OKAY.SECURE BELLY BAR AND SET HOOD GUIDES.SECURE L/F STEER WHEEL, AND COVERS.CHECK FLUOIDS AND ROAD TEST.ALL CHECKS AND TEST WERE OKAY.

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless