

Invoice

Main Location

Invoice #: 204
 Opened: 5/06/2021 3:41 PM
 Closed: 5/11/2021 10:09 AM
 PO Ref #:
 Page: 1

Bill To:

Vehicle #: Truck 67
 Year: 2000
 Make: Freightliner
 Model: FLD120
 License #:
 VIN #: 1FVXFEDB5YLG70926
 Meter: Miles 72874 Hours 1369
 Engine: Cat C10

(SIGNATURE)

(DATE)

Notes:

Rebuilt fan hub due to bearing noise during operation. Found bad bearing upon disassembly. Tested fan operation in shop and everything is fine at this time.

Services Performed

Service Code	Description	Taxable	Hours	Rate (hourly)	Total Price
5059	Engine-Fan	Y			
Total Service					

Parts Used

Part Number	Description	Taxable	Quantity	Price (each)	Total Price
994305H0R	Fan Hub Rebuilt Kit-Truck 67	Y	1.00		
Total Parts					

Sub Total

State

County

Grand Total

\$681.89

Main Location

Invoice

Invoice #: 311
Opened: 8/05/2021 3:10 PM
Closed: 8/26/2021 6:55 AM
PO Ref #:
Page: 1

Bill To:

Vehicle #: Truck 67
Year: 2000
Make: Freightliner
Model: FLD120
License #:
VIN #: 1FVXFEDB5YLG70926
Meter: Miles 80070.5 Hours 1785.6
Engine: Cat C10

(SIGNATURE)

(DATE)

Services Performed

Service Code	Description	Taxable	Hours	Rate (hourly)	Total Price
6080	Chassis- Springs	Y	8.00		
Total Service					

Parts Used

Part Number	Description	Taxable	Quantity	Price (each)	Total Price
9999	Freight	Y	1.00		
M18006	Spring Plate	Y	2.00		
MLC11	Rubber Load Spring	Y	2.00		
MS19-29028	Restrictor Can	Y	2.00		
Total Parts					

Sub Total

State

County

Grand Total

\$1,593.18

Invoice

Invoice #: 392
Opened: 10/20/2021 2:06 PM
Closed: 11/17/2021 6:20 AM
PO Ref #:
Page: 2

Bill To:

Vehicle #: Truck 67
Year: 2000
Make: Freightliner
Model: FLD120
License #:
VIN #: 1FVXFEDB5YLG70926
Meter: Miles 85134.3 Hours 2060
Engine: Cat C10

(SIGNATURE)

(DATE)

HC04024	Hubcap-6 hole 4.5" BC (cap only)	Y	2.00
HDV8033	Air Bag	Y	1.00
RS0010	Oil Sample Kit	Y	1.00
Set 406	3782/3720 Wheel Bearing Set	Y	2.00
Set 413	Wheel Bearing Set (HM212049/HM212011)	Y	2.00

Total Parts

Sub Total

State

County

Grand Total

\$3,741.76

Main Location

Invoice

Invoice #: 392
Opened: 10/20/2021 2:06 PM
Closed: 11/17/2021 6:20 AM
PO Ref #:
Page: 1

Bill To:

Vehicle #: Truck 67
Year: 2000
Make: Freightliner
Model: FLD120
License #:
VIN #: 1FVXFEDB5YLG70926
Meter: Miles 85134.3 Hours 2060
Engine: Cat C10

(SIGNATURE)

(DATE)

Notes:

Replaced hydraulic drum controls
Replaced hub bearings and seals on lift axle
Replaced air bag on lift axle

Services Performed

Service Code	Description	Taxable	Hours	Rate (hourly)	Total Price
9067	Truck 67 Service Service Added From PM Warnings.	Y	4.00		
0100	Misc. Repairs	Y	3.75		
0100	Misc. Repairs	Y	9.25		
0100	Misc. Repairs	Y	9.25		
0100	Misc. Repairs	Y	5.25		
0100	Misc. Repairs	Y	4.00		

Total Service

Parts Used

Part Number	Description	Taxable	Quantity	Price (each)	Total Price
0000422	Vacuum Filter Gauge	Y	1.00		
0082988	Drum Charge Cylinder - Truck 67	Y	1.00		
15w40	Bulk Oil	Y	42.00		
1643B-100	Hubcap-6 Hole 5.5" BC	Y	1.00		
35058	Wheel Seal-Truck 67 Lift Axle	Y	2.00		
760120	Hydraforce Block - Truck 67	Y	1.00		
9999	Lift Axle from Parts Truck in Pasture	Y	1.00		
B99	Oil Filter	N	1.00		
BF1272-SPS	Fuel Filter - Truck 67	N	1.00		
BF7587	Fuel Filter	Y	1.00		

Sub Total

State

County

Grand Total

\$3,741.76