

# INVOICE

Terms	Date	Invoice #
Due on receipt	11/1/2022	81920


P.O. No.	YEAR	MAKE	MODEL	MILEAGE	KEY
88	2009	PETERBILT	389	493764/14471	
Item	Description	Qty	Rate	Location	Amount
LABOR	GOLDEN GRAIN ENT. 9N777142 IN 10/26 Steering Gear RG65219X REMOVE FRONT DIFFERENTIAL CARRIER TO ALLOW GEAR CHANGE AND REPLACEMENT OF NEEDED COMPONENTS, REPLACE REAR DIFFERENTIAL CARRIER WITH REMANUFACTURED UNIT WITH MATCHING RATIO, RENISTALL BOTH UNITS FILL WITH PROPER LUBRICANT AND TEST RUN.	14			
MISC	MISC CHARGE	14			
216220-1	OVERHAUL KIT FRONT, DS404	1			
513384	EATON R&P DS404, 3.36 RATIO FRONT, 211466	1			
128049	METRIC NUT; INPUT SHAFT DS404, M42 X 1.5, AFTER 1/1/95	1			
FREIGHT IN	FREIGHT IN	1			
127588	METRIC NUT; DS404 THRUSHAFT, M39 X 1.5, AFTER 1/1/95	1			
51845	Permatex Anaerobic Gasket Maker; 300 ml Cartridge	1			

<b>Subtotal</b>
<b>Sales Tax (9.15%)</b>
<b>Total</b>
<b>Balance Due</b>

# INVOICE

Terms	Date	Invoice #
Due on receipt	11/1/2022	81920

P.O. No.	YEAR	MAKE	MODEL	MILEAGE	KEY
88	2009	PETERBILT	389	493764/14471	
Item	Description	Qty	Rate	Location	Amount
RSP40-3.36	Differential, Rear 3.36	1			
450876-10	AXLE GASKET 8 HOLE 6" ID, 8 1/4" OD, 7" B/C, 5/8 BOLT	4			
80/90W-PAIL	GEAR OIL: 80/90W DELO ESI, 35LB PAIL, 224503-783	2			

Authorized work was completed to my satisfaction and I agree to pay the charges as billed.

Signature \_\_\_\_\_

**Subtotal**

**Sales Tax (9.15%)**

**Total**

\$4,686.23

**Balance Due**

# INVOICE

Terms	Date	Invoice #
Due on receipt	11/3/2022	82108

P.O. No.	YEAR	MAKE	MODEL	MILEAGE	KEY
88	2009	PETERBILT	389	493764/14471	
Item	Description	Qty	Rate	Location	Amount
ENGLABOR	9N777142 PERFORM OVERHEAD ADJUSTMENT PROCEDURE.	3			
MISC	MISC CHARGE	3			
	REPAIRS NEEDED AND FOUND DURING DIFFERENTIAL R & R AND PROGRAMMING DUE TO GEAR CHANGE.				
LABOR	PROGRAM ECM WITH NEW GEAR RATIO	1			
R & R 1610-18...	REMOVE AND REPLACE 1610 - 1810 U-JOINT	4			
BALANCE 1-P...	BALANCE 1-PIECE 1480 - 1760	1			
BALANCE 2-P...	BALANCE 2 PIECE 1810 AND SPL AND RPL	1			
5-675X	U-JOINT; HR W/STRAPS 1710	2			
5-676X	U-JOINT, 1810 HALF ROUND	2			
6.5-4-4571-1X	END YOKE; 1810 2.274-44 Spline, 5.190 Tall, 3.000 Hub, 2.500 Thur Hole PRIMARY APP INPUT DS404	1			
6-4-8991-1X	END YOKE; 1710 2.024-39 Spline, 6 1/8 Tall, 3.000 Hub, 2.281 Thur Hole PRIMARY AP INPUT RR DIFF EATON	1			
LABOR	SERVICE ENGINE, INSPECT AND LUBE CHASSIS, CHECK AND OP OFF ALL FLUIDS.	2			
P559000	OIL FILTER; CUMMINS ISX IS	1			
P552203	FUEL FILTER	1			
P552200	FUEL FILTER CUMMINS	1			

Authorized work was completed to my satisfaction and I agree to pay the charges as billed.

Signature \_\_\_\_\_

<b>Subtotal</b>	
<b>Sales Tax (9.15%)</b>	
<b>Total</b>	\$2,430.93
<b>Balance Due</b>	