

MAKE & MODEL		2008 Ford F350 Super Duty FX4		VIN		1FTWW33R08EA30831		ENGINE SIZE		6.4L V8 F		TRANSMISSION		6 SPD MANUAL M5		COLOR		PRD DATE		TERMS		Net 30	
LICENSE NO.		MILES IN/OUT		CATALOG		DESCRIPTION		QTY		PARTS		LABOR		DISC		TOTAL		Code		PO #			

Pull Engine, Inspect Damage, Put Cab On Truck And Pulled
 Outside Until Approval, Replace Long Block
 Customer Supplied Engine, Remove Broke Bolts In Head For
 Exhaust Manifold, Remove Oil Pans On 2 Motors & Inspect
 Exhaust Manifold Gasket Set
 6.4L Engine Assembly
 Hardware
 Intake Gasket
 Gasket
 ICP Sensor Pigtail Powerstroke
 3/8" Fuel Hose
 Torque Converter Hex Nut
 6.4L EGT Sensor On UpPipe 03-07 Powerstroke
 Dipstick Tube
 Red Butt Connector, Weatherproof (18-20)
 6.4L Air Filter 08-10 Powerstroke
 T4 Rotella Triple15w-40 CJ4
 6.4L Fuel Filter Kit 08-10 Powerstroke
 OWAF Fleet Charge Antifreeze
 Full Synthetic Multi-Vehicle Transmission Fluid
 Freon
 Compressor Oil
 Diesel Fuel

TOTAL \$14,453.30

Signature _____

Date _____

MAKE & MODEL

2008 Ford F350 Super Duty FX4

LICENSE NO.

VIN

TORQUE

ENGINE SIZE

TRANSMISSION

COLOR

PRD DATE

CATALOG

1FTWW33R08EA30831

6.4L V8 F

6 SPD MANUAL M5

DESCRIPTION

QTY

PARTS

LABOR

DISC

TOTAL

Code

Diag A/C Issue, Pulled Truck Into Shop, Hooked Up A/C Machine & Monitored Pressures (High), Checked Over All Connections & Fittings With UV Light, Found High Side Shrader Valve Leaking, Recovered Freon, Installed New Shrader Valve, Charged System With Correct Amount, Ran A/C On High While Monitoring Temp & Pressures (52Degrees Out Vent, Pressures Good)
Shrader Valve

\$300.00 JB

\$3.45 PMA-WS

TOTAL

\$313.24

Print Name

Signature

Date