

Fleet Maintenance Work Order Detail

WO#	4622	0967	0967 - Excavator Hydraulic	5,353 H
Date In	05/05/16	Complete	1018535	
Date Out	06/02/16			

Act Date / ID	05/05/16 616,123	PM Item	Regular	Overtime	Labor Cost
		- none -			

Part Number	Part Name	Task	Quantity	Unit Cost	Parts Cost
BW203FF	BEARING / BW203FF	Engine (Diesel)	1.00		
IS6BG1TRW02-A	ENGINE ISUZU	Engine (Diesel)	1.00		
JC30/926020	FILTER FRESH AIR / JC30/926020	Engine (Diesel)	1.00		
REPAIR	REPAIR	Engine (Diesel)	1.00		
WX49131	FILTER AIR / WX49131	Engine (Diesel)	1.00		
WX49132	FILTER AIR / WX49132	Engine (Diesel)	1.00		
WX57324	FILTER OIL - WX57324	Engine (Diesel)	2.00		
IS1113671320	GASKET OIL PAN	Engine (Diesel)	1.00		
IS8970728230	SEAL REAR CRANK WITH SLEEVE	Engine (Diesel)	1.00		
AL9007541401	OIL SHDII 1540W	Engine (Diesel)	22.00		
AL900AN0046BU	OIL HYDRAULIC PREM ISO46 (ANTI-WEA	Engine (Diesel)	120.00		

Parts &

Work Order #4622 Total	Labor Hours	Labor Cost	Parts Cost	Total Cost
				\$15,829.41

Invoice

DATE INVOICE #

5/16/2016 28162

Phone #

Fax #

E-mail

BILL TO

SHIP TO

PO.# OR MODEL

TERMS

SER #

HRS

ITEM

#

DESCRIPTION

U/M

RATE

AMOUNT

New Wholegood

1 NEW 6BG1TRW02-A REPLACEMENT ENGINE
FAN TO FLYWHEEL, SER # 361035, ENGINE
IS COMPLETE, ACCESSORIES WILL NEED TO
BE TRANSFERRED FROM OLD ENGINE.
ENGINE CORE IS REQUIRED DUE TO TIER 1
REQUIREMENTS

Total

\$14,500.00