

Invoice

Replaced @ 78,452K

ACTIVITY

Parts

Motor and install cash or check

Parts

Heater hose

Parts

upper radiator hose

Parts

lower radiator hose

Parts

idler pulley

Parts

serpentine belt

Parts

exhaust gasket

Automatic Transmission Flush

Pulling pan and replacing filter and gasket using 6 qts of Mopar ATF+4 68218057AA

has two codes C1219 and C1240 ABS/Steering
could be clock spring in the steering wheel

needs A.C. charged estimate \$400-\$600 at dealership

PAID

SUBTOTAL

TAX (7%)

TOTAL

PAYMENT

BALANCE DUE

6,863.66

6,863.66

\$0.00