

Invoice:
Date / Time: 11/26/2014 12:22:54 PM
Parts Order:
Customer:
Branch:
Invoice Total: \$9,480.63

Page 1 of 1

Customer P/O:

Invoiced By:

Supplier	Part / Misc	Description / Ref Number	U/M	Quantity	Price	Ext Price
HME	20918B	trans	EA	1		

Invoice Subtotal:

Total Tax:

Invoice Total: \$9480.63

PARTS TICKET NO.

Your Ord _____

Invoice Date: 12-23-14

TERMS: DUE ON RECEIPT

MAKE	MODEL & SERIAL NUMBER	UNIT NO.	MILEAGE	HOURS	ENGINE MODEL	ENGINE NUMBER
MAZDA - RED	CL 713	012358	24866		E7	

Remove RTD 1698 LL TRANSMISSION - Replace Dead Engine mount Pads - Install new Clutch Assy
 RATED AT 2250 TORQUE - Resurface Fly wheel - Switch Bell Housing - & yoke & senders TO NEW RTD 20918
 TRANSMISSION - install oil plug kit in transmission For older style Bell Housing - Install 1850 SHIFT KNUCK
 Rebuild SHIFT Tower - Drill out isolator pin & Replace isolator Bushings & Tower Bolt & O-Rings kit
 Reseal PTD - Leaking - Replace Front engine mount - Reseal Turbo Drive & Oil Fill Tube - Look at
 Fabricate and install Hydraulic Pump Support - missing on old TRANSMISSION - Install New
 SHIFT PATTERN Dial on Deck - Install Late style Speed Sensor & ADAPTOR Pile Tail To Hook up
 To Truck wireing - Install New Bell Housing Bushings & Clutch
 Release Fork & BOTH CROSS SHAFTS & 2 Piece Clutch Brake
 Fill TRANSMISSION WITH 50WT SYNTHETIC OIL
 Tighten Clamps on PK HOSES & TROFFER PK OIL

Total Labor	
Total Parts	
Oil, Grease	
Sublet Repairs - Surface Flywheel	
Mileage	
Freight	
Hazardous Waste Disp1 Surcharge	
Tax	
PAY THIS AMOUNT	3570 50

