

Fleet Maintenance Work Order Detail

WO#	22647	12-1727	12-2014 FRTLNR 114SD DUMP TRUCK	0 M Road
Date In	08/30/23	Incomplete	1FVHG3DV5EHFX6849	
Date Out				

Act Date / ID	08/31/23	572,180	PM Item	Regular	Overtime	Labor Cost
Employee			- none -	1.50	0.00	

[illegible]

Act Date / ID	08/30/23 571,840	PM Item	Regular	Overtime	Labor Cost
Contractor	B&B HYDRAULICS	- none -	0.00	0.00	

Part Number	Part Name	Task	Quantity	Unit Cost	Parts Cost
PUMP PISTON	REBUILD - PUMP PISTON	Hydraulics	1.00		
freight	freight	Hydraulics	1.00		
				Parts Cost	
				Parts & Labor Cost	

Act Date / ID	09/06/23 573,648	PM Item	Regular	Overtime	Labor Cost
Contractor	FLEETPRIDE	- none -	0.00	0.00	

Part Number	Part Name	Task	Quantity	Unit Cost	Parts Cost
890 LDR02A	GAUGE-OIL LEVEL WI THERMOSTAT	Hydraulics	1.00		
				Parts Cost	
				Parts & Labor Cost	

Work Order #22647 Total	Labor Hours	Labor Cost	Parts Cost	Total Cost
	1.50			\$3,879.75

Work Order Notes

HAD HYDRAYLIC PUMP REBUILT--REMOVED SAND SPREADER CONTROLS AND REMOVED EVERYTHING INSIDE FOR AUCTION