

INVOICE

YEAR: 2001
MAKE/MODEL: DODGE RAM 3500 BASE
VIN: 3B6MF36591M284221
ENGINE: V8-360 5.9L

TRANS/DRIVE: A518/
LICENSE/STATE: 734KFP/
MILES IN/MILES /

In: 6/16/2020 Out: 6/16/2020

VEHICLE ISSUE #1: TOW IN

TECH REPORT: TRANSMISSION OVERHAUL

PART	INTERMEDIATE FRONT BAND	1 @ \$26.90
PART	A518 MASTER KIT	1 @ \$190.31
PART	FILTER	1 @ \$7.29
PART	FRONT BAND BUSHING	1 @ \$3.47
PART	BUSHING KIT	1 @ \$29.70
PART	MANUAL VALVE	1 @ \$29.95
PART	PRESSURE REGULATOR VALVE	1 @ \$60.40
PART	MULTIVEHICLE FLUID	10 @ \$7.00
PART	PRECISION TORQUE CONVERTER	1 @ \$224.93
PART	4TH TORQUE COVERTER CLUTCH SOLENOID	1 @ \$80.63
PART	HP GOV PRESSURE SENSOR	1 @ \$78.00
PART	GOVERNOR PRESSURE SOLENOID	1 @ \$53.12
PART	THROTTLE CABLE VALVE	1 @ \$113.76
LABOR:	REMOVE AND REINSTALL TRANSMISSION	6 @ 80.00
LABOR:	TRANSMISSION OVERHAUL	8 @ 80.00
LABOR:	TOW IN	1 @ 80.00
LABOR:	REMOVE AND REPLACE THROTTLE CABLE VALVE	1 @ 80.00

Payment Rec'd

Date: 6/26/2020

Recommended Repairs:

Labor/Jobs

Parts

Sublet

Total Fees

Subtotal

Tax @ 7.5%

Total

Payments

Balance

INVOICE

ID	YEAR:	2001	TRANS/DRIVE:	A518/4WD
	MAKE/MODEL:	DODGE RAM 3500 BASE	LICENSE/STATE:	734KFP/
	VIN:	3B6MF36591M284221	MILES IN/MILES	192469/
	ENGINE:	V8-360 5.9L		

VEHICLE ISSUE #1: NO MOVEMENT
FLUID IS BURNT BLACK
TOWED IN

TECH REPORT: OVERHAUL TRANSMISSION

PART	OVERHAUL GASKET SET	1 @ \$225.98	/
PART	FILTER	1 @ \$15.76	/
PART	PUMP BODY BUSHING	1 @ \$7.48	/
PART	FORWARD STEEL	4 @ \$6.54	/
PART	FORWARD DIRECT STEEL	5 @ \$7.22	/
PART	MULTIVEHICLE FLUID	10 @ \$10.80	/
PART	TORQUE CONVERTER	1 @ \$243.24	/
LABOR:	REMOVE AND REINSTALL TRANSMISSION	7 @ 90.00	!
LABOR:	TRANSMISSION OVERHAUL	8 @ 90.00	!

VEHICLE ISSUE #2: REAR U-JOINT ON DRIVESHAFT AT THE REAR DIFFERENTIAL IS BROKEN

PART	REAR U-JOINT	1 @ \$66.14	
------	--------------	-------------	--

Total for "REAR U-JOINT ON DRIVESHAFT AT THE REAR DIFFERENTIAL IS BROKEN "

Payment Rec'd	C	Date: 4/28/2023	
---------------	---	-----------------	--

Recommended Repairs:	Labor/Jobs	
	Parts	
	Sublet	
	Total Fees	
	Subtotal	
	Tax @ 7.5%	
	Total	
	Payments	
	Balance	