

#4 \* Customer Reports:

OTHER: REPLACE STARTER AND FLYWHEEL

Installed F81Z 11V002 AARM :STARTER MOTOR ASY

Installed 88163NA : FLYWHEEL

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize line repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or else where for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warrantles on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warrantles either express or implied, including any implied warrantly of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR

PARTS

DEDUCTIBLE

SUBLET

SHOP SUPPLIES

HAZARDOUS MATERIALS

SALES TAX OR TAX I.D.

SPECIAL ORDER DEPOSIT

DISCOUNTS

TOTAL DUE

9379.19

BoJ:

Hau

start

alt opt

SERVICE DEPARTMENT HOURS 7:00 a.m. to 7:00 p.m. Monday - Friday 7:30 a.m. ± 6:00 p.m. Saturday

R/O Open Date	R/O Number 30
8/13/20	8138911/1
R/O Close Date	Status
8/25/20	Pre-Invoice
Mileage In	Mleage Out
164860	164884
COLUMN TO SERVICE AND ADDRESS OF THE PARTY O	The state of the s

FK3947

DESCRIPTION OF SERVICE AND PARTS

FORD

Cell: 785-640-2617

2004

#1 - BLEC: BLECTRICAL SYSTEM DIAGNOSIS C/S ENGINE WILL NOT TURN OVER AT ALL- HAS GOTTEN HOT BEFORE. PLEASE ADVISE.

F-450 SD

Tech: Bryan P Fairbanks (720)
FOUND ENGINE SEIZED FROM GETTING HOT. WILL NOT
TURN OVER AT ALL. SEE BELOW FOR ENGINE
REPLACEMENT. NOTE-REPLACED RADIATOR AND CLUTCH
ASSEMBLY AND FLYWHEEL AND STARTER AT THE SAME
TIME AS ENGINE REPLACEMENT.

Sub Total: 112.00

#2 - Q99PX: MULTI-POINT INSPECTION

Sub Total: .00

#3 \* Customer Reports:

ENGINE REBUILD/REPLACE

Tech: Bryan P Fairbanks (720)

Installed 5C3Z 7515 A : LEVER ASY - CLUTCH RELEASE

Installed F81Z 7B602 AA :STUD

Installed 4C3Z 8005 EB : RADIATOR ASY

Installed 8C3Z 7L596 DA : KIT - CLUTCH REPAIR

Installed 4C3Z 6006 ARM :SERVICE ENGINE ASY

Installed 3C3Z 2A790 AA : CONNECTOR

Installed VC 7 B :ANTI-FREEZE

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. 'I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or else where for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warrantles on the products sold hereby are those Imade by the manufacturer. The seller hereby expressly disclaims all warrantles either express or implied, including any implied warrantly of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any illability in connection with the sale of sald products. Any limitation contained herein does not apply where prohibited by law.

THE VALUE OF COMMISSION OF COMMISSION CONTRACTOR CONTRA

LABOR

PARTS

DEDUCTIBLE

SUBLET

SHOP SUPPLIES

HAZARDOUS MATERIALS

SALES TAX OR TAX I.D.

SPECIAL ORDER DEPOSIT

DISCOUNTS

TOTAL DUE