

License 312247	VIN 1GND5135742343436	Year 1980
Make CHEVY	Model PICK UP	
Engine	Transmission 350 TURBO	
In 84961	Mileage Out	Fleet # P.O. Number
RW/AW-ABS	State Insp PURPLE	Written By:

Problem Statements

~~3000-2300~~ STALL CONVERTER
FLUID IS BLACK & LOW, WANTS TO SERVICE

Recommended Services

Labor Operations

Tech	Type	Description
TD	Lab	RAN DIAGNOSTIC, CHECK TRANSMISSION FLUID IS VERY DARK & BURNT, RECOMMEND REBUILD
AS	Lab	TRANSMISSION COMPLETE W/2000-2300 STALL TORQ CONVERTER
JE	Lab	REMOVE/REINSTALL TRANSMISSION FLUSH & FLOW TEST COOLER & LINES
	Lab	REBUILD TRANSMISSION W/SHIFT KIT & 2000-2300 STALL TORQ CONVERTER
		1YR/ UNLIMITED MILEAGE ~NON-TRANSFERABLE~ WARRANTY

Parts

Part Number	Part Description
BNM 30262	SHIFT KIT, B&M TH350
K35900L	GKT/SEAL/RING KIT
B18506	350 BW LO/REV FRICTION
B35103	350 FWD /DIR. FRICTION
32740	GM TH350 INT RED EAGLE FRICTION
35710B	TH350 FILTER350/C NYLON FILTER
35820R	350 ROSTRA RED-STR MODULATOR VALVE
35723HD	HD INTERMED OUTER RACE
35724	ROLLER 350 INT OE
15-5755	HOSE MENDER-UNION

Date	12/12/2023
RO #	26343
RO Total	\$2,617.84
Balance Due	\$0.00

R6

