

Invoice #	
Date	8/1/2023
Time	13:19

PO#	
Terms	PAID
Due Date	8/1/2023

RO#			
RO Date	8/1/2023		
Miles	In	0.0	Out 0.0
Hours	In	0.0	Out 0.0
Service Writer			
Stock#	(1		
Serial#	1VRH16122F1000135		
Yr Make Model	Vermeer 604N		
Description	Baler		
License			
Fleet#			
In Service Date	12/31/9999		

Service Invoice

Customer

Memo

Customer Service Issue # 1

Com: REWORK

Cause:

Fix:

Note:

Mech	Type	Description	Total
25	Labor	Labor	4.0000
	Item	351010 SCREW-HCS-.31-18X1.00-GR5	20.0000
	Item	510301006 SCREW-HCS-.31-18X.75-GR5	20.0000
	Item	27997060 PICKUP TINE - HEAVY DUTY 5/16 BOLT	7.0000
	Item	510510638 BAR - TOOTH MOUNT 4' RH 5/16 BOLT	5.0000
	Item	27997051 PICKUP TINE-OFFSET 5/16 BOLT	3.0000
	Item	510508269 FINGER - NET PICKUP GUIDE	2.0000
	Item	A-CL60IMP 60 CONN. LINK IMPORT	1.0000

Printed:5/10/2024 12:29 PM

Page 1 of 1 Pages

Invoice #	
Date	8/9/2023
Time	13:33

PO#	
Terms	PAID
Due Date	8/9/2023

RO#				
RO Date	8/9/2023			
Miles	In	0.0	Out	0.0
Hours	In	0.0	Out	0.0
Service Writer				
Stock#				
Serial#	1VRH16122F1000135			
Yr Make Model	Vermeer 604N			
Description	Baler			
License				
Fleet#				
In Service Date	12/31/9999			

Service Invoice

Customer

Memo

Customer Service Issue # 1

Com: HAY IN FRONT

Cause:

Fix: STARTER ROLLER NOT POSITIONED RIGHT. PUT BACK RIGHT. MADE BELTS BACK TO FACTORY LENGTH

Note:

Mech	Type	Description	Total
25	Labor	Labor	8.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 3

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
25	Labor	Labor	0.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 4

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
25	Labor	Labor	0.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 5

Com: BELT REPAIR 6.8"

Printed:5/10/2024 12:30 PM

Customer Name	Invoice#	RO#	Date
			08/09/2023

Cause:

Fix:

Note:

Mech	Type		Description	Total
25	Labor	Labor	Labor	0.0000
	Item	25085367	ALLIGATOR STYLE LACING	2.0000
	Item	510504019	PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator		1.0000

Customer Service Issue # 6

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type		Description	Total
25	Labor	Labor	Labor	0.0000
	Item	25085367	ALLIGATOR STYLE LACING	2.0000
	Item	510504019	PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator		1.0000

Invoice #		PO#	
Date	6/23/2023	Terms	PAID
Time	08:13	Due Date	6/23/2023



Service Invoice

Customer

Memo

RO#					
RO Date	3/8/2023				
Miles	In	0.0	Out	0.0	
Hours	In	0.0	Out	0.0	
Service Writer					
Stock#					
Serial#	1VRH16122F1000135				
Yr Make Model	Vermeer 604N				
Description	Baler				
License					
Fleet#					
In Service Date	12/31/9999				

Customer Service Issue # 1

Com: COULD NOT ADD CUSTOMER NAMES TO MONITOR CLUTCH WENT OUT ONE OF THE PICKUP ANGLE IRONS ARE BENT EXTRA SHORT BELT AND LONG BELT WENT THROUGH LAST YEAR ONE OF THE GUARDS IS MISSING ON ONE SIDE

Cause:

Fix:

Note:

Mech	Type	Description	Total
Item	510524128	BEARING - 1 1/4 HEX SPHR. CAST 4.19BC E3 P	2.0000
Item	510520230	BEARING - 1 3/4 HEX SPHR. IN CAST E3	2.0000
Item	510523613	QUICKLINC 90 DEGREE 1/8" NPT RIGID FITTING	1.0000
Item	510336647	WASHER-MCHBSHG-2.00- 2.03X2.50-18G	2.0000
Item	510511738	TUBE - 4 3/4 IDLER ROLLER, 4' LONG	1.0000
Item	510515860	BEARING - 2 7/16" CYLIND. TRIPLE LIP SEAL P	2.0000
Item	510511750	COVER - IDLER ROLLER BEARING 2 7/16	2.0000
Item	510508606	RUBBER FLAPPER AUGER 4ft BUILDUP	2.0000
Item	510337607	WASHER-FLATSTD-.38-.44X1.00 -.08	6.0000
Item	510510200	PLATE - CROP FLOW, RH	1.0000
Item	27997051	PICKUP TINE-OFFSET 5/16 BOLT	15.0000
Item	27997060	PICKUP TINE - HEAVY DUTY 5/16 BOLT	21.0000
Item	4472006	3/8-16X3/4 GR 5 SLF TAP WA HD	22.0000
Item	510377006	SCREW-.31-18X.75-THRD CUT F	20.0000
Item	510510638	BAR - TOOTH MOUNT 4' RH 5/16 BOLT	5.0000
Item	89982001	BAND-PICKUP	2.0000

Printed:5/10/2024 12:26 PM

Customer Name	Invoice#	RO#	Date
			06/23/2023

Item	510504043	BEARING - BALL 1in - 1641 - 2RSNR	2.0000
Item	382020	SCREW-HCS-.44-20X2.00-GR8	10.0000
Item	15354001	NUT-TLHEX-.44-20-C	10.0000
Item	111738001	WASHER-7/16 HARDENED ASTM -A325	10.0000
Item	1732004	BEARING - DBL ROW BALL 1/2 ID X 1 1/2 OD	10.0000
Item	510515206	PICKUP AUGER ASSY. W/SECTS. LOWER RH	1.0000
Item	4051001	BRG-1 1/4 CYL-RA103RR2 W/COL	2.0000
Item	510513196	CLUTCH - 3 ROW RADIAL PIN 1 1/4 HEX W/SEAL	1.0000
Item	510503002	SHEET - TOP NET GUIDE	1.0000
Item	A-RC80IMP	RC 80 X 10FT (IMPORT)	20.0000
Item	A-RC60IMP	RC 60 X 10FT (IMPORT)	18.0000
Item	A-RC50USA	RC50USA	8.0000
Item	A-CL50	50 CONN. LINK DRIVES	2.0000
Item	A-CL80USA	OFFSET LINK - 80 CHAIN - USA	3.0000
Item	A-CL60IMP	60 CONN. LINK IMPORT	2.0000
Item	510320501	NUT-TLHEX-1.00-8-8	2.0000
Item	510504019	PIN - BELT LACE .15 X 6.2	6.0000
Item	129607001	3IN BELT IDLER ROLLER 4FT	1.0000
Item	Monitor Repair	Monitor Repai	1.0000
Misc.	Freight		2.0000

Customer Service Issue # 2

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
23	Labor	Labor	13.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 3

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
23	Labor	Labor	0.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 4

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
23	Labor	Labor	0.0000

Printed:5/10/2024 12:26 PM

Page 2 of 3 Pages

Customer Name	Invoice#	RO#	Date
			06/23/2023

Item	25085367	ALLIGATOR STYLE LACING	2.0000
Item	510504019	PIN - BELT LACE .15 X 6.2	1.0000
Misc.	Belt Labor - Gator		1.0000

Customer Service Issue # 5

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
23	Labor	Labor	0.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000

Customer Service Issue # 6

Com: BELT REPAIR 6.8"

Cause:

Fix:

Note:

Mech	Type	Description	Total
23	Labor	Labor	0.0000
	Item	25085367 ALLIGATOR STYLE LACING	2.0000
	Item	510504019 PIN - BELT LACE .15 X 6.2	1.0000
	Misc.	Belt Labor - Gator	1.0000