

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
64485	04/18/2023	\$0.00	04/18/2023	Due on receipt	

VEHICLE
2013 JEEP WRANGLER
3.6L

VIN
1C4AJWAG7DL565124

ACTIVITY	QTY	AMOUNT
<p>3.6L CHRYSLER LONG BLOCK (deleted-1) 3.6L CHRYSLER LONG BLOCK</p> <p>Corrected Cylinder head Design So it will not fail like the OEM engine did</p> <p>MEMO FROM FRASER PRODUCTION: PLEASE READ BEFORE INSTALLATION</p> <p>Depending on the application, this engine may contain a different size temperature sensor. There are two different possible temperature sensor sizes that fit this engine and may need to be changed out to fit your application before installation. The temperature sensor is located on the left side cylinder head towards the rear of the engine.</p> <p>Fraser Engines and Transmissions has provided you the current Chrysler part number of each temperature sensor in the event you may need to replace what is currently on this engine.</p> <p>Size: M12 Part Number: 05149077AB Size: 3/8th Part Number: 68164627AA</p> <p>CORE The Core Must be Sent Back Within 90 Business Days or Warranty Is Voided!</p> <p>DO NOT SCHEDULE THE CORE BY YOURSELF, THAT MAY LEAD TO THE CORE GETTING LOST OR YOU BEING CHARGED FOR THE FREIGHT CHARGES. PLEASE CALL THE CORE DEPARTMENT FOR THE PROPER INSTRUCTIONS ON GETTING THE CORE BACK. WE PAY FOR THE CORE PICK UP.</p> <p>Once The Core Is Picked Up, Normally Takes 10 To 14 BUSINESS DAYS For The Refund Due To Transit Time And Our Check In Process.</p>		

ACTIVITY	QTY	AMOUNT
<p>Cores must be returned within 90 days of receipt of rebuilt/remanufactured engine to receive approved core value reimbursement.</p> <p>Cores not received within 90 days will result in a charge to the purchasing credit card, covering the core charge as agreed upon during purchase. If there are extenuating circumstances, these must be discussed and agreed upon in writing in order to receive a payment extension.</p> <p>By accepting these terms and arrangements, you agree that if Fraser Engines is not able to recover the core costs, you will be responsible for potential litigation that will occur according to the laws of the State of Michigan. You will be responsible for costs incurred including your own transportation, lodging, court costs, and any costs required in order to recover the core value.</p> <p>The core being returned must be the same engine or head that was supplied; same style, type, and displacement.</p> <p>"SOME"Core being returned must not have visible damage or cracks to the block, crankshaft, connecting rods, or cylinder head(s).</p> <p>Core being returned must be assembled to be sure the core is complete. Main, rod, and cam caps must be on the properly installed on the core.</p> <p>SHIPPING CHARGE (deleted-1) Shipping and Core Pickup in the United States with the exception of Alaska, Hawaii, all offshore U.S.territories and possessions.</p> <p>Shipping options are available for customers outside of the United States please contact is for details.</p> <p>CUSTOMER SERVICE- FOR ALL CUSTOMER SERVICE INQUIRIES, PLEASE GO TO OUR WEBSITE UNDER THE CUSTOMER SERVICE TAB TO SUBMIT A REQUEST OR CALL US, THANK YOU FOR THE BUSINESS.</p> <p>TERMS & CONDITIONS:</p> <p>VENUE The interpretation of this Agreement shall be governed by the laws of the State of Michigan. Any action arising under this Agreement shall be brought in the applicable State court located in Macomb County, Michigan.</p> <p>Disassembly of the engine UNAUTHORIZED will void the warranty!!!</p> <p>All returns are subject to a 25% restocking fee. If the engine fails it is the policy of this company to refuse exchange or refund based upon inspection.</p> <p>Any attempt to alter, remove or conceal part markings will void the warranty.</p> <p>If the heat tabs are melted or removed the warranty will be void.</p> <p>Any attempt to alter, remove or conceal part markings will void the warranty.</p> <p>If the heat tabs are melted or removed, the warranty will be void.</p> <p>DAMAGED SHIPMENT DISCLAIMER:</p>		

ACTIVITY	QTY	AMOUNT
<p>It is the responsibility of the purchaser to inspect any shipment before it is delivered - that is, signed for, and/or removed from the transport. If there is damage to the shipment, REFUSE THE PRODUCT. WE WILL SEND A REPLACEMENT.</p> <p>If the shipment, however, is delivered (signed for and/or removed from the transport), any damage discovered after delivery is the responsibility of the purchaser. If a no-fault warranty is in effect, the purchaser will need to make a claim to address the damages, or to purchase new product(s)</p> <p>CREDIT CARD SALE (IF PAID BY CARD THIS APPLIES TO YOU):</p> <p>All transactions are subject to approval by your credit card company. The above mentioned item(s) and / or Purchase Order may not be Canceled, Returned, nor Rescheduled. However, item(s) may be returned for repair or replacement if defective. Any estimated delivery is an estimate only and may be subject to change. A change to the delivery date will not mitigate Buyer's obligation under this agreement. Receipt of your signed acknowledgment above is required for us to accept/proceed with your order.</p> <p>CHECK SALE (IF PAID BY ECHECK THIS APPLIES TO YOU):</p> <p>CUSTOMER PAID BY ELECTRONIC CHECK. ELECTRONIC CHECKS TAKE 3 TO 5 BUSINESS DAYS TO CLEAR INTO OUR ACCOUNT. WE WILL NOT SHIP OUT PRODUCT UNTIL PAYMENT IS DEPOSITED INTO OUR ACCOUNT.</p> <p>Engine oil coolers If you have an aftermarket or factory style oil cooler you MUST replace the cooler and lines with a new assembly. It is impossible to thoroughly flush the oil coolers. You may also eliminate the oil cooler if desired.</p> <p>Prime the Pump To avoid dry start-up, it is best to prime the oil system with an engine-priming tool or a pre</p> <p>VENUE The interpretation of this Agreement shall be governed by the laws of the State of Michigan. Any action arising under this Agreement shall be brought in the applicable State court located in Macomb County, Michigan.</p>		

TOTAL

5,899.00