

1999 Sterling dump truck
EK3332

Clutch Repair

CUST PO #		SHP VIA	WRITER	SALESPERSON	UNIT ID	REFERENCE	
DELIVERY							
QTY SHP	QTY B/O	ITEM	DESCRIPTION	BN 1	BN 2	UNIT PRICE	EXTD PRICE
1		170F/FUL 4308226	GASKET-HOUSING,CLUTCH				
1		170F/FUL 14311	GASKET				
1		170C/4089544	KIT,SEAL				
1		170D/SP 308925 82	CLUTCH-EASYPEDAL ADVANTAGE 15.				
1		170F/SP 127760	BRAKE-CLUTCH BRAKE DISC ASSEMB				
1		170F/02-12176-000	BEARING-PILOT,72 X 30 X 19MM				

1999 Sterling dump truck - 549,899 miles
 - New clutch
 - Pilot bearing
 - Clutch brake
 - Engine rear main seal
 4/1/24

Customer Copy: Please Process For Payment

TOTAL	1,227.14
-------	----------

C.O.D.

Invoice

DATE	INVOICE #
4/3/2024	187192

P.O. NUMBER	TERMS	Account Type	REP	SHIP DATE	SHIP VIA	PROJECT
	Due on receipt	None		4/3/2024		
QUANTITY	ITEM CODE	DESCRIPTION	PRICE EACH	AMOUNT		
84	811-24--ht	1-1/2" SUCTION & RETURN HOSE				
4	HC130--bp	T-BOLT CLAMP				
1	BMFB112-1...	1-1/2 X 1-1/4 BLK MI HEX BUSHING				
1	221-600	RESERVOIR BREATHER + FILLER (BOLT-ON), No Charge State Sales Tax				
WRONG FITTING, \$18 after TAX.						
Total				\$245.27		

STERLING, SUCTION hose from tank to PTB pump, HOSE CLAMPS
for SUCTION HOSE

PARTS INVOICE

Invoice No: 2339195
Date: 4/3/2024
Page: 1 of 1
Payment Type: Credit Card

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
2.00	0.00	X11343-16-16	HOSE FITTI	HFC025				
83.00	0.00	X487TC-16-RL	Bulk Hose	HR				

Customer PO No:

Tax Exempt No:

Salesperson:

Total: \$375.26