

Vehicle : 2014 Toyota Tacoma 2.7 L 2694 CC L4 DOHC

VIN : 5TFPX4EN9EX019506

Fleet #/Driver :

Created : 8/19/2024 9:14:41 AM CDT

Invoiced : 8/23/2024 12:46:41 PM CDT

Odometer In : 187102

Odometer Out : 187102

Qty	Code/Tech*	Reference	Description	Condition
1.25		Guide	A/C COMPRESSOR DRIVE BELT TENSIONER/IDLER Remove & Replace	

Note:

1	NBH	25070901	NAPA Belts & Hoses Serpentine Belt
1	OY07	2335187	Murray Pulleys and Tensioners - Litens Belt Drive Tensioner
1	NBH	36174	NAPA Belts & Hoses Accessory Drive Belt Idler Pulley

Labor

Parts

Shop supplies

Credit Card Fee

Sales Tax

Total	\$556.82
PAYMENT	\$556.82
BALANCE DUE	\$0.00

Invoice

Date 2/12/2024
Invoice # 6383

Ship To

Terms

Description	Qty
Part cleaner	3
Plugs	4
Coil boots	4
Valve cvr	1
Chain guide	1
Gasket	1
Gasket	1
Diagnose & replace parts	4.5

Total \$951.15
Payments/Credits \$0.00
Balance Due \$951.15

Vehicle : 2014 Toyota Tacoma 2.7 L 2694 CC L4 DOHC

VIN : 5TFPX4EN9EX019506

Fleet #/Driver :

Created : 8/26/2024 5:00:00 PM CDT

Invoiced : 9/10/2024 4:25:50 PM CDT

Odometer In : 187165

Odometer Out : 187165

Qty	Code/Tech*	Reference	Description	Condition
5		Guide	CAMSHAFT GEAR OR SPROCKET Remove & Replace	
Note:				
1	Toyota	1305075030	Engine Timing Camshaft Sprocket	
1	SFI	21348MP	NAPA Proformer Engine Oil Filter	
5.5	OIL	OIL0W20SYNNAPA	Ful Synthetic 0W20 Motor Oil	

Labor

Parts

Shop supplies

Total	\$1,028.17
PAYMENT	\$1,028.17
BALANCE DUE	\$0.00

Invoice

Date	
1/9/2024	

Ship To

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
			1/9/2024			
Quantity	Item Code	Description	Price Each	Amount		
1	PART	9-5611(az) CHAIN GUIDE				
1	PART	JV5179(az) TIMING COVER SET				
20.1	LABOR	timing cover, guides, sprocket LABOR				
1	OIL CHANGE 6 qt	oil change 6 qt				
1	waste oil disposal fee	waste oil disposal				
1	PART	35-1383(az) VARIABLE TIMING SPROCKET				
1	PART	600-488(or) FRONT DIFF ACTUATOR				
1	PART	16711-0C140(bh) SHROUD				
1	PART	24F-DL(az) DURALAST BATTERY (2YR WARR)				
1	PART	ELECTRONIC CHASSIS CONTROL MODULE (5TFPX4EN6CX010601)(lkq) INV#152031195				
2	PART	2-4800DL(az) U-JOINT				
1	PART	TRANSFER CASE ASSEMBLY(5TEUU42NX8Z508963)(lkq) INV#152031130				
8	LABOR	LABOR transfer case,diff acuator,ujoint,				
2	ANTI-FREEZE	ANTI-FREEZE				
1	Outside	OUTSIDE SERVICE weld timing cover Sales Tax				