

Repair Order

In Date: Jun. 24,2023

P/U Date: Aug. 24,2023

MODEL INFORMATION

Year	Manufacturer	Model	Model Code	Color	VIN/HIN/SN	Engine #	Keyboard	In - Out
2012	Polaris	RZR 900 XP		White Voodoo Blue	4XAJT9EA3CB601033	0120465507255		3217.00 - M / 249.00 - H

Job: Motor locked up.

Polaris RZR 900 XP 2012 - 4XAJT9EA3CB601033

Do a full inspection and see what it all needs.
Give quote.
Quoted \$10000

Part #	Part Description	Qty	Price	Unit Extension	Extension
0925-1318	CAMCHAIN TENSIONER POL, HC00063				
PSN R1009-S	PSN POLARIS RZR 900 XP 11-12 ENGINE MOTOR REBUILT 6 MONTH WARRANTY				
2889398	PS-4 0W50 EXTREME BULK SOLD BY QT.				
2878068	AGL GEARCASE OIL QTS(12)	1			
2877922	DEMAND DRIVE PLUS,QT				
7081889	ASM-FILTER,INTAKE				
2540086	FILTER-OIL,10 MICRON,(12)				
3211148	BELT-DRIVE,10.5,CD				
5138791	SHAFT-PIVOT,250.28MM,15.88OD				
5436973	BUSHING-A-ARM,LONG,102.36MM(10)				
2202015	KIT,CROSS & BEARING,NONGREASE				
1543377-458	ASM-RADIUS ROD,M.BLK				
1542940-458	ASM-RADIUS ROD,TOP,BLK				
7081620	SHIFT CABLE				

Technician	Description
BHamm	Motor locked up.

Resolution:

replaced motor, ran it and did first service
had to open motor and replace exhaust cam
from old motor because PSN put 2 intake cams
in so motor wouldn't run, PSN said they'd cover
time and the tensioner
replaced radius rods
replaced front upper arm bushings
changed all fluids
replaced throttle cable

Recommended Repairs:

rear radius rods have play
front upper arm bushings
front propshaft ujoints have a little play
throttle cable is locked up
fluid change
PSN motor

Notes:

[REDACTED] Total: \$10,281.78

07/27/2023

08/24/2023

We appreciate your feedback. If you are unsatisfied with the level of service provided, please contact us at 620.846.2259 or email at info@countryfeeds.com.