

* CODE N = NEW U = USED R = REBUILT

QUAN.	*	PART NO.	DESCRIPTION
1			clutch
1			rear main seal
2			rear mtr. mount 7 ⁰⁰ / ₁₆
2			5/8 x 3 bolt 4 ⁰⁰ / ₁₆
6			5/8 x 4 bolt 5 ⁰⁰ / ₁₆
8			5/8 lock nut 3 ⁰⁰ / ₁₆
1			3/4 x 6 bolt
2			3/4 lock nut 3 ⁰⁰ / ₁₆
1			long x shaft (pctc)
1			short x shaft
2			x-shaft bushing 12 ⁰⁰ / ₁₆
1			release fork
1			pilot brg.
1			release fork lever
1			grease hose
1			imp. cover w/ grommet
4			1/8 x 5/16 x 20 inch rod 9 ⁰⁰ / ₁₆
1			3" x 40" ex. elbow
4.5 ft.			5" straight pipe 15 ⁰⁰ / ₁₆
1.5 ft.			5" stainless flex 25 ⁰⁰ / ₁₆
4			5" perforated pipe 30 ⁰⁰ / ₁₆
1			5" silencer pipe
mbc.			hanger bracket/bolt/nut etc.
mbc.			bolt/nut/clamp/tie etc.
* note: used new clutch brake supplied by customer.			
TOTAL PARTS			
SUBLET REPAIRS			
1			re-surf face fly wheel
TOTAL SUBLET REPAIRS			

YEAR 1966	MAKE Dodge	MODEL 387	COLOR White	LICENSE TG 8645	SPEEDOMETER 807,428												
MOTOR NO. L-15 Auct CAT		SERIAL NUMBER 6D632636															
LUBRI- CATE	CHANGE OIL	FLUSH TRANS.	FLUSH DIFF.	WASH	POLISH												
OPER. NO.																	
INSTRUCTIONS																	
TK1 - Clutch will not release at times. Found pieces of springs in belt housing, clutch coming apart. R/F exhaust splitter and cab over, drive shaft, etc. for access. Pull tranny, clutch & flywheel. Rear main seal leaking oil. Replace rear main seal. Rear motor mount broken. Jack up engine & replace rear motor mount and all bolts & nuts. Have flywheel re-surfaced, replace clutch, pilot brg., release fork & both x-shaft & bushing, & broken release lever. Re-assemble, adjust clutch brake & free travel. Re-build extremely rusted out exhaust pipe & band & install hangers for exhaust. Test drive & check over, works great, no leaks, etc.																	
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck, or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.																	
AUTHORIZATION BY:																	
RECEIVED BY:																	
<table border="1"> <tr> <td>Not Responsible For Loss or Damage to Cars or Articles Left in Cars in Case of Fire, Theft or Any Other Cause Beyond Our Control.</td> <td>Gas, Gas @</td> <td></td> </tr> <tr> <td></td> <td>Oil, Oil @</td> <td></td> </tr> <tr> <td></td> <td>Gas, Trans. Fld. @</td> <td></td> </tr> <tr> <td></td> <td>TOTAL</td> <td></td> </tr> </table>						Not Responsible For Loss or Damage to Cars or Articles Left in Cars in Case of Fire, Theft or Any Other Cause Beyond Our Control.	Gas, Gas @			Oil, Oil @			Gas, Trans. Fld. @			TOTAL	
Not Responsible For Loss or Damage to Cars or Articles Left in Cars in Case of Fire, Theft or Any Other Cause Beyond Our Control.	Gas, Gas @																
	Oil, Oil @																
	Gas, Trans. Fld. @																
	TOTAL																
<table border="1"> <tr> <td>F.S.</td> <td>Total Labor</td> </tr> <tr> <td></td> <td>Total Parts</td> </tr> <tr> <td></td> <td>Sublet Repairs</td> </tr> <tr> <td></td> <td>Freight</td> </tr> <tr> <td></td> <td>Subtotal</td> </tr> <tr> <td>4.5% TAX</td> <td>TOTAL \$ 558.25</td> </tr> </table>						F.S.	Total Labor		Total Parts		Sublet Repairs		Freight		Subtotal	4.5% TAX	TOTAL \$ 558.25
F.S.	Total Labor																
	Total Parts																
	Sublet Repairs																
	Freight																
	Subtotal																
4.5% TAX	TOTAL \$ 558.25																

17064

DEALER REGISTRATION NO.

CASH CHARGE BUDGET

DATE 12-2-24 A.M. P.M.

PHONE YES NO

PROMISED A.M. P.M.

RETAIN PARTS FOR INSPECTION

DISCARD PARTS

LABOR