

Vehicle: 2003 Ford E550 Super Duty

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
1	---	3J8272	SEAT BELT	New		
Note: CLOSE CALL INV72191						
1	LIT	94706	LED ADAPTER PLUG			
2	NS	76686	GAS GRANDE FLEET SHOC			
2	NS	911039	REFLEX TRUCK SHOCK			
1	IFD	3C329NS17AA	BOLT	New		
1	IFD	W300010	BOLT	New		
1	ECH	AR272	RELAY			
1	SLO	94789	PIG TAIL	New		
1	LIT	19721	MOUNT	New		
1	LIT	1960	LAMP			
1	2KW	440161MTL	FIRE EXTINGUISHER	New		
1	2KW	798S1G	TRIANGLE FLARE KIT	New		
1	LIT	60559R	LED 60 STT FLN HW AMP	New		
1	9IN	27293	OIL PAN GASKET	New		
1	ATP	15924	Automatic Transmission Filter Kit - Rubber Coated Metal - OE Style - Carded			
Note: w/ 4R100 Transmission;w/ Deep Pan;Refer to Tech Bulletin;w/ 20 Bolt Pan						
2	9IN	MS408221	STABILIZER LINK	New		
1	MMM	08880	NON-CHLOR BRAKE CLNR	New		
1	---	81952911	OIL FILLER CAP			
1	9HD	F81Z7A194BA	PAN ASSEMBLY	New		
1	9NJ	6002001	OIL COOLER			
2	OWI	NPB20	Wiper Blade - NAPA - Front			
1	9HD	TA6310	TIE ROD END	New		
1	9HD	29497	LEFT INNER DRAG LINK	New		
1	---	8192006	DIP STICK TUBE	New		
1	---	FP20B	OIL PAN			
2	9HD	YC3Z5484BA	BUSHING	New		
1	BRG	HB88508A	D/S BRG			
1	1FD	7C2Z17683DA	MIRROR	New		
1	OIL	1540	PREMIUM DIESEL OIL			
7	OIL	DEXRON5	FULL SYNTHETIC TRANS FLUID			
5	9OC	ANTIGAL	FLEETCHARGE 50/50 ANTI FREEZE	New		
4	---	173026009	225/70/19.5 RM 257			
Note: 22570195						
4	-	FET	FEDERAL EXCISE TAX			
2	---	173026024	225/70/19.5 RM170+	New		
Note: 22570195						
2	-	FET	FEDERAL EXCISE TAX			
6	-	DISPLTT	LIGHT TRUCK TIRE DISPOSAL			

JJD COMPANIES

Qty Code/Tech* Reference
6 --- VALVESTEMHD
BK* DOT
Note: DECAL #24088954
1 9HD 29497

Description
VALVE STEM HEAVY DUTY
DOT INSPECTION
LEFT INNER DRAG LINK

Vehicle: 2003 Ford E550 Super Duty

Condition

New

Labor
Parts
Tires
Shop Supplies
DISPOSAL OF HAZARDOUS MATERIALS
Charges
Sales Tax

Total
PAYMENT
BALANCE DUE \$11,069.38

Technician Code Certification #

JA
BK

***ALL INVOICES ARE DUE UPON RECEIPT. 1.5% FINANCE CHARGE WILL BE APPLIED TO ALL INVOICES AFTER 30 DAYS WITH A \$3 MINIMUM

ALL VEHICLES THAT HAVE HAD TIRES REMOVED OR ROTATED NEED TO RETURN FOR WHEEL RETORQUE AFTER 50 MILES.
THANK YOU FOR YOUR BUSINESS

Customer Signature _____

415

DR
P/M - 61200

3/19/24

3/19/24