

Invoice Number: 8096

Invoice Date: May 30, 2023

		CONTRACTOR OF THE PARTY OF THE	
Parts & Labor	Quantity	Unit Price	Line Total
Turbo charger And Gaskets	1		
Oil Return Tube Turbo Charger	1		
Water pump	1		
Dip Stick tube Kit Metal and plastic	1		
Thermostat kit	1		
Oil Filter	1		
Fuel Filter	1		
Outer air filter	1		
Coolant	4		
Inner air filter	1		
Oil 15W40D	12		
Cleaner	12		



Parts & Labor	Quantity	Unit Price	Line Total
Service Completed Our shop / Removed bad engine, Removed all parts and transferred to new Engine. Installed new Turbo charger, New water pump, New oil return tube, New Dip stick, Rebuilt Injection pump, All new filters, New thermostat. Installed new engine.	40		
		Total:	\$8,148.58
		Amount Due (USD):	

Sales Order

Date	S.O. No.	
3/27/2023	BSO-21769	

Item	Description	MPN	Serial No.	Qty	Rate	Amount
B4.5 Std LB	housing S/N: 20225744 XSK0518 - 65/80 LB4.5DP-3 #5744 Long block assembly, B4.5 Front Gear Train with gear housing for VE or DP injection pump. Includes block, head, internal rotating assembly, gear housing and cover, camshaft, gear train, valve train, lube oil pump and cooler, front sump oil pan, gear, valve, and side covers, rear main seal. All parts used from failed engine must meet re-use guidelines and be free of contamination 4B/B4.5FGT Lower Gasket set			1		
3804896DK	4B/B4.5FGT Upper Gasket Set	3804896		il		

Total