

SOLD TO

**SHIP TO** 

CONTACT

PAGE 1 OF 1
"" CREDIT CARD ""

05-MAR-2020	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
CUSTOMER NO.	SHIP VIA WILL CALL	FAIL DATE	ENGINE SERIAL NO. 79013587	CPL NO.	EQUIPMENT MODE
REF. NO. OE-100-95647	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
UANTITY BACK	QUANTITY PART		PRODU	CT	

ORDERED ORDER	ED SHIPPED NUMBER	DESCRIPTION	CODE	UNIT PRICE	AMOUNT
1	1 5362253	PUMP, FUEL TRANSFER	CECO		
1	1 4954474	GASKET,SUPPORT	CECO		

TRACKING#

SUB TOTAL: LOCAL TAXES: STATE SALES TAX:

522

Billing Inquiries? Call (877)480-6970 or email CBSNPower.Receivables@cummins.com

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

**TOTAL AMOUNT: US \$** 

476.13

RECEIVED BY (print name)\_

SIGNATURE

DATE

6-7-23 paced 7279

Purchase Order	
то	DATE 6-7-23
ADDRESS	DATE REQUIRED
CITY, STATE, ZIP	TERMS UM 4
SHIP TO	HOW SHIPPED
ADDRESS	REQ. NO. OR DEFT.
CITY, STATE, ZIP	Miles 696195
QUANTITY DESCRIPTION	PRICE UNIT
1 L Noise in from	t of engine
Removed Radi	
3 Gear housing	cover uper
and lower, i	nspected all
gear they lo	ock ok -
	ack lash in gear
1 they were	out adjusment
	rs and inspeted
· Gear bushing	gs the checked
10 ot, cheened h	lousia bear install
	engine work of
12 customer drove	
	nt engine, hooted
" computer to en	
15 one overfueling,	Removed and istalle
IMPORTANT	new insector Please send copies of your INVOICE
Purchase Order Number must appear on all invoices - packaging, etc.	with ORIGINAL BILL OF LADING.
to complete the order by date specified.	abor \$ 2800
A-6831 T-46140/46141 ORIGINA	IL 01-11

BILL TO

INVOICE # 6175

DATE 05/20/2023

DUE DATE 06/10/2023

TERMS Net 10

DATE	SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
05/20/2023	INJECTOR-HD ISX 870	4088665RXCUM	1		
	ACTUATOR- METERING KIT (ISX)	4089985RXCUM	lash if q		
	KIT ACTUATOR (ISX)	4089986PXCUM	0011151		
	GASKET SUPPORT ACCESSORY DRI	4965690CUM	10		
	VALVE COVER GASKET ISX 870	4026507CUM	4 500 11		
	frent main-seal ISX (99-02)	4955383	A TOP OF THE		
	FRONT GEAR HOUSING GASKET	4985562CUM	gue beet		
	Shop-Supplies	MISC	cuad ng		

TRK# 4 INTERNATIONAL DAY CAB VIN# 4C091294 MILEAGE (696186) SUBTOTAL TAX TOTAL BALANCE DUE

\$2,985.74

BILL TO

INVOICE # 6166
DATE 05/11/2023
DUE DATE 06/10/2023
TERMS Net 10

DATE	SERVICE	DESCRIPTION	OTY	RATE	AMOUNT
05/11/2023	Eaten clutch 2050	125M/2104-30892525	1		CONTRACTOR OF STREET
	FLYWHEEL	RESURFACE	1		
	Pilet Bearing	Pilot Bearing BC306DD / N25- 63062RS	1		
	Clutch Brake 200	AHB200	1		
	Clutch Ferk	FR105C137	1		
	Shift Tower Gasket	4305294	1		
	Short C/S Bushings	12815	4		
	Cress-Shaft (short)	106C1498	1		
	ISX Rear-Seal- Crankshaft	4965569CUM	1		
	REAR MOTOR MOUNT KIT (IHC)	401C/4965569	1		
	50WT-Syn Gear Oil	50WT SYNTHETIC	5		
	9" Grease line	CLT009P	1		
	M JIC 7/8-STRAIGHT FITTING #10	6400-10-08	2		
	Brake Clean / W7340	Brakleen	6		
	Laber/hr	-REPLACE NEW 2050 EATON CLUTCH. -REPLACE NEW REAR MOTOR MOUNTS. -RESURFACE FLYWHEEL. -REPLACE REAR MAIN SEAL.	1		



-REPLACE NEW TRANSMISSION. (CP)

Note, 1-		
TERMS: Net 10 to all past due	balances. This is an ANNUAL PERGEN	(44)
OUAN.	CHARGE ON ACCT. MOSE RET. FALL DESCRIPTION	YAWAY CUST ORDER NO.  PRICE AMOUNT
Z FROF 1 Z K412 7	16210£ #e/25	
Trons	Chare o	
neceived by	MUST be accompanied by this bill.	
EGENDS	Thank you!	TOTAL 5 295 45

TRK# 4 INTERNATIONAL DAY CAB

VIN# 091294

MILEAGE (696186)

BILL TO

INVOICE # 5710
DATE 04/08/2023
DUE DATE 04/10/2023
TERMS Net 10

4,664.97

	2521125				
DATE	SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
04/08/2023	seal-rectangular strip	4962722CUM	1		
	gasket-front cover	4962721CUM	1		
	front main-seal ISX (99-02)	4955383	1		
	KIT-MAIN BEARING	5406110CUM	1		
	Bearing-Rod (Set)	Bearing -Rod (Set) 4089405CUM	6		
	Oil Pan Gasket (ISX)	4026684	1		
	Retella Oil	15/40	13.50		
	Oil Filter LF14999NN22	Oil Filter LF14000NN	1		
	SPICER U JOINT.	250	2		
	DRIVELINE	-SPL SLIP YOKE -SPLINED SLEEVE -SUPPLY CHG -MACHINE TIME & LABOR	1		
	Shop Supplies	misc	1		
	Labor/hr	-R&R rod & main bearings with new oil pan gasketchange oilR&I drive line back of transmission & install 2 new u joints.	1		

SUBTOTAL

TAX

TOTAL

From:

Sent: Wednesday, July 12, 2023 11:49 AM

To:

Subject:

Engine oil leak and misfire, hooked computer to engine ecm found code in fuel solenoids front ran test found to be shorth out. Removed and installed use solenoids and tested they work ok, order new solenoids and installed in truck, engine work ok. Found engine oil leak at air compressor drained coolant removed air compressor lines and power steering pump. Removed air compressor and cleaned installed new seal, installed air compressor back started truck checked for leaks found no leaks



BILL TO

SHIP TO

INVOICE # 22640 DATE 12/26/2023

DESCRIPTION		QTY	RATE	AMOUNT
Exchange:ECM Exchange Cummins ISX/ISM ECM Exchange - Cummins ISX/ISM Model: CM ISX 870 ***ONE YEAR WARRANTY included*** WARRANTY ID# 1394 NW# 19183 (121/29/23) Fed Ex Overnight EXS 12pm	at. 12/30/23 by	1		
Exchange:Core Received  Core received and approved as a repairable core		1		
Services:ECM Programming - Custom ECM Programming Services - Custom Programmi	na	1		
Services:Shipping & Handling Shipping & Handling Services FedEx Ground® End of Day Thu Dec 28, 2023		1		
No refunds on services delivered. No returns for goods purchased.	SUBTOTAL			
	TOTAL PAYMENT			1,950.00

QUAN.	PART NO.	T DESCRIPTION	PRICE	7		4.6344.6		51	835 B
- 1	dy300-29	9 Kito DIN	1 00012	1111					
		The Control of the							1
				CONTROL OF THE PERSON SEED	E .			d	
		1			1000000				
-				NAME				DATE 4-2	7909A
				ADDRESS	0.00	9 9		PHONE	
			1	CITY				PROMISED	A.M./P.M
1		0.5		YEAR T	Tuter Tuter	9400i	COLOR MILEAG	E	PHONE WHEN READY
								N CUST. ORDER I	NO. YES NO
			Ī	UNIT NO.	SERIAL N	091294	SERVICE SALESMA	N CUST. ONDER	NO. YES NO
				OPER. NO.	1,00	DESCRIPTI	ON OF WORK		AMOUNT
				TONY		ALigw.	Steer Luic		
	1997			33	MX 47	4 CASTO	- 1	2 X 2 CAMBO	¥ .
	188 24			To	0		E 2		
	2100 N/3					1		10	
-	000 014 ·			TOWY IN	STALL NY	en King &	in Lestind	Kiylor, Class	
	120		1	chinic 1800	some le	HARR CHO	rolsade . PRES	W. Carper	
-					# 3				
		TOTAL PARTS	i						
	OUTSIDE	REPAIRS							
		9		100					THE PERSON
	5 5 5	1	ļ	Not Responsible Cars in Case of F	le for Loss or ire, Theft or A	Damage to Car ny Other Cause	rs or Articles Left in e Beyond Our Cont	TOTAL LABOR	
18 8	ACCESS	ORIES .		I hereby authorize the a	bove repair work t	o be done along with	h the necessary material,	and OUTSIDE REP	
3	Stop.	Supply		described on streets, his	ghways or elsewhe	ere for the purpose of	h the necessary material, the car, truck, or vehicle he if testing and/or inspection truck or vehicle to secure only, material is extra.	ACCESSORIE	
19.1		2 9 1		amount of repairs the	n I understand est	imates are for labor	only, material is extra.	GAS, OIL, GRI	EASE
		7 3 3 3 3		AUTHORIZED BY				SUB'	TOTA
				RECEIVED					TA
	TOTAL ACCE	SSORIES							TOTAL 902
STOWN N	NO SERVICE DE LA CONTRACTION D								
	A CASA CONTRACTOR			S (F S KARKER)	ANALYSIA S	DECEMBER	THEFT	ISLUSTED IN	

