



Invoice for RO #14811

Date Created: 04/21/25 at 02:24 PM CDT

Vehicle: 2013 Ford F-350 Super Duty XLT

Client concerns:

- no start, throwing codes for trans
- dead battery

1 - DIAGNOSE NO START

Tech: A Underwood

Labor: DIAGNOSE NO START. FOUND VEHICLE IS NOT REGISTERING A KEY. BELIEVE VEHICLE NEEDS A NEW KEY

Part: NEW CHIPPED KEY + SERVICE CALL

✓ Approved on 04/28/25 at 11:32 AM CDT

2 - BATTERY

Tech: A Underwood

Labor: Remove & Replace Battery (One)

Part: Economy

✓ Approved on 05/28/25 at 11:58 AM CDT

Total Repair Order & Signature:

Grand Total: \$767.87