

Remit

Branch

Boyd Okc

Date	Time	Page
09/19/25	22:30:49 (B)	01
Account No	Phone No	Inv No
DIAMO005		S13071
Ship Via	Purchase Order	
	76442	
Tax ID No		
	73-00064	
		Salesperson
		RCG

SERVICE INVOICE

holding.

AST02 - 9-15-25: 5932 Hr.

1RW9570RCJE062083

PTP 000190.02 - Engine and Transmission Input Speed
Conflict

CONTINUED ON PAGE 02

TERMS: NET 10th OF MONTH FOLLOWING PURCHASE. A CHARGE OF 1.5% PER MONTH (18% PER ANNUM) WILL BE ADDED TO ALL PAST DUE ACCOUNTS. ANY ACCOUNTS PAST DUE WILL BE SUBJECT TO A CASH BASIS ONLY.

Return Policy: All claims and returned items must be accompanied by this invoice and in original package. Claims for shortage, errors or imperfections should be made in writing within five (5) days after receipt of goods. Returned non-stock items are subject to 25 % restocking charges, additional freight and handling charges. Return items prepaid to 4220 W. Reno Ave Oklahoma City, OK 73107.

Remi

Branch			
Boyd Okc			
Date	Time	Page	
09/19/25	22:30:49 (B)	02	
Account No	Phone No	Inv No	
DIAM0005		S13071	
Ship Via	Purchase Order		
	76442		
Tax ID No	73-0706457		
		Salesperson	
		RCG	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
Q013396	9570R 570HP SCR TR	5492	1RW9570RHJE060427	03/27/20	2000
442	9570S	S	80041107	01/01/75	3000

Gained access to the transmission input speed sensor since it was not reading RPM in address 42.

Unplugged the speed sensor and there was no voltage. Ohmed out the wires from the sensor to the rear frame controller and they were both OL.

Informed Scott that new wires will have to be ran.

AST02 - 9-16-25

Ran 2 new wires for the transmission input speed sensor Spliced them into the rear chassis harness at the controller and at the sensor connector.

Started the tractor and it would now go into forward and reverse gears. Informed Scott the tractor will now move and he asked me to button up what I took apart and leave the rest.

1040001	LABOR	SEGMENT TOTAL==>	1092.50
---------	-------	------------------	---------

SEGMENT# 2 C AST02 FSC 09/15/25 09/15/25 09/30/25

FIELD SERVICE CHARGE

CONTACT: Scott 405-431-7089

ADDRESS OR COORDINATES: 336 N Falcon Dr, OKC, OK

FIELD SERVICE CHARGE: \$60.20 ROUND TRIP

TOTAL NUMBER OF TRIPS: 2

1040001	LABOR	SEGMENT TOTAL==>	120.40
---------	-------	------------------	--------

***** WORK ORDER TOTALS *****

LABOR	1212.90
-------	---------

CONTINUED ON PAGE 03

TERMS: NET 10th OF MONTH FOLLOWING PURCHASE. A CHARGE OF 1.5% PER MONTH (18% PER ANNUM) WILL BE ADDED TO ALL PAST DUE ACCOUNTS. ANY ACCOUNTS PAST DUE WILL BE SUBJECT TO A CASH BASIS ONLY.

DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Return Policy: All claims and returned items must be accompanied by this invoice and in original package. Claims for shortage, errors or imperfections should be made in writing within five (5) days after receipt of goods. Returned non-stock items are subject to 25% restocking charges, additional freight and handling charges. Return items prepaid to 4220 W. Reno Ave Oklahoma City, OK 73107.