

DESCRIPTION

FIX LIGHTS- backed trailer into shop had to rewire the male plug from a 5 pin automotive to a 7 pin semi plug. also had to replace the two four in round stop turn tail lights in center of trailer also replaced 1 amber 2in light. all lights working correctly at this time.

BRAKES INOP- inspected and found that all the brakes were out of adjustment tried to adjust brakes and found that the slack adjusters were siezed up got customer approval to replace all four slack adjusters. removed the slack adjusters three out of four had to be heated and hammered off. cleaned and installed four new slack adjusters and adjusted brakes. greased the trailer and checked wheel hub oil level. all ok at this time

installed mud flap on right hand side and moved pinnal hitch down

clevis pin kit pl-806 kt

brake clean 3m

lucas hub oil

2in amber light

LED stop turn tail rf826r-7

3-way plug rf421-491

mudflap

22-18 gauge butt connectors 87670 1

male 7-way 15-730

slack adjuster r803110

- - -

BALANCE DUE

\$1,681.53