

Service Invoice

Customer

Engine Serial Number

Memo

Customer Service Issue # 1

Com: wont start

Cause: failed starter and batteries weak

F

ound the no start issue to be a defective starter and weak batteries. Ordered a new starter and batteries. Had to clock the mounting head on the starter to mount on the customer's Started machine. Tested operation. Noticed the belts are slipping. Removed belts. Drove to returned to location and installed new belts. Tested complete operation. Job complete.

N

Description

Field

V-BELT

STARTER

6mo wty bat

Subtotal \$2,119.84



\$2,191.17	PAY THIS AMOUNT



Com: HYD LEAK

Cause: BLOWN HOSE

Fix: DROVE TO JOBSITE, LOCATED MACHINE, LOCATED BLOWN HOSE, REMOVED HOSE, DROVE TO AMERIFLEX HAD NEW HOSE MADE,
DROVE BACK TO MACHINE INSTALLED AND CHECKED FOR LEAKS, NO LEAKS.

Note:

Subtotal	\$976.15
----------	----------