



INVOICE W 47712  
 Date //  
 Date Open 08/31/2021

Sold To : 232-9800 785

Ship To :



|                      |               |                  |               |          |       |          |
|----------------------|---------------|------------------|---------------|----------|-------|----------|
| Written By<br>NCHRIS | Terms<br>CASH | Time<br>09:22:17 | Customer Po # | Promised | Phone | Ship Via |
|----------------------|---------------|------------------|---------------|----------|-------|----------|

|              |         |              |                      |             |                           |                 |        |
|--------------|---------|--------------|----------------------|-------------|---------------------------|-----------------|--------|
| Unit #<br>28 | Plate # | Year<br>2010 | Make<br>FREIGHTLINER | Model<br>M2 | Mileage/Hrs<br>139916/0.0 | VIN<br>ADAM6746 | Engine |
|--------------|---------|--------------|----------------------|-------------|---------------------------|-----------------|--------|

| Qty   | Loc    | Description                                  | Price    | Amount   |
|-------|--------|--|----------|----------|
| 1.000 | IMPDR  | NFC71515 1/4X1/8 MALE CON                    |          | 2.49     |
| 1.000 | VISION | FRTINCOMING INCOMING FREIGHT- OIL GAUGE TUBE |          | 13.34    |
| 1.000 |        | CUM3969058 OIL GAUGE TUBE                    |          | 171.28   |
| 2.000 | DISP4  | ALL27101-CTCS TRANSYND ATF 1 GALLON          |          | 109.46   |
|       |        |  | SubTotal | 35546.63 |



Parts.....  
 Labor.....

Env/Shop Sup  
 Freight.....

Sub Total  
 Sales Tax....

UPON RECEIPT OF INVOICE. ALL CURRENT BALANCE(S) DUE ON RECEIPT.

Thank you for your business and we look forward to serving you again.

TOTAL DUE

41388

INVOICE W 47712  
 Date //  
 Date Open 08/31/2021

Page: 3 of 5

Sold To : 232-9800 785

Ship To :

|  |  |
|--|--|
|  |  |
|--|--|

|                      |               |                  |                      |             |                           |                 |        |
|----------------------|---------------|------------------|----------------------|-------------|---------------------------|-----------------|--------|
| Written By<br>NCHRIS | Terms<br>CASH | Time<br>09:22:16 | Customer Po #        | Promised    | Phone                     | Ship Via        |        |
| Unit #<br>28         | Plate #       | Year<br>2010     | Make<br>FREIGHTLINER | Model<br>M2 | Mileage/Hrs<br>139916/0.0 | VIN<br>ADAM6746 | Engine |

| Qty   | Loc   | Description  | Price | Amount   |
|-------|-------|--|-------|----------|
| 1.000 |       | INSTALLED BELL HOUSING ON NEW ENGINE. REMOVED OIL PAN AND PICK UP TUBE FROM NEW ENGINE. INSTALLED FRONT MOTOR MOUNT. INSTALLED BELL HOUSING BOLTS, TORQUE CONVERTER BOLTS, STARTER, AIR COMPRESSOR, BRACKETS, ALTERNATOR, AC COMPRESSOR, FAN HUB, TENSIONER BELT AND FAN. INSTALLED RADIATOR, FAN SHROUD, CHANGED BALANCER TO ONE FROM OLD ENGINE. ONE ON NEW ONE WAS TOO LARGE. INSTALLED RADIATOR HOSES AND COOLANT HOSES. CLEANED AND INSTALLED OIL PAN AND PICK UP FROM OLD ENGINE. FILLED WITH OIL. INSTALLED NEW COOLANT FILTER. VACUUM FILLED COOLING SYSTEM. VACUUMED AC SYSTEM, INSTALLED NEW EXHAUST FLEX PIPE. INSTALLED NEW OIL FILTER. CHANGED PARAMETERS WITH INSITE. STARTED ENGINE AND CHECKED FOR LEAKS. FOUND PIPE PLUG ON OIL FILTER HOUSING LEAKING. TIGHTENED AND DOUBLE CHECKED FOR LEAK, LEAK WAS GONE. FOUND FITTING ON TRANSMISSION FOR OIL COOLER HOSE LEAKING. REMOVED FITTING AND FOUND IT WAS CRACKED. INSTALLED NEW FITTING. REFILLED TRANSMISSION. STARTED AND CHECKED FOR LEAKS, ALL OK. ROAD TESTED WITH NO ISSUES, UPON RETURN, CHECKED FOR LEAKS AGAIN. ALL OK. |       | 26500.00 |
| 1.000 |       | CUMDR6431RX ENGINE   |       | 373.07   |
| 1.000 |       | ABPN49F26374 EXHAUST BELLOWS   |       | 9.72     |
| 5.000 | SEC11 | HAL224394045 METALLIZED BULB HOLDER  |       | 13.90    |
|       |       | HTIHHBLU037 BLUE SILICONE HEATER HOSE 3/8  |       |          |

Disclaimers of Warranties: Any Warranties on the products sold hereby are those made by the Manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and Pluss Corporation neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. We hereby certify that these goods were produced in compliance with all applicable requirements of sections 8, 7 and 12 of the fair labor standards act of 1938. As amended and or regulations and orders of the administrator or wage and hour division issued under section 14 thereof. PAYMENT FOR TECHNICAL SUPPORT AND INVOICES ARE DUE UPON RECEIPT OF INVOICE. ALL CURRENT BALANCE(S) DUE ON RECEIPT.

Parts.....  
 Labor.....

Env/Shop Sup  
 Freight.....

Sub Total 38447.67  
 Sales Tax.... 2941.25

Thank you for your business and we look forward to serving you again.

TOTAL DUE Continued o

INVOICE W 47712  
 Date / /  
 Date Open 08/31/2021

Page: 2 of 5

Sold To : 232-9800 785

Ship To :

|  |  |
|--|--|
|  |  |
|--|--|

|                      |               |                  |               |          |       |          |
|----------------------|---------------|------------------|---------------|----------|-------|----------|
| Written By<br>NCHRIS | Terms<br>CASH | Time<br>09:22:16 | Customer Po # | Promised | Phone | Ship Via |
|----------------------|---------------|------------------|---------------|----------|-------|----------|

|              |         |              |                      |             |                           |                 |        |
|--------------|---------|--------------|----------------------|-------------|---------------------------|-----------------|--------|
| Unit #<br>28 | Plate # | Year<br>2010 | Make<br>FREIGHTLINER | Model<br>M2 | Mileage/Hrs<br>139916/0.0 | VIN<br>ADAM6746 | Engine |
|--------------|---------|--------------|----------------------|-------------|---------------------------|-----------------|--------|

| Qty   | Loc    | Description  | Price    | Amount  |
|-------|--------|--|----------|---------|
| 1.000 |        | FREA22-72462-000 CONDENSER                             |          | 394.29  |
| 1.000 | VISION | FRTINCOMING INCOMING FREIGHT                           |          | 25.00   |
| 9.000 | DISP4  | FLECC36077 ANTI FREEZE RED EXTENDED LIFE RED 50/50 MIX |          | 123.03  |
| 1.000 | SEC11  | HTISHBLU225 2 1/4 SILCONE STICK HOSE S-22843           |          | 28.93   |
| 1.000 | SEC11  | HTISHBLU200 2" SILICONE STICK HOSE 2" S-22842          |          | 26.84   |
| 4.000 | PEG1R  | NFC40532 32 LINER CLAMP                                |          | 12.04   |
| 2.000 | PEG1R  | NFC40536 36 LINER CLAMP                                |          | 7.70    |
| 1.000 | VID5D  | NEWS22123 RADIATOR CAP 16PSI RC1630                    |          | 15.79   |
|       |        |  | SubTotal | 2776.04 |

Complaint : CHECK AND ADVISE ENGINE RUNNING HOT AND PUSHING COOLANT. (RADIATOR JUST REPLACED)

Correction : FOUND ENGINE WAS PASSING COOLANT AFTER RADIATOR INSTALL. PULLED CYLINDER HEAD TO CHECK FOR DAMAGE. SUGGEST ENGINE REPLACEMENT. PULLED HOOD, DRAINED COOLANT, EVACUATED REFRIGERANT. REMOVED RADIATOR AND REMAINING COMPONENTS IN ORDER TO PULL ENGINE. REMOVED OLD ENGINE. REMOVED FRONT ENGINE MOUNT, BELL HOUSING, BALANCER AND OIL PAN FROM OLD ENGINE.

7727.29

Disclaimers of Warranties. Any Warranties on the products sold hereby are those made by the Manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and Plus Corporation neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. We hereby certify that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the fair labor standards act of 1938. As amended and or regulations and orders of the administrator or wage and hour division issued under section 14 thereof. PAYMENT FOR TECHNICAL SUPPORT AND INVOICES ARE DUE UPON RECEIPT OF INVOICE. ALL CURRENT BALANCE(S) DUE ON RECEIPT.

Parts.....  
 Labor.....  
 Env/Shop Sup  
 Freight.....

Thank you for your business and we look forward to serving you again.

Sub Total 38447.67  
 Sales Tax.... 2941.25

TOTAL DUE Continued o

Summ  
PO Bo  
877.2  
435.2  
DUNS

Cus

Gr  
Je  
35  
To  
U

**Quoted To:**



| Customer ID | Good Thru | Payment Terms | Sales Rep |
|-------------|-----------|---------------|-----------|
| GRE400      | 1/7/18    | C.O.D.        |           |

| Quantity | Item | Description  | Unit Price | Amount    |
|----------|------|--|------------|-----------|
| 1.00     |      | ROTOBEC ELITE 80 M-21<br><br>ROTOBEC ELITE 80 M-21, 20' 6" MAX REACH, A-FRAME OUTRIGGERS, CONTINUOUS ROTATION USING ROTOBEC HYDRAULIC JOINT AND ELECTRICAL COLLECTOR RING. MAX OPERATING PRESSURE AT 3300 PSI, 12 VOLT STANDARD, STANDARD ROTOBEC YELLOW AND BLACK.<br><br>INCLUDES REMOVAL OF EXISTING CRANE, COLLIS CRANWORKS KEEPS OLD CRANE, INCLUDES INSTALLATION OF NEW CRANE AND REQUIRED ACCESSORIES SUCH AS NEW PTO AND PUMP, HYDRAULIC TANK, HOSES, NEW FLUID, AND COMPLETE LOAD TESTING.<br><br>REUSE OF CUSTOMERS KINSHOFER HPX GRAPPLE. GRAPPLE IS TO WORK CORRECTLY WITHIN HYDRAULIC PARAMETERS OF ROTOBEC CRANE PRESSURES WHEN WORK IS COMPLETED. | 0          | 48,800.00 |

|              |                  |
|--------------|------------------|
| Subtotal     |                  |
| Sales Tax    |                  |
| <b>TOTAL</b> | <b>53,423.80</b> |

INVOICE W 47712  
 Date //  
 Date Open 08/31/2021

Page: 4 of 5

Sold To : 232-9800 785

Ship To :

|            |  |            |  |
|------------|--|------------|--|
| [Redacted] |  | [Redacted] |  |
|------------|--|------------|--|

|                      |               |                  |                      |             |                           |                 |        |
|----------------------|---------------|------------------|----------------------|-------------|---------------------------|-----------------|--------|
| Written By<br>NCHRIS | Terms<br>CASH | Time<br>09:22:16 | Customer Po #        | Promised    | Phone                     | Ship Via        |        |
| Unit #<br>28         | Plate #       | Year<br>2010     | Make<br>FREIGHTLINER | Model<br>M2 | Mileage/Hrs<br>139916/0.0 | VIN<br>ADAM6746 | Engine |

| Qty   | Loc   | Description                            | Price      | Amount |
|-------|-------|--|------------|--------|
| 1.000 | VID1D | CUM4934278 SEALING WASHER              | [Redacted] | 3.41   |
| 6.000 | DELO  | CHV39831 10/30 GAL JUG DELO            | [Redacted] | 178.26 |
| 1.000 | SEC27 | FLEFS19624 FUEL/WATER SEPARATOR        | [Redacted] | 18.36  |
| 1.000 | SEC30 | FLEFF5636 FUEL FILTER                  | [Redacted] | 23.82  |
| 1.000 | RK17D | FLEWF2071 WATER, SPIN-ON               | [Redacted] | 9.11   |
| 1.000 | VID1D | CUM2866636 GASKET, AFM DEVICE          | [Redacted] | 14.62  |
| 1.000 | SEC16 | FLEAF26154 AIR FILTER CA4700           | [Redacted] | 80.20  |
| 7.000 |       | FRETLB13371-45 ISOLATOR                | [Redacted] | 97.44  |
| 2.000 |       | FRE01-15047-002 ENGINE MOUNTING SLEEVE | [Redacted] | 33.76  |
| 2.000 |       | FRE23-12955-100 CAP HEX SCREW          | [Redacted] | 29.74  |
| 2.000 |       | FRE23-12965-00 NUT                     | [Redacted] | 11.54  |
| 1.000 | SEC9B | SPI6.5-70-18X STRAP KIT                | [Redacted] | 14.39  |
| 1.000 | SEC11 | CUM5332563 OIL PAN GASKET              | [Redacted] | 56.62  |
| 3.000 | BULLP | MMM08880 BRAKE CLEAN                   | [Redacted] | 20.19  |
| 4.000 | VID1D | CUM3103015 GROMMET                     | [Redacted] | 15.68  |
| 1.000 | VID1D | CUM5398279 CONNECTION GASKET           | [Redacted] | 11.34  |
| 2.000 | PEG1R | NFC40096 HOSE CLAMP                    | [Redacted] | 7.60   |

Disclaimers of Warranties: Any Warranties on the products sold hereby are those made by the Manufacturer, if any. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty or merchantability or fitness for a particular purpose, and Plus Corporation neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. We hereby certify that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the fair labor standards act of 1938. As amended and or regulations and orders of the administrator or wage and hour division issued under section 14 thereof. PAYMENT FOR TECHNICAL SUPPORT AND INVOICES ARE DUE UPON RECEIPT OF INVOICE. ALL CURRENT BALANCE(S) DUE ON RECEIPT.

Parts.....  
 Labor.....  
 Env/Shop Sup  
 Freight.....

Thank you for your business and we look forward to serving you again.

Sub Total 38447.67  
 Sales Tax.... 2941.25

TOTAL DUE Continued o

INVOICE W 47712  
 Date //  
 Date Open 08/31/2021

Page: 1 of 5

Sold To : 232-9800 785

Ship To :

|  |  |
|--|--|
|  |  |
|--|--|

|                      |               |                  |                      |             |                           |                 |        |
|----------------------|---------------|------------------|----------------------|-------------|---------------------------|-----------------|--------|
| Written By<br>NCHRIS | Terms<br>CASH | Time<br>09:22:16 | Customer Po #        | Promised    | Phone                     | Ship Via        |        |
| Unit #<br>28         | Plate #       | Year<br>2010     | Make<br>FREIGHTLINER | Model<br>M2 | Mileage/Hrs<br>139916/0.0 | VIN<br>ADAM6746 | Engine |

| Qty   | Loc | Description  | Price | Amount  |
|-------|-----|--|-------|---------|
|       |     | Complaint : RADIATOR IS LEAKING.   |       | 1176.01 |
|       |     | Correction : INSTALLED DRIVE LINE AND MOVED TRUCK TO THE SHOP. DRAINED REMAINING COOLANT. EVACUATED A/C. REMOVED CONDENSER, CHARGE AIR COOLER (CAC) PIPES, AND THEN CAC. REMOVED RADIATOR BRACES, COOLANT HOSES, AND RADIATOR. REMOVED CAGE FROM RADIATOR AND TRANSFERRED TO NEW RADIATOR. INSTALLED NEW RADIATOR AND CONNECTED NEW RADIATOR STICK HOSE. INSTALLED COOLANT LINES AND FAN SHROUD THEN CAC AND CAC PIPES. FILLED COOLING SYSTEM BACK UP. RE-INSTALLED OLD LEAKING CONDENSER DUE TO NOT GETTING NEW ONE IN FROM FREIGHTLINER. GOT NEW CONDENSER IN, EVACUATED AC SYSTEM AND INSTALLED CONDENSER. CHARGED TO 2.8 LBS. VACUUMED AC SYSTEM AND THEN CHARGED. STARTED TRUCK AND CHECKED FOR LEAKS. ROAD TESTED TRUCK AND GOT UP TO OPERATING TEMPERATURE. MONITORED COOLANT TEMP, GOT UP TO 215° F THEN BACK DOWN TO 200° F. WHEN PULLING HILLS. TRUCK HAS COOLING PROBLEM. |       |         |
|       |     | ****NOTE*****  |       |         |
|       |     | ** REPLACED BAD RIGHT FRONT TURN SIGNAL SOCKET **  |       |         |
| 1.000 |     | ORR43-7272PTH<br>RADIATOR<br>OE# 43-7272PTH  | \$    | 966.41  |

Warranties: Any Warranties on the products sold hereby are those made by the Manufacturer, if any. The seller hereby expressly disclaims warranties either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and Plus Corporation assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. We hereby certify that these were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the fair labor standards act of 1938. As amended and or orders of the administrator or wage and hour division issued under section 14 thereof. PAYMENT FOR TECHNICAL SUPPORT AND INVOICES ARE DUE RECEIPT OF INVOICE. ALL CURRENT BALANCE(S) DUE ON RECEIPT.

Parts.....  
 Labor.....

Env/Shop Sup  
 Freight.....

Sub Total 38447.67  
 Sales Tax... 2941.25

TOTAL DUE Continued o

you for your business and we look forward to serving you again.