

# Invoice

Date: 04/06/2026  
Invoice No.: 10142  
Salesperson: 1  
Customer PO No: 31



Qty	Item	Description		
1		WABCO HCU ABS valve		
1		Brake master cylinder position sensor		
1		ECM repair		
8		Replaced HCU ABS for failed accumulators, replaced brake position sensor for brake fluid leak, sent ECM for repair for injector circuit codes		



Total \$6,321.89  
Balance Due \$6,321.89

Bus 31

Please contact us for more information about payment options.

Thank you for your business.