

Invoice

Date	Invoice #
4/7/2024	521

Project	Terms	Due Date
JCB300	Net 30	5/7/2024

Item	Quan...	Description	Rate	Amount
Labor	39	Wash off and inspect JCB300 skidloader. Found skid had an engine knock. Priced estimates to rebuild or replace engine with new JCB engine. Decided best route was to order new engine, which included new fuel and exhaust systems. Drained fluids, removed all engine accessories, removed engine. Uncrate and install new engine, installed all accessories. Filled with new fluids, bled fuel system, installed new air filters. Started up and checked oil pressure and engine temp. Everything was perfect. Removed and rebuilt main boom lift cylinder with new seal kit, reinstalled cylinder. Checked rest of skid functions, all seemed to work. Washed off and called customer for pick up.		
Parts		Seal kit, misc shop		
hyd oil	10	5 Ultraction		
engine oil...	5	15w40 bulk		
antifreeze	4	Antifreeze		
			Total Balance	

INVOICE

Bill to

Ship to

Shipping info

Ship via: pre pay and add
Ship date: 02/29/2024

Invoice details

Invoice no.: 2252
Terms: Due on receipt
Invoice date: 02/09/2024
Due date: 02/09/2024

#	Date	Product or service	SKU	Qty	Rate	Amount
1.		JCB 320/40635 Replacement Engine		1		
		JCB 320/40635 – ENGINE 444 TA4-55kW 12V SI-LP to replace old engine sn: 320/40635 U3718913				

Ways to pay

Total \$17,913.00