

Invoice details

Invoice no.: 1140
Terms: Net 30
Invoice date: 06/12/2026
Due date: 07/12/2026

#	Product or service	Description	Qty	Rate	Amount
1.	Labor	Completed work on Ditch Witch. Started by blowing out all hydraulic lines going to hydraulic pumps. Installed new pump. Replaced all o-rings for hoses going to pump. Installed new coupler and pump mount for hydraulic pump. Filled machine with engine oil. Installed new oil filter. Filled machine with hydraulic oil. Primed hydraulic pumps. Started machine and checked for leaks. Note: there could be a leak from the right drive motor lines.			
2.	Parts	15 gallons of hydraulic oil, 5 quarts of engine oil, engine oil filter	1		
Total					\$3,324.95

RECEIPT

Job Number

DATE

8/5/2026

Purchase Order #

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Repair tandem Brevini hydrostat. Install new parts as needed, assemble and test, re-install customers implement pump.	1		-
PWG shaft bearings			-
PWG swash plate			-
PWG 21cc valve plate			-
PWG servo piston assembly			-
22x25x25 brass bushing			-
21cc patriot seal kit			-
PVG charge pump with SAE thru drive			-
			-
No warranty on customers implement pump, unit reported to be working and no repairs were performed.			-
			-
			-
			-

If you have any questions concerning this purchase, please contact:

TOTAL

\$5,328.95

Warranty & Claims: Items shipped are warranted to be free of defects in material and workmanship unless excluded for a period of 90 days. Seller's liability is limited to repair or replacement of defective item and in no case is Seller liable for consequential damages exceeding the invoice amount of item.