

FC4746	0112027	Location: District 1-Topeka - Radio	LOCUS DIAGNOSTIC X 2-WAY RADIO ANALYZER, MDL. DX1000C SN: 2018, Unit Dead does not power up
FC4746	1113018	Location: District 1-Topeka - Radio	TEKTRONIX OSCILLOSCOPE MDL. THS720P SN: B055068
FC4746	1113024	Location: District 1-Topeka - Radio	AEROFLEX RADIO TEST SET MDL. 2975 SN: 598003397
FC4746	1836	Location: District 1-Topeka - Radio	VARIOUS ATTENUATOR, SWITCH AND ROUTER PARTS (1 lot of 8 items) Merrimac Coaxial Attenuator, Mdl. U-46A/21646, SN: 1264, QTY 1; Agilent Amplifier, Mdl. 8447D, SN: 2944A10721, QTY 1; Huntron Switcher Mdl. HSR410, SN: 31011610, QTY 1; Adtran TDU 120e AC, SN: C20A0607, CA20A0659, QTY 2; Telect RJ48 and RJ48C IXC Termination Pannels, QTY 1; Cisco Mdl. 1760access Routers, Chassis Only, QTY 2
FC4746	3113017	Location: District 1-Topeka - Radio	CADEX BATTERY ANALYZER, MDL. C7000-1 SN: VGAD031111
FC4746	5111052	Location: District 1-Topeka - Radio	ICOM COMMUNICATION RECEIVER MDL. IC-R7000 SN: 03786
FC4746	5111073	Location: District 1-Topeka - Radio	HELPER MATCHBOX EFFICIENCY METER MDL. MB-800A SN: 00234
FC4746	5113036	Location: District 1-Topeka - Radio	CADEX BATTERY ANALYZER, MDL. C7000 SN: VGAF05658
FC4746	5114016	Location: District 1-Topeka - Radio	TERMALINE WATTMETER, 300 WATT, MDL. 8173 SN: 4175, Defective
FC4746	6113012	Location: District 1-Topeka - Radio	MOTOROLA COMMUNICATIONS SYSTEM ANALYZER MDL. R2670A SN: 496LAL0041
FC4746	6113013	Location: District 1-Topeka - Radio	TEKTRONIX OSCILLOSCOPE MDL. THS730A SN: B034332
FC4746	6113014	Location: District 1-Topeka - Radio	TEKTRONIX OSCILLOSCOPE MDL. THS730A SN: B034334
FC4746	6113015	Location: District 1-Topeka - Radio	MOTOROLA COMMUNICATIONS SYSTEM ANALYZER MDL. R2670B SN: 496LBL0010