

Invoice

Date	Invoice #
2/25/2021	5997

PAID
03/01/2021

P.O. Number	Terms	Make/Model	Mileage In/Out	VIN #
		Amarillo	152238	

Quantity	Item Code	Description	Price Each	Amount
1	Diesel 15 Quart ...	Replaced all 8 injectors. Replaced stand pipes and dummy plugs. Installed upper air boot. Changed oil and filter.		
8	Fuel Injector			
2	Stand Pipe			
2	Plug			
1	Valve Cover Gas...			
1	Intake Air Boot			
	Labor			
	Shop Supplies			

Thank you for your business!

Subtotal
Sales Tax (7.0%)
Total

\$3,217.12

Payments/Credits

Balance Due

Invoice

Date	Invoice #
2/14/2014	362

PAID
02/17/2014

P.O. Number	Terms	Make/Model	Mileage In/Out	VIN #
		2006 F350	130140	

Quantity	Item Code	Description	Price Each	Amount
		Lifted cab from frame and removed cylinder heads. Heads and exhaust manifolds cleaned and surfaced by Arnold's machine shop. Three valves were ground. Installed ARP head studs. Replaced water pump, 3 idler pulleys, tensioner assembly and serpentine belt. Installed new oil cooler and replaced gaskets in oil filter stand. Installed new glow plugs and replaced both glow plug harnesses. Installed Banks EGR delete. Installed Magnaflow 4" exhaust. Removed IPR valve and replaced o-rings and filter screen. Repaired cam sensor harness. Changed oil and filter and filled Northland 15W40. Filled radiator with Ford GLS antifreeze. Installed Bully Dog programmer. Replaced both batteries.		

Thank you for your business!

Subtotal

Sales Tax (7.0%)

Total

Payments/Credits

\$4,679.72

Balance Due

Invoice

Date	Invoice #
2/14/2014	362

PAID
02/17/2014

P.O. Number	Terms	Make/Model	Mileage In/Out	VIN #
-------------	-------	------------	----------------	-------

		2006 F350	130140	
--	--	-----------	--------	--

Quantity	Item Code	Description	Price Each	Amount
----------	-----------	-------------	------------	--------

		Lifted cab from frame and removed cylinder heads. Heads and exhaust manifolds cleaned and surfaced by [REDACTED]. Three valves were ground. Installed ARP head studs. Replaced water pump, 3 idler pulleys, tensioner assembly and serpentine belt. Installed new oil cooler and replaced gaskets in oil filter stand. Installed new glow plugs and replaced both glow plug harnesses. Installed Banks EGR delete. Installed Magnaflow 4" exhaust. Removed IPR valve and replaced o-rings and filter screen. Repaired cam sensor harness. Changed oil and filter and filled Northland 15W40. Filled radiator with Ford GL5 antifreeze. Installed Bully Dog programmer. Replaced both batteries.		
--	--	---	--	--

Thank you for your business!

Subtotal
Sales Tax (7.0%)
Total

\$4,679.72

Payments/Credits

Balance Due