



205 South Main Street
Phone: (608) 592-3276
(800) 261-1600
Lodi, Wisconsin 53555
www.bushnellford.com

RO 16838	VIN 0 0 8 4 0 7	E80 PLUS		DATE IN 02/13/13
YEAR	MAKE TRAILER	MODEL L1009	COLOR O	TIME IN 13:24
MILES IN 2	MILES OUT 120	FIRST USE 1/1	LIC. WI	CLOSED 12:17 02/18/13
SEE ALSO			H: (608) 846-1880 W: (608) -	WRITER 3662 KAREN

(1) DOT INSPECTION
COMPLETED DOT INSPECTION.

Labor	T43	90.00
CARQUEST # 16838		83.49
Total Labor		90.00
Total Sublet		83.49
Total Repair (Customer)		173.49

(43-2443 PETER-) A

(2) REPAIR TRAILER BRAKES.
INSPECTED BRAKE LININGS AND WERE FALLING OFF. ADJUSTERS FROZEN AND ACCUATOR LEVERS WERE STUCK. REMOVED AND REPLACED ALL SIX COMPLETE BACKING PLATES. REMACHINED DRUMS. REPACKED WH EEL BEARINGS AND REPLACED CAPS WITH CORRECT O NES. CHECKED AND REPAIRED BRAKE AWAY SYSTEM AND LIGHT WIRING. ROAD TEST OK.

Labor	T04	800.00
23-105	(BACKING PLATE)	3 165.00
23-106	(BACKING PLATE)	3 165.00
10-10	(SEAL)	6 19.80
21-431	(CAP)	6 13.20
85-1	(PLUG)	6 6.60
Total Labor		800.00
Total Parts		369.60
Total Repair (Customer)		1169.60

(04-0011 KEN-) A

0% HANDLING ON ALL RETURNS, NO RETURN AFTER 10 DAYS. NO RETURNS ON ELECTRICAL PARTS OR SPECIAL ORDERED ITEMS. NO REFUND WITHOUT THIS INVOICE.		THANK YOU	W/C	INT.	CUSTOMER
DISCLAIMER OF WARRANTIES Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of products. Any limitation contained herein does not apply where prohibited by law.					
Page 1 of 1	Job 16838				Labor 890.00 Parts 369.60 Sublet 83.49 Waste Dispos .00 Oil/Grease .00 Sub Total 1343.09 Tax 73.87 Total (Cash) 1416.96
16838		Customer Copy			