## Invoice

Date	Invoice #	
4/1/2005	5713	

			Unit	Цо	urs/Miles
			1570 Case	21	34 hours
Quantity	item#	Des	cription	Price Each	' Amount
1	flywheel	to have flywheel surfaced	/ #27848		
1	A44012	hydraulic filter kit			
1	1981248C1	gasket			
6	502	#10 lock			
2	1981314C1	plate			
2	A155859	plate			
1	A64370	spring			
1	A76480	ring			
1	A66610	sleeve			- Indiana
1	A76482	bushing			
1	A58778	gear			
2	A58608	gasket			
1	A62885	seal			
3	A177478	coupling			
4	52054	dust cover			
1	A42668	gasket			
1	A42667	gasket			and the same of th
2	131-620	retainer			
6	A63896	screw			
6	A63897	nut			
1	1341339C2	gauge			-
3	A66788	ubolt			
1	A66733	unit			

Each invoice is due upon receipt. Thank-you





Date	Invoice #
4/1/2005	5713



	Unit		Цои	rs/Miles
	1570 Case		213	34 hours
Description		Pric	ce Each	· Amount
sket sitive str crimp				

Quantity	Item #	Description	Price Each	' Amount
1	A63793	gasket		
1	4010005P	positive str crimp		
2	4010005N	negative str crimp		
2	5614010R	tubing		
2	5613010B	tubing		
1	4110005P	positive r crimp		
6	A155865	retainer		
5	326-840	bolt		
1	A43194	seal kit		
1	45511	1/2x2-1/2 bolt		
1	001	gal. antifreeze		
1	water	gallon of distilled water		
20	009	medium wire ties		
4	5/16 f	#8 5/16 flat washer		
2	5/16 n	#8 5/16 nut		
4	5/161	#8 5/16 lock washer		
0.75	silicone	silicone		
0.75	ZPX51850	sealant		2 -
1	7/161	#8 7/16 lock washer		
1	misc. parts	cotter pin		
24	002	can either, to clean with		
1	electrical c	wire end connector		
12	5/8 1	#8 5/8 lock washer		

Balance Die

Each invoice is due upon receipt. Thank-you



## Invoice

Date	Invoice #
4/1/2005	5713

	Linit 1570 Case		Llours/		/Miles	
			1570 Case	2		2134 hours
Quantity	Item#	De.	scription	Price	Each	· Amount
1 1 2	3/4 1 010 1895	#8 3/4 lock washer brown buff pads bulb Total Parts	replaced the water temp.		en e	
31	Labor for the following: replaced the water temp. sender, the transmission sender & gauge, installed new hydraulic filters, drained & refilled the hydraulic oil with oil furnished by the customer, replaced the drain plug washers, replaced the nuts & screws on the dash panel, installed new dash light bulbs-fixed the dash lights so they would work, installed a new rear main seal, ring gear, torque limit clutch, all the hardware, PTO drive gear & bushings, & the split gasket, installed 3 hydraulic couplers & dust plugs, resealed the rear hood to cab, checked the air conditioner, crimpped new ends on the battery cables					
	Freight	Incoming Freight Charg	ge		<u> </u>	



## Invoice

Date	Invoice #
2/9/2006	9066

ν

Unit Hours/Miles
1570 Case 2360 hours

Qty.	Item	Description	Price Each	Amount
1	A59887	hose		
1	A145619	hose		
1	A44068	filter kit		
4	5744	hose clamp		
2	A64069	mounting pipe		
1	A141225	сар		
1	1342784C1	thermostat gasket		
2	A57641	thermostat		
1	AM4096404	turbo		
1	A156842	hose		
2	222-154	grommet		
]	A150449	hose		
1	A58892	gasket		
2	A43710	seal kit		
4	188954	snapring		
2	A65936	collar		
2	167111	snapring		
2	32052	clamp		
1	radiator	to have radiator re-cored, #48662		
3		R-134A fre-on, 12 oz.		
10	002	either, to clean with		
1	flowex	exhaust sealer		
4	001	antifreeze		
3	water	distilled water, gallon Total Parts		
24	Labor	Labor per hour		
	Freight	Incoming Freight Charge		
64	mileage	mileage/Ellinwood		