

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2005 Make Mack Model CH613 Serial # 1M1AA18YD5N157619

Tire Size 11R22.5 Ply Rating 15 Company Number 227

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
10	7	13				4959	Replaced both mud flaps + brackets + wipers
10	10	13				4896	Replaced EGR Cooler + Valve + fuel pump
10	29	13	212968	✓	✓	13245	Service
10	30	13	212968			4908	Replaced Turbo
3	1	14					Annual Vehicle Inspection
3	7	14	215085			4996	Replaced air switch, gauge + dryer cartridge, EGR tube + mirror
4	24	14	221112			4996	Replaced heater hose
5	1	14	221717			5083	Replaced muffler
4	28	14	221703	✓	✓	13847	Service
5	27	14				5090	Replaced air sensor
6	2	14				5024	Replaced hood cable
6	13	14				5039	Replaced 4-way flasher
6	4	14	226002			Foley	Charge A/C
7	16	14				5050	Tightened shifter knob, replaced left headlight
7	14	14	230190			5151	Replaced compressor
7	25	14	231605	✓	✓	13885	Service
8	9	14	234204			5160	Replaced air dryer
9	16	14	238067			5252	Replaced air dryer filter
9	30	14				5317	Replaced top radiator hose
10	4	14	242502	✓	✓	5319	Service, replaced engine harness, u-joint + radiator cap

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2005 Make Mack Model CH613 Serial # 1M1AA18Y05N157619
 Tire Size 11R22.5 Ply Rating 15 Company Number 227

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
8	22	12	174439	✓	✓	12440	Service
8	22	12					Annual Vehicle Inspection
8	22	12	174539			4312	Replaced taillight + back up light bulb
9	6	12				4447	Replaced air sensor
9	15	12				4495	Replaced right side turn signal
9	20	12				4503	Repositioned + tightened right side quarter fender bracket
9	20	12				4504	Revised electrical cord to trailer for tail gate + drop axle, replaced fuses
10	23	12	180245			Hoyts	Replaced motor mounts + repaired coolant leaks
11	8	12				4350	Replaced radiator cap
12	14	12	184969	✓	✓	13046	Service, replaced radiator
12	14	12				4635	Replaced right front headlight assy
1	21	13	185347			4589	Replaced s-cam bushing, brake springs, shoes + drums, wheel seals, left + right hand s-cam, hydr hose to pump, mud flaps + hangers
1	24	13					Annual Vehicle Inspection
3	28	13				4616	Replaced batteries
4	2	13				4661	Replaced CB antenna mount
5	6	13				4685	Replaced 4 way flasher
5	13	13				4649	Tightened hose clamps for coolant leaks
5	30	13	197906	✓	✓	13132	Service
6	15	13				4789	Replaced torque rods
7	1	13				4775	Replaced transmission temp sensor
7	10	13	202671			Foley	Repaired A/C
7	17	13				4804	Replaced glow stat + dome light bulb
7	29	13				4785	Replaced input shaft b7, oil pan gasket, oil filter + oil
8	9	13	20624			4860	Replaced batteries
8	24	13	207901			4866	Replaced air valve + 2 tires
8	26	13	207945			Hoyts	Alignment
9	7	13	209326			4884	Replaced fuel pump + taillight
9	13	13				4874	Replaced power steering hose + repaired hood spring
9	20	13				4779	Replaced upper overflow reservoir

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2005 Make Mack Model CH613 Serial # 1M1AA18Y05N157619
 Tire Size 11R22.5 Ply Rating 15 Company Number 227

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
7	27	10	143991	✓	✓	10697	Service
9	3	10				3496	Replaced electrical receptacle
9	29	10				3480	Replaced back-up alarm + air dryer filter
10	6	10				3533	Replaced left rear wheel seal and air line from compressor to dryer
10	22	10	123463	✓	✓	10795	Service
10	28	10				3604	Repaired EGR pipe clamp
10	30	10				3609	Tightened upper + lower radiator hose clamps, thermostat housing + oil cooler hose clamps
3	22	11				3751	Replaced drive fan
11	19	10	126324			3669	Replaced idler + tensioner
5	11	11	187436			Foley	Replaced A/C accumulator
6	10	11	133680	✓	✓	11491	Service
6	24	11				3935	Replaced plug socket, wiring + circuit breaker
7	7	11					Annual Vehicle Inspection
7	18	11				3971	Replaced air bag
8	13	11	141970	✓	✓	11570	Service
8	4	11	140940			3491	Replaced injectors + gasket
9	15	11				4018	Coolant Leak - Repositioned hose + tightened clamps
10	13	11				4038	Replaced fuel sensor
11	30	11				4148	Replaced tensioner, bushing + dipstick
12	6	11	152961	✓	✓	11714	Service
12	20	11				4158	Replaced torque rods
1	26	12				4199	Replaced #6 injector + air line
1	27	12				4167	Adjusted clutch
12	14	11	153104			4178	Replaced exhaust + turbo
3	24	12	153386			4224	Replaced glad hand rubber + air fitting
4	6	12				4255	Replaced switches for trailer air ride + drop axle
4	26	12				4285	Replaced air compressor
5	14	12	162324	✓	✓	12339	Service
5	15	12	162331			Foley	Replaced A/C compressor
5	17	12				4304	Replaced u-joints, fan drive + belts
6	20	12				4390	Replaced blower motor
7	19	12				4430	Replaced fuel sender

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2005 Make Mack Model CH613 Serial # 1M1AA18Y05N157619

Tire Size 11R22.5 Ply Rating 15 Company Number 227

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
7	24	08					Annual Vehicle Inspection
7	24	08				2394	Replaced wheel seal
8	15	08	65019			2444	Replaced Radiator
9	2	08				2469	Tightened air compressor mounting bolts to top oil line
9	4	08				2472	Adjusted clutch free travel
9	13	08	68800	✓	✓	9015	Service
10	29	08				2524	Replaced air compressor
11	11	08	77599	✓	✓	9090	Service
11	11	08				2526	Replaced tractor protection valve
1	28	09				2544	Replaced emergency air line
3	11	09	81696	✓	✓	9689	Service
4	1	09				2693	Replaced belt tensioner + 11- Joints at transmission
5	22	09				2750	Replaced 2 hub caps
5	28	09	89044	✓	✓	9746	Service
7	14	09	92089			MCAT	Repair A/C
8	8	09	95647	✓	✓	9831	Service
8	11	09					Annual Vehicle Inspection
8	18	09	95990			2888	Repaired ground on alternator
8	19	09				2919	Replaced all batteries
10	3	09	101953	✓	✓	9914	Service
10	9	09				Auto Glass	Replaced windshield
11	17	09	105893	✓	✓	9955	Service
12	4	09				3112	Re-positioned 3-4 clamps + lightened (water leak)
11	2	09	105893			3108	Replaced EGR Valve, oil cooler, air valve, torque rod + hand pumps
4	21	10				3209	Replaced air governor, had radiator repaired
4	9	10	106340			3199	Replaced fuel pump + motor
5	4	10	106867			3301	Replaced air dryer (used off of 219)
5	27	10				3323	Replaced air dryer (new) + filter
5	25	10				Edits	Replaced pressure sensor
6	2	10				3314	Replaced heater + A/C control assy
6	14	10				3338	Replaced inside drivers door map pocket
6	29	10				3382	Replaced radiator
7	15	10					Annual Vehicle Inspection
7	26	10				3475	Replaced mud flap

SHILLING CONSTRUCTION - REPAIR ORDER HISTORY

Equip. # 227

Date	Mileage	Work Repair Order #	Work Performed on Equipment
8-3-06	181581	1645	Changed oil + filter
8-8-06	Custom	Truck	Diagnosis + Repair
9-14-06	Custom	Truck	Replaced coolant level + temp sensor.
9-23-06	—	2283	Installed Backup alarm
10-2-06	189256	1647	Service
10-19-06		1748	Replaced Steering Gear Box
10-30-06	191000	2303	Replaced Tensioner, Idler Arm Pulley + 2 Belts
12-8-06	195240	7865	Service
12-20-06	—	1825	Replaced fan clutch
2-1-07	Hay's Mack		Repair (see service)
5-11-07		2354	Repaired Hub cap with a repair kit
5-10-07	Auto Glass		Replaced windshield
6-1-07	2132	MCAT	Charge A/C
6-7-07	309,305	8008	Service
5-31-07	Hay's Mack		Repair valve covers, rocker arm, injectors, unit pumps
7-21-07			Annual Vehicle Inspection
7-23-07		2062	Replaced rear brake shoes, drums + spring kit, steering brake drums + shoes
7-28-07		2064	Replaced oil cooler hose, cleaned ABS sensor's
8-22-07		2112	Replaced Coolant Hoses
8-31-07	22256	8150	Service
10-6-07	30505	8182	Service
11-26-07	35,718	2207	Replaced Intake + water manifold gaskets, thermostat kit, shut off valve, thermostat spacer, O-ring air trans tube, Bypass hose, fan belt, alt + A/C Belts
12-3-07		2211	Replaced fitting on water manifold
12-24-07	36698	8535	Service
3-11-08	38040	2301	Replaced idler acc, tensioner + filter
4-18-08	43342	8838	Service
6-7-08	51708	8901	Service
7-23-08	62340	8953	Service
7-24-08			Annual Vehicle Inspection
7-24-08		2394	Replaced wheel hose
8-15-08	65019	2444	Replaced Radiator
9-2-08		2469	Tightened Air Compressor Mounting Bolts to stop oil leak
9-9-08		2472	Adjusted clutch + free travel