

Shilling Construction — Repair Order History

Equip.# 224

K 7320

150421++

Date	Mileage	Work Repair Order #	Work Performed on Equipment
9-13-04	6,870		Service
10-4-04	9,470		
11-12-04	14,370		Service
1-11-05	21,398		
2-28-05	23,200		Service
6/7/05	31,400		Service
7/30/05 7/30/05	36,375	1529	Service + Inspection
9-14-05	44,181	1586	Service
9-16-05	44,262	1593	Service finished waiting on some filters ^{change belts}
9-16-05	44,262	1592	Hds Drive (new)
9-22-05	45,353	2088	replaced fuel tank belting
9-24-05	45,455.2	2092	Fan Belt
11-6-05	53,944	2160	Service
11-12-05	55,435	2216	Reglued passenger back window
12-7-05	59,508	6935	Service
12-8-05		2237	Drained trans. & both diff., put new oil in, cleaned diff breathers & replaced 1 breather, oiled gaskets
12-14-05		2223	PTO Pump lines hooked up backwards - corrected
2-13-06		2250	Replaced Hyds. Hoses & fittings
2-21-06		1777	Removed & straightened step & Bracket, Repaired dump control box
3-15-06		1782	Replaced left rear tail lamp
4-1-06	67,210.8	7108	Service
4-25-06	Burnetts		Tire repair
5-30-06	77,367	7149	Service
7-29-06	86,189	7252	Service, Replaced PTO Pump seal

SHILLING CONSTRUCTION - REPAIR ORDER HISTORY

Equip. # 224

Date	Mileage	Work Repair Order #	Work Performed on Equipment
7-29-06			Annual Vehicle Inspection &
9-16-06	94259	7319	Service, New Hangers + Mud Flaps
9-13-06	Zeis Truck		Align front end
11-24-06		1751	Replaced thermostat (2) and Sensor
11-24-06	-	1815	Replaced PTO air shifter, fitting on exhaust
12-1-06	100083	7860	Service, Replaced rt side turn signal bulb
5-16-07		2358	Replaced wheel seal, brake shoes, brake spring kit, brake drums + piggy back kit
5-3-07	Hay's Mack		Pipin exhaust manifold, update cooling system
6-27-07			Annual Vehicle Inspection
7-10-07	106,691	8048	Service
7-21-07		2061	Replaced oil cooler + hose, thermostat housing hose, drive fan, anti-freeze, A/C Belt, fan belt + filters
9-29-07		8173	Service
9-29-07		2185	Re-positioned driver side fuel tank
11-7-07	122119	8218	Service
1-11-08		2223	Installed Kit Mack Mode Box, Base Control + (dis. Filter Indicator (Worn out Heater Controls))
3-18-08		2289	Replaced Hand Primer
4-16-08	123750	MCAT	Repaired A/C
4-18-08	127230	8840	Service + Changed Belts
4-18-08		2379	Repaired Stabilizer Bracket
6-21-08			Annual Vehicle Inspection
7-3-08	138944	8936	Service
7-15-08	Auto Glass		Replaced Windshield
8-28-08	145928	9000	Service
9-3-08		2461	Replaced air compressor, front traction bar, alternator + rear coolant line
11-20-08	152682	9089	Service
12-2-08	158538	2533	Replaced air compressor, belts + gasket
3-9-09	158993	2651	Service
3-16-09		2659	Replaced mudflaps + hangers
4-1-09		2692	Tightened clamps on coolant hoses

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2004 Make Mack Model CH613 Serial # 1M2AA18Y04N155959
 Tire Size 11R24.5 Ply Rating 15 Company Number 224

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
8	28	08	145928	✓	✓	9000	Service
9	3	08				2461	Replaced air compressor, front traction bar, alternator + rear coolant line
11	20	08	152682	✓	✓	9059	Service
12	2	08	158538			2533	Replaced air compressor belts + gasket
3	9	09	158993	✓	✓	2651	Service
3	16	09				2659	Replaced mudflaps + hangers
4	1	09				2692	Tightened clamps on coolant hoses
5	11	09	166179	✓	✓	9729	Service
5	13	09				2724	Replaced mud flap hangers
5	13	09	Auto Glass				Replaced passenger side window (Storm damage at Benton)
6	20	09					Annual Vehicle Inspection
6	24	09	167085			MCAT	Repair A/C
7	3	09	172854	✓	✓	9800	Service
7	10	09				2817	Replaced air compressor, pilot bearing, heavy duty clutch, clutch brake, rear main seal, whip hose throw out bearing + light
7	22	09				2900	Checked engine oil leak
7	28	09				2910	Tightened nuts for mounting brackets for rear fenders
8	19	09				2918	Added shim to clutch brake
8	27	09				2985	Replaced light bulbs
9	4	09	179525			2991	Replaced flasher, pogo stick, compressor belts + gasket
9	4	09	179525	✓	✓	9880	Service
9	24	09				3034	Replaced mirror bracket cover
10	3	09	184278			3038	Replaced fuel pump
10	16	09				3056	Replaced idler, tensioner + belts
10	16	09	186110	✓	✓	9919	Service
2	23	10	190940	✓	✓	10506	Service
2	23	10	190940			3185	Replaced torque rod
5	6	10	193467			3303	Replaced seat, arm rests + steps
5	17	10				3240	Replaced air coupler + nipple
6	1	10	195618			3356	Installed 5 th wheel kit

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2004 Make MAK Model CH613 Serial # 1M2AA18Y04N155959
 Tire Size 11R24.5 Ply Rating 15 Company Number 224

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
6	2	10					Annual Vehicle Inspection
6	18	10				3345	Adjusted clutch brake + free travel
6	22	10				3350	Turned fuel tanks
7	27	10				3426	Cleaned radiator cores, remounted, replaced A/C cooler
8	17	10				3492	Replaced temp. sensor + back up alarm
8	24	10	204349	✓	✓	10724	Service
9	11	10				3502	Replaced Brake Shoes, drums, S-cams, bushings wheel seals + u-joints
9	21	10	205963			3506	Replaced turbo
9	24	10				3524	Repaired hydraulic leaks
9	24	10	206131			3542	Replaced stub, nut, exhaust gasket + turbo gasket
10	30	10				3608	Tightened hose clamps on oil cooler hose
11	17	10	214285	✓	✓	10902	Service
11	23	10				3650	Replaced right front turn signal bulb
9	24	10	205711			Hoyts	Repaired transmission
3	15	11				3727	Replaced batteries
4	5	11	216801			3711	Replaced front motor, mounts, rear side motor mounts + belts
4	11	11				3732	Replaced window washer pump + cab air bag
3	24	11				3718	Replaced drive fan, EGR Valve + engine fan
4	25	11				3746	Replaced RPM sensor, EGR valve + air sensor
4	26	11				3748	Replaced engine speed sensor
5	2	11	217646			Hoyts	Installed mass air flow sensor + controller
7	6	11					Annual Vehicle Inspection
7	14	11	225802	✓	✓	11524	Service
7	13	11	224680			Hoyts	Repaired transmission
7	26	11				3949	Replaced air compressor, surge tank, recovery tank + low level sensor
9	16	11	230687			Bruckner	Replaced steering axle shaft
11	9	11				4094	Replaced carrier bearing + torque rods
1	17	12	235902	✓	✓	12231	Service
1	23	12	235902			4182	Replaced dipstick, seal, air dryer cartridge purge air dryer + turbo belts
6	22	12	247222	✓	✓	12387	Service

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2004 Make Mack Model CH613 Serial # 1M2AA18Y04N155959
 Tire Size 11R24.5 Ply Rating 15 Company Number 224

Month	Day	Year	Mileage	Lube	Oil	Work Order #	Repair & Other Service
6	23	12	247222			4391	Replaced wiper arms + adjusted clutch free travel
6	23	12					Annual Vehicle Inspection
7	20	12				4422	Replaced AC + Heater control, repaired window crank handle on drivers door
7	23	12				4424	Replaced wiring harness on AC - Heater control panel
8	14	12	253015			4483	Replaced manifold gaskets
9	13	12	256734	✓	✓	12466	Service
10	22	12				4575	Replaced turn signal flasher
12	12	12	263027	✓	✓	13045	Service
1	15	13					Annual Vehicle Inspection
1	16	13				4541	Replaced serpentine belt, belt tensioner, rear end oil, transmission oil, power steering box seal kit + mudflaps
3	27	13				4615	Replaced light cord for trailer
4	2	13				4617	Replaced boost sensor
4	24	13				4678	Replaced ABS light cord
6	6	13	276579	✓	✓	13155	Service
6	8	13				4764	Repaired splitter valve, replaced wiper blades + fuel nozzle
6	20	13	278252			4741	Replaced door handle, drums, brakes, king pins, water pump, isolators, exhaust tube + dust cover
7	12	13				4816	Replaced fan + alt belt
8	28	13				4834	Replaced bulb in right brake light
9	19	13				4875	Checked + adjusted brakes
10	7	13				4961	Replaced turn signal + dimmer switch
10	10	13				4966	Replaced air side valve + fittings
10	14	13				4968	Replaced battery, EGR air valve, front diff pinion seal, right front turn signal bulb
10	18	13				4971	Replaced torque rods + wiper sprayer motor
2	26	14	291690	✓	✓	13251	Service
2	26	14					Annual Vehicle Inspection
3	21	14	295320			Roberts	Replaced mass air sensor
5	29	14	306571	✓	✓	13860	Service

INSPECTION AND MAINTENANCE RECORD - POWER UNIT

Year 2004 Make Mack Model CH613 Serial # 1M2AA18Y04N155959

Tire Size 11R24.5 Ply Rating 15 Company Number 224

[illegible]