

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
11/15/13	Canceled	45503		\$0.00		9487	9487

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
11/13/13	Invoice	45489		\$332.68	11/21/13	9487	9487

Labor Item	Category	Tech	Description
GEN	GEN	BM	GENERAL OUTSIDE REPAIR WORK.

TRUCK CAME INTO SHOP WITH A LEAKING RIGHT REAR BRAKE CHAMBER. R@R BRAKE CHAMBER W/ NEW AS NEEDED TO FINISH REPAIRS TO TRUCK.

Parts Mfg	Item	Description	Category	Qty	UOM	Condition
IMP	71386	WIRE ZIP TIE	GEN	1	EA	New
MGM	3430008	30/30 PIGGY/ BRAKE CHAMBER	BRK	1	EA	New
PET	90525A806	ENGINE FAN 31.75" 8 BLADE	GEN	1	EA	New
		CARRY OUT FOR 2003 PETE				

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
9/6/13	Invoice	44967		\$99.83	9/13/13	613753	613753

Labor Item	Category	Tech	Description
GEN	GEN	FM	GENERAL OUTSIDE REPAIR WORK.

TRUCK CAME INTO SHOP WITH A BLOWN AIR BAG ON LIFT AXLE. R@R AIR BAG W/NEW PROVIDED BY CUSTOMER TO CORRECT PROBLEM. REPAIRED PTO LIGHT WIRING THEN FOUND NO LIGHT IN CAB.

Parts Mfg	Item	Description	Category	Qty	UOM	Condition
IMP	71889	STEP DOWN SHRINK BUTT	GEN	1	EA	New

Sublet/Misc.

Item	Description	Category
MISC.	PTO SWITCH CONNECTOR	

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
8/29/13	Invoice	44921		\$1,215.51	9/6/13	613743	613753

Labor Item	Category	Tech	Description
RT	GEN	FM	ROAD TEST

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
8/29/13	Invoice	44921		\$1,215.51	9/6/13	613743	613753
Labor							
Item		Category	Tech	Description			
GEN		GEN	BM	GENERAL OUTSIDE REPAIR WORK. R@R SPEEDOMETER GUAGE WITH NEW AND CALIBERATED. TESTED AND REPLACED RADIATOR CAP WITH NEW. R@R LEAKING COOLANT LINES TO TRANSMISSION COOLER AS NEEDED TO INCLUDE NEW CLAMPS AND HARDWARE TO FINISH REPAIRS ON TRUCK. TEST DROVE.			
GEN		GEN	BM	GENERAL OUTSIDE REPAIR WORK. TRUCK CAME INTO SHOP WITH A STOP ENGINE LIGHT FLASHING. FOUND COOLANT LEVEL VERY LOW. ADDED COOLANT AS NEEDED TO CORRECT STOP ENGINE LIGHT ISSUE. CUSTOMER OPTED TO KEEP TRUCK AT SHOP TILL COOLANT LEAKS COULD BE FIXED AND TO R@R SPEEDOMETER.			
CLU1		DRT	BM	CLUTCH ADJ. ADJUSTED CLUTCH BRAKE AND FREE TRAVEL. LUBED LINKAGES AS NEEDED.			
Parts							
Mfg	Item	Description	Category	Qty	UOM	Condition	
PEN	300016	NAL-COOL 3000	GEN	2	EA		
WH	3325X8	1/2 HEX NIPPLE	GEN	1	EA		
KW	D22082443	BALL VALVE 90 DEG.	GEN	1	EA		
KW	D22082242	1/2 BALL VALVE YELLOW HANDLE	GEN	1	EA		
KW	D20064519	CLAMP	GEN	4	EA		
GDY	65023	5/8 HEATER HOSE (RED)	GEN	11	FT	New	
HTC	71379	14-1/2" ZT	GEN	17	EA	New	
INT	VEL10283	LARGE 10LB RAD CAP	GEN	1	EA	New	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
8/29/13	Invoice	44921		\$1,215.51	9/6/13	613743	613753

Parts		Description		Category	Qty	UOM	Condition
Mfg	Item						
KW	Q4310192	SPEEDO GAUGE		GEN	1	EA	New
ANT	ANTIFREEZE	COOLANT (GAL) SHELL		GEN	3	EA	

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
7/25/13	Canceled	44716		\$0.00		0	0

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
7/22/13	Invoice	44696		\$58.73	7/22/13	0	0

Parts						
<u>Mfg</u>	<u>Item</u>	<u>Description</u>	<u>Category</u>	<u>Qty</u>	<u>UOM</u>	<u>Condition</u>
FIL	BF7587	NEW CAT FUEL FILTER	SVC	1	EA	
FIL	BF1259	CUMMINS/CAT FUEL FILTER	SVC	1	EA	
CAT	1R0716	OIL FILTER (CAT)	ENG	1	EA	
		CARRY OUT				

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
6/6/13	Invoice	44486		\$1,212.54	6/14/13	605826	605836

Labor		Category		Tech	Description
Item					
RT		GEN		FM	ROAD TEST

THE TRUCK WAS ROAD TESTED BY THE DR. OR ONE OF HIS STAFF, AND THE WORK COMPLETED HAS MET HIS STANDARDS, WITH THE HIGHEST REGARDS FOR QUALITY, SAFETY, AND PERFORMANCE. REMEMBER, IF YOUR BIG TRUCK OR TRAILER IS SICK, BRING IT IN TO SEE THE TRUCK DR. AT FLOYD'S TRUCK REPAIR. THERE IS A DIFFERENCE! WE THANK YOU FOR YOUR BUSINESS. BE SAFE.

GEN GEN BM GENERAL OUTSIDE REPAIR WORK.

TRUCK CAME INTO SHOP TO FIX A/C, REPAIR LEAKING EXHAUST, CHECK RIGHT REAR BRAKES. TIRES ARE GETTING CHEWED UP. R@R DRIVERS SIDE MUFFLER INLET ELBOW AS NEEDED TO INCLUDE NEW MUFFLER AND PIPES. SHORTENED RIGHT HAND STACK AND FABRICATED RUBBER SUPPORT FROM CAB TO STACK. CHECKED A/C AND FOUND BROKEN WIRE AT COMPRESSOR CONNECTOR. INSTALLED CAB FILTER AS NEEDED. R@R HEATER CONTROL CABLE WITH NEW. CHECKED INTO REAR BRAKE AND TIRE WEAR ISSUE. INSPECTED BRAKES. FOUND BRAKE DRUM NOT CENTERING RIGHT. R@R BRAKE DRUM WITH NEW

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

AS NEEDED TO FINISH REPAIRS ON TRUCK. TEST  
DROVE.  
\*\*\*\*\*NOTE\*\*\*\*\* EXHAUST MANIFOLD HAS BROKEN  
STUDS AND TURBO WASTE GATE ARM IS BREAKING  
OFF.

Original (continued)		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
6/6/13	Invoice	44486		\$1,212.54	6/14/13	605826 605836
Labor Item		Category	Tech	Description		
A/C		A/C	BM	A/C SETUP CHARGE		

HOOK MACHINE UP TO TRUCK RETRIEVE, AND  
RECHARGE FREON AS NEEDED.

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
KW	FA1005	CONTROL CABLE	GEN	1	EA	
IMP	78611	1/4" FLAT WASHER	GEN	2	EA	New
GUN	3600AX	BALANCED DRUM	BRK	1	EA	New
KW	19501	KW CAB FILTER ADD ON KIT	GEN	1	EA	New
IMP	71755	20-18GA MALE TERM.	ELC	1	EA	New
HTC	71379	14-1/2" ZT	GEN	7	EA	New
IMP	42308	5/16-18 LOC. NUT	GEN	2	EA	New
IMP	78612	5/16" FLAT WASHER	GEN	4	EA	New
IMP	16127	5/16 X 1-1/2 BOLT	GEN	2	EA	New
IMP	78613	3/8" FLAT WASHER	GEN	6	EA	New
DON	P226147	5" STAINLESS STEEL FLEX PIPE	GEN	1	EA	New
TRU	9624	BAND CLAMP	EXH	4	EA	New
TRP	500ZP	5" CLAMP	EXH	4	EA	
FOR	3699	MUFFLER	EXH	1	EA	New
TRU	10317	ELBOW	EXH	1	EA	New
KW	EP50EL45207A	EXHAUST PIPE/ELBOW LEFT SIDE	GEN	1	EA	New

Original		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
2/25/13	Invoice	43927		\$1,142.19	3/6/13	600929 600929
Labor Item		Category	Tech	Description		
GEN		GEN	MQ	GENERAL OUTSIDE REPAIR WORK.		

TRUCK CAME INTO SHOP FOR A DOT INSPECTION,  
CHECK STEERING COMPONENTS, AND CHECK  
CLUTCH. R@R CLUTCH ROD END. ADJUSTED  
BRAKES AND CLUTCH. INSPECTED TRUCK. R@R  
STEERING SHAFT U-JOINTS. TIED UP HOSES ON  
REAR AXLE. R@R LEFT TOP BED LIGHT. R@R

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

RIGHT REAR DRIVE AXLE BRAKES. R@R DS AND PS  
WINDSHIELD

Original (continued)		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
2/25/13	Invoice	43927		\$1,142.19	3/6/13	600929 600929

Labor

Item	Category	Tech	Description
DOT1	GEN	MQ	TRUCK INSPECTION PERFORMED D.O.T. INSPECTION AS NEEDED UPON REQUEST.
CLU1	DRT	MQ	CLUTCH ADJ. ADJUSTED CLUTCH BRAKE AND FREE TRAVEL. LUBED LINKAGES AS NEEDED.

Parts	Mfg	Item	Description	Category	Qty	UOM	Condition
	KEL	FD49SN	DOT INSPECTION LABEL	GEN	1	EA	New
	KEL	FD400FSC2	DOT INSPECTION REPORT	GEN	1	EA	New
	TL	40202Y	LIGHT	ELC	1	EA	
	TL	40700	GROMMENT	GEN	1	EA	New
	ECU	E10244	BRAKE KIT (EATON EXTENDED)	BRK	1	EA	
	ABX	4709DES-11	EXTENDED EATON BRAKE SHOE (DRIVE)	BRK	2	EA	Replated
	KW	DL471730	KENWORTH WINDSHIELD	GEN	2	EA	New
	TL	10208R	RED LIGHT	GEN	1	EA	
	HTC	71379	14-1/2" ZT	GEN	2	EA	New
	IMP	71386	WIRE ZIP TIE	GEN	1	EA	New
	IMP	71287	7-1/2" ZT	GEN	1	EA	New
	SPI	5170X	U-JOINT	DRT	2	EA	New
	KW	SPF6S	LINKAGE END	GEN	1	EA	

Original		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
10/4/12	Invoice	43108		\$1.83	10/4/12	0 0

Parts	Mfg	Item	Description	Category	Qty	UOM	Condition
	FIL	BF1259	CUMMINS/CAT FUEL FILTER	SVC	1	EA	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
10/4/12	Invoice	43108		\$1.83	10/4/12	0	0

Parts		Description		Category	Qty	UOM	Condition
Mfg	Item						
FIL	BF7587	NEW CAT FUEL FILTER		SVC	-1	EA	

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
6/22/12	Invoice	42464		\$297.01	6/22/12	586632	586632

Labor		Description	
Item	Category	Tech	
GEN	GEN	MQ	GENERAL OUTSIDE REPAIR WORK.

TRUCK CAME INTO SHOP TO REPAIR RIGHT REAR ENGINE MOUNT MOUNTING. REMOVED ENGINE MOUNT. CLEANED MOUNTING HOLES AND INSTALLED STUDS. REPAIRED MOUNT FACE AND REINSTALLED TO FINISH REPAIRS ON TRUCK.

Parts		Description		Category	Qty	UOM	Condition
Mfg	Item						
PAI	71384	3/4-10 ROD		GEN	1.5	EA	
IMP	76177	3/4 LOCK WASHER		GEN	1	EA	New
IMP	40162	3/4-10 NUT		GEN	1	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
5/30/12	Invoice	42308		\$1,055.96	6/12/12	584619	584629

Labor		Description	
Item	Category	Tech	
RT	GEN	FM	ROAD TEST

THE TRUCK WAS ROAD TESTED BY THE DR. OR ONE OF HIS STAFF, AND THE WORK COMPLETED HAS MET HIS STANDARDS, WITH THE HIGHEST REGARDS FOR QUALITY, SAFETY, AND PERFORMANCE. REMEMBER, IF YOUR BIG TRUCK OR TRAILER IS SICK, BRING IT IN TO SEE THE TRUCK DR. AT FLOYD'S TRUCK REPAIR. THERE IS A DIFFERENCE! WE THANK YOU FOR YOUR BUSINESS. BE SAFE.

GEN	GEN	BM	GENERAL OUTSIDE REPAIR WORK.
-----	-----	----	------------------------------

TRUCK CAME INTO SHOP WITH A VIBRATION AND AIR LEAK ON AIR TANK. ROR PRESSURE PROTECTION VALVE TO CORRECT AIR LEAK. CLEAN ASPHALT AND MUD OUT OF WHEELS AND BALANCED AND ROTATED. RIGHT STEER TIRE WAS OUT OF ROUND AND WANTED 33 OZ OF WEIGHT. ROTATED TIRE ON RIM AND TIRE WANTED 10 OZ OF WIGHT. TOOK TIRE TO C & K SERVICE AND HAD NEW TIRE MOUNTED. LEFT STEER WHEEL IS BENT AND TIRE IS STRAIGHT, TOOK 6 OZ OF WEIGHT. RE BALANCED NEW TIRE ON RIGHT STEER WHEEL AND

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

TOOK 22 OZ OF WEIGHT AND STILL OUT OF ROUND.  
REMOVED WHEEL AND ROTATED TIRE 180 DEGREES.  
AND TIRE WANTED 21 OZ OF WEIGHT. DISMOUNTED  
AND MOUNT ANOTHER NEW TIRE AND BALANCED.  
CHECKED STEER AXLE COMPONENTS. ALIGNED  
STEER AXLE AND ADJUSTED STEER AXLE. ROAD  
TESTED TO FINISH REPAIRS.

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
5/30/12	Invoice	42308		\$1,055.96	6/12/12	584619	584629
Labor		Category		Tech		Description	
Item							
ALI		ALI		BB		ALIGNMENT SETUP CHARGE	
				MACHINE SET-UP			
SB		ALI		BM		SPIN BALANCE STEER TIRE	
				INCLUDES SET MACHINE UP. INSTALL WEIGHTS AS NEEDED.			
Parts		Description		Category		Qty	
Mfg	Item					UOM	
PET	1604831	SWITCH- MOMENTARY SET/RESUME		ELC		1 EA	
		CARRY OUT GARY					
WH	3200X6X4	PIPE ADAPTER		GEN		1 EA	
KW	223585	PRESSURE VALVE		SUS		1 EA	
TEC	300360	STICK ON WEIGHTS .5 OZ		GEN		40 OZ	
Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
1/10/12	Invoice	41448		\$1,105.93	2/21/12	581730	581738
Labor		Category		Tech		Description	
Item							
RT		GEN		MQ		ROAD TEST	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
1/10/12	Invoice	41448		\$1,105.93	2/21/12	581730	581738

Labor

Item	Category	Tech	Description
WASH	GEN	MQ	HIGH PRESSURE WASH
GEN	GEN	MQ	GENERAL OUTSIDE REPAIR WORK.

R@R ALL DRIVE AXLE SLACK ADJUSTERS AS NEEDED. SHORTEN REAR AXLE PUSH RODS AS NEEDED. TIGHTEN R.R.D. AXLE FLANGE NUTS AS NEEDED. REPLACED REAR AIR LINE BLOCK WITH NEW AS NEEDED TO REPAIR LEAK. CHECK ALL BOLTS AND HOSES. TIGHTEN COOLANT HOSE CLAMPS AS NEEDED TO REPAIR WATER SEEPING LEAK. INSTALLED UNLOADER KIT IN AIR COMPRESSOR TO REPAIR BUILDING AIR ISSUES. WASHED TOP SIDE OF TRANSMISSION AND TRY AND FIND OIL LEAK. REPLACE MISSING BOLTS IN TRANSMISSION LID TO REPAIR LEAK. CHECK TRANSMISSION OIL AS NEEDED.

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
BW	107515	UNLOADER KIT	ENG	1	EA	New
IMP	57106	1/4-20 LOCK NUT	GEN	2	EA	New
IMP	78611	1/4" FLAT WASHER	GEN	4	EA	New
IMP	16104	1/4 X 1 BOLT	GEN	2	EA	New
WH	3220X8X6	PIPE BUSHING	GEN	1	EA	
INT	91916R91	3/8 AXLE VENT	DRT	1	EA	
GUN	AS1132	SLACK ADJUSTER	BRK	4	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
10/25/11	Invoice	40968		\$1,618.83	10/25/11	0	0

Labor

Item	Category	Tech	Description
CLU1	DRT	BM	CLUTCH ADJ.

ADJUSTED CLUTCH BRAKE AND FREE TRAVEL. LUBED LINKAGES AS NEEDED.

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
-	41036ACE	PETE RADIATOR	ENG	1	EA	New
		JOHN KEIMS RADIATOR				



## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
7/14/11	Invoice	40146		\$28.17	7/14/11	0	0
Labor Item		Category	Tech	Description			
CLU1		DRT		CLUTCH ADJ.			
				ADJUSTED CLUTCH BRAKE AND FREE TRAVEL. LUBED LINKAGES AS NEEDED.			

Original Date	Type	Repair Order Number	Reference	Invoice Amount	Invoice Date	Odometer In	Odometer Out
4/4/11	Invoice	39531		\$361.21	4/7/11	552224	552234
Labor Item		Category	Tech	Description			
GEN		GEN	BB	GENERAL OUTSIDE REPAIR WORK.			
				TRUCK CAME INTO SHOP FOR C.E.L. ISSUES AND TRUCK RUNNING ISSUES. HOOK TRUCK TO COMPUTER AND CHECK CODES. R@R COOLANT LEVEL SENSOR WITH NEW AS NEEDED TO REPAIR PROBLEM. TEST DRIVE AND CHECK. CHECKED O.K.			
COMP		ENG	BB	COMPUTER HOOKUP CHARGE			
				CHECKED AND CLEARED CODES ADDRESSED FAULT TREES AS NEEDED.			

Parts Mfg	Item	Description	Category	Qty	UOM	Condition
PET	113P/86714A1	COOLANT LEVEL SENSOR	GEN	1	EA	New
Original		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
2/3/11	Invoice	39121		\$727.28	2/11/11	550587 550598
Labor						
Item		Category	Tech	Description		
RT		GEN	FM	ROAD TEST		

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
2/3/11	Invoice	39121		\$727.28	2/11/11	550587	550598

Labor

Item	Category	Tech	Description
GEN	GEN	BM	GENERAL OUTSIDE REPAIR WORK.

R@R SERVICE VALVE ABOVE PUSHER AS NEEDED TO REPAIR AIR LEAK. CHECK FOR AIR LEAKS AND DRAIN ALL TANKS, ADDED DRAINS. (NEEDS TO BE DRAINED MORE OFTEN) CHECK FOR MIRROR HEAT ISSUES, FOUND THAT MIRROR HEAT HAD NO FUSE OR RELAY INSTALLED. REPAIRED AS NEEDED. CHANGE ENGINE PARAMETERS AS REQUESTED BY CUSTOMER FOR JAKE BRAKE ISSUES. FIX ALL LIGHTS AS WELL AS LEFT HAND HEAD LIGHT. REPAIRED WIRES AS NEEDED.

\*\*\*\*\*NOTE\*\*\*\* VALVE COVER LEAKS, REAR STRUCTURE LEAKS, SHIFT TOWER GASKET LEAKS, STEERING INPUT SEAL LEAKS, R.F. BAGS ON BOTH AXLES LEAKS.

Parts	Mfg	Item	Description	Category	Qty	UOM	Condition
	WH	1460X6	3/8 SLEEVE CARRY-OUT	GEN	2	EA	
	WH	1484X6	3/8 INSERT CARRY-OUT	GEN	2	EA	
	GE	1893	BULB	ELC	1	EA	
	GE	1003	BULB	ELC	1	EA	
	GE	1004	BULB	ELC	1	EA	
	IMP	12454	M12-1.75 NUT	GEN	1	EA	New
	KAR	73027	7/8 HOSE TENDER	GEN	1	EA	
	HOW	103060	HOWES ANTIGEL	GEN	6	EA	
	BX	275491X	D-2 GOV. REMAN CARRY-OUT	BRK	1	EA	
	MID	31000	AIR BRAKE ANTIFREEZE	GEN	1	EA	New
	WH	1425	1/4 DRAIN COCK	GEN	4	EA	
	GRO	41160	REF. TAPE (150 FT.)	GEN	4	FT	New
	IMP	71287	7-1/2" ZT	GEN	8	EA	New
	IMP	71763	TRIPLE SHROUD	ELC	1	EA	New

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
2/3/11	Invoice	39121		\$727.28	2/11/11	550587	550598

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
IMP	71757	20-18 FEMALE TERM	ELC	1	EA	New
IMP	71386	WIRE ZIP TIE	GEN	5	EA	New
IMP	74002	16-14GA GRAY SEAL	ELC	5	EA	New
IMP	71755	20-18GA MALE TERM.	ELC	4	EA	New
EUC	110410	NEW SEALCO RELAY VALVE	GEN	1	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
1/26/11	Invoice	39061		\$11.26	1/31/11	0	0

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
GE	H4656	LIGHT (LOW BEAM)	ELC	2	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
1/4/11	Invoice	38906		\$393.33	1/6/11	549407	549417

Labor		Category	Tech	Description
Item				
RT		GEN	MQ	ROAD TEST

GEN GEN GENERAL OUTSIDE REPAIR WORK

SERVICE AIR DRIER AS NEEDED. R@R PROTECTION  
VALVE IN AIR TANK AS NEEDED. DRAINED BOTH AIR  
TANKS. GREASED ALL U-JOINTS AS NEEDED. NEEDS  
SOME DRIVE LINE WORK ASAP....

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
KW	223585	PRESSURE VALVE	SUS	1	EA	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
1/4/11	Invoice	38906		\$393.33	1/6/11	549407	549417

## Parts

Mfg	Item	Description	Category	Qty	UOM	Condition
BW	K022105BXW	PURGE VALVE DRYER	GEN	1	EA	New
BX	109493X	AD-IP CARTRIDGE KIT (EXCH)	BRK	1	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
12/31/10	Invoice	38881		\$3,696.39	1/12/11	549550	549560

## Labor

Item	Category	Tech	Description
RT	GEN	BM	ROAD TEST

THE TRUCK WAS ROAD TESTED BY THE DR. OR ONE OF HIS STAFF, AND THE WORK COMPLETED HAS MET HIS STANDARDS, WITH THE HIGHEST REGARDS FOR QUALITY, SAFETY, AND PERFORMANCE. REMEMBER, IF YOUR BIG TRUCK OR TRAILER IS SICK, BRING IT IN TO SEE THE TRUCK DR. AT FLOYD'S TRUCK REPAIR. THERE IS A DIFFERENCE! WE THANK YOU FOR YOUR BUSINESS. BE SAFE.

GEN GEN BM GENERAL OUTSIDE REPAIR WORK.

R@R LEFT FRONT DRIVE WHEEL SEAL. R@R ALL U-JOINTS AND TO INCLUDE NEW YOKES ON REAR DIFF., FRONT DIFF. OUTPUT, AND FRONT DIFF. INPUT AS WELL AS TRANSMISSION OUTPUT YOKE. CHECK OUTPUT BEARINGS IN TRANSMISSION. CHECKED O.K. CHECK ALL FLUID LEVELS CHECKED O.K. R@R COMPRESSOR OIL SUPPLY LINE W/NEW. CHECK PUSHER AXLE AND ADJ. TOE AS NEEDED. LEFT WHEEL SEEMS TO BE BENT. REBUILD DRIVE LINE AS NEEDED TO REPAIR PROBLEM. R@R CARRIER BEARING WITH NEW ON FRONT DRIVE LINE TO FINISH REPAIRS.

SB ALI SPIN BALANCE STEER TIRE

INCLUDES SET MACHINE UP. INSTALL WEIGHTS AS NEEDED.

Parts		Description	Category	Qty	UOM	Condition
Mfg	Item					
FIL	BF5800	FUEL FILTER CARRY-OUT	SVC	1	EA	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order	Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In Out
12/31/10	Invoice	38881		\$3,696.39	1/12/11	549550 549560
Parts						
Mfg	Item	Description	Category	Qty	UOM	Condition
FIL	BF5810	FUEL FILTER CARRY-OUT	SVC	1	EA	
FIL	B495	DETROIT OIL FILTER CARRY-OUT	SVC	2	EA	
ROW	18N28117	WELD YOKE	GEN	1	EA	New
ROW	18N43891	C/B END YOKE	GEN	1	EA	New
SPI	LAB155	BALANCE 2/PC 1760/UP	DRT	1	EA	New
-	LAB125	(2) WELDS 1760 & UP	GEN	1	EA	New
LAB	LAB110	(1) WELD 1760/1810	GEN	1	EA	New
SPI	5281X	U-JOINT	DRT	3	EA	New
SPI	231502	NUT(1 1/4" 18 THD	DRT	1	EA	New
SPI	36301027300	TUBE	GEN	1	EA	New
SPI	6.5-53-91	MIDSHIP STUB	GEN	1	EA	New
SPI	5003323	CARRIER BEARING	DRT	1	EA	New
SPI	6528117	YOKE	DRT	1	EA	New
SPI	6531371KX	SLIP YOKE	DRT	1	EA	New
-	6-4-9181X	YOKE ASSY	GEN	1	EA	New
-	6-4-9191X	YOKE ASSY	GEN	1	EA	New
-	FREIGHT	FREIGHT		1	EA	
-	210736	INPUT SEAL (DS461)	GEN	1	EA	New
-	210737	OUTPUT SEAL	GEN	1	EA	New
EAT	126155	INPUT NUT (DS461)	GEN	1	EA	New
NAT	210724	SEAL	GEN	1	EA	New
EAT	128049	M42X1.5 METRIC NUT FRONT DS404	DRT	2	EA	
IMP	42314	1/2-13 LOC NUT	GEN	2	EA	New
IMP	76174	1/2 LOCK WASHER	GEN	2	EA	New
IMP	78615	1/2" FLAT WASHER	GEN	4	EA	New
IMP	16200	1/2 X 2 BOLT	GEN	2	EA	New
IMP	42318	5/8-11 LOC NUT	GEN	1	EA	New
IMP	16244	5/8 X 3 BOLT	GEN	1	EA	New

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
12/31/10	Invoice	38881		\$3,696.39	1/12/11	549550	549560
Parts							
Mfg	Item	Description	Category	Qty	UOM	Condition	
STR	H21304-250R	#4 LINE	GEN	1	EA	New	
STR	P23921-4-4	90 DEGREE SWIVEL	GEN	1	EA		
STR	4M	#4 MALE SWIVEL	GEN	1	EA		
PRI	327	TUBE GREASE	SVC	1	EA		
ECU	E3479	CAMSHAFT WASHER	BRK	2	EA		
ROC	19X127	CLEVIS PIN	BRK	1	EA	New	
IMP	70708	3/32 X 3/4" COTTER PIN	GEN	2	EA	New	
BW	201225	SLACK BUSHING	BRK	1	EA		
IMP	70722	1/8 X 1" COTTER PIN	GEN	1	EA	New	
IMP	70708	3/32 X 3/4" COTTER PIN	GEN	1	EA	New	
ROC	19X127	CLEVIS PIN	BRK	1	EA	New	
BW	202550	1/2 PIN	BRK	1	EA		
CR	47697	SEAL NAT#370003A	DRT	1	EA		
INT	91916R91	3/8 AXLE VENT	DRT	1	EA		
ECU	E2435	AXLE GASKET	DRT	1	EA		
FUL	K2918	SEAL KIT	DRT	1	EA	New	
FUL	4306520	NUT	GEN	1	EA	New	
SPI	5280X	U-JOINT	DRT	2	EA	New	
TEC	300360	STICK ON WEIGHTS	GEN	27	OZ		
Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
12/1/10	Invoice	38660		\$4,101.68	12/10/10	548288	548298
Labor							
Item		Category	Tech	Description			
RT		GEN	BB	ROAD TEST			

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
12/1/10	Invoice	38660		\$4,101.68	12/10/10	548288	548298

Labor

Item	Category	Tech	Description
GEN	GEN	BB	GENERAL OUTSIDE REPAIR WORK.

R@R REAR SWAY BAR SUSPENSION W/NEW  
 UPDATED SUSPENSION BARS. R@R DRIVE AXLE  
 SHOCKS LOWER BUSHING WITH NEW. R@R ALL  
 UPPER TORQUE TOD BUSHINGS. REPLACE AND  
 TIGHTEN LEAKING AIR FITTINGS ON REAR. CHECK  
 THREE AXLE ALIGNMENT. R@R FAN AND  
 ALTERNATOR BELTS. R@R ALTERNATOR PULLEY  
 W/NEW. AFTER TEST DRIVE FLOYD FOUND COOLANT  
 LEAK. R@R HOSE CLAMP WITH NEW AS NEEDED TO  
 REPAIR PROBLEM.

Parts

Mfg	Item	Description	Category	Qty	UOM	Condition
KW	HWC01021	SHOCK WASHER	SUS	4	EA	New
-	CT350	3.5" HOSE CLAMP	GEN	1	EA	New
MCY	7753	PULLEY	GEN	1	EA	New
DYN	22550	FAN BELT	ENG	2		
DYN	17611	BELT	ENG	2		
IMP	71379	15-1/4 CABLE TIE	GEN	4	EA	New
INT	C604100	AIR LINE 1/4	GEN	2.5	FT	
WH	1462X4	1/4 UNION	GEN	2	EA	
KW	K066266	KENWORTH SHOCK BUSHINGS	GEN	4	EA	New
IMP	42318	5/8-11 LOC NUT	GEN	14	EA	New
IMP	16250	5/8 X 5 BOLT	GEN	8	EA	New
-	839310	BUSHING	GEN	8	EA	New
-	C65-1000	BAR ASSY. CONV. 200	SUS	2	EA	New
-	C13-1007	CONV. KIT (AG400)	GEN	1	EA	New

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
8/24/10	Invoice	37937		\$237.93	8/25/10	547980	547990

Labor

Item	Category	Tech	Description
RT	GEN	BM	ROAD TEST

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
8/24/10	Invoice	37937		\$237.93	8/25/10	547980	547990

Labor

Item	Category	Tech	Description
CLU1	DRT	BM	CLUTCH ADJ.

ADJUSTED CLUTCH BRAKE AND FREE TRAVEL.  
LUBED LINKAGES AS NEEDED.

GEN	GEN	BM	GENERAL OUTSIDE REPAIR WORK.
-----	-----	----	------------------------------

R@R CLUTCH BRAKE WITH NEW AS NEEDED TO  
REPAIR ISSUE. ADJUST CLUTCH AS NEEDED. FREE  
UP ADJUSTMENT LINKAGE AND GREASE.

Parts Mfg	Item	Description	Category	Qty	UOM	Condition
BAB	SB200	CLUTCH BRAKE	DRT	1	EA	

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
7/29/10	Invoice	37727		\$3,193.83	8/10/10	546017	546027

Labor

Item	Category	Tech	Description
A/C	A/C	MQ	A/C SETUP CHARGE
GEN	GEN	MQ	GENERAL OUTSIDE REPAIR WORK.

INSTALLED USED EVAPORATOR. INSTALLED NEW  
COIL PLATES AND THERMOSTAT. INSTALLED NEW  
CONDENSER AND BRACKETS AS NEEDED.  
INSTALLED USED A/C COMPRESSOR WITH NEW  
CLUTCH AND BELTS AS NEEDED. INSTALLED NEW  
RECEIVER DRIER AND EXPANSION VALVE. MADE  
NEW HOSES AND CLAMPED IN PLACE. WIRE SYSTEM  
AS NEEDED. R@R AIR SWITCH FOR FAN CLUTCH  
LIGHT AS NEEDED TO FINISH REPAIRS.

RT	GEN	MQ	ROAD TEST
----	-----	----	-----------

Parts Mfg	Item	Description	Category	Qty	UOM	Condition
BEL	737299	1/4 SPLIT LOOM	GEN	7.5	FT	



## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
7/29/10	Invoice	37727		\$3,193.83	8/10/10	546017	546027
Parts							
Mfg	Item	Description	Category	Qty	UOM	Condition	
KAR	ELECCONN	VARIOUS ELE. CONNECTIONS	GEN	2	EA		
-	467002	COVER	GEN	1	EA	New	
TSC	1	COMP WEATHER PACK KIT	ELC	2	EA		
KAR	WIRE	MISC WIRE	GEN	7.5	FT		
KW	USED	A/C COMPRESSOR	GEN	1	EA	Used	
KW	USED	USED EVAPORATOR	GEN	1	EA	Used	
AC	ESOIL	ESTER OIL	GEN	8	OZ		
AC	R134A	FREON	GEN	3.4	LBS		
KAR	ZT	ZIP TIES	GEN	27	EA		
DAY	D20542798	#12 MALE STRAIGHT W/#10 NUT	A/C	1	EA	New	
DAY	D20542863	#12 FEMALE 90DEG W/#10 NUT	A/C	1	EA	New	
STR	21310	#10 LINE	GEN	8	FT		
DAY	D20542629	#8 FEMALE 90DEG 3/4 -16	A/C	1	EA	New	
STR	H21308-250R	#8 LINE	GEN	3	FT	New	
DAY	D20542512	#6 MALE STRAIGHT	A/C	1	EA	New	
DAY	D20542551	#6 FEMALE STRAIGHT	A/C	2	EA	New	
STR	H21306-250R	# 6 LINE	GEN	7	FT	New	
KAR	48	HOSE CLAMP	GEN	2	EA		
-	CLAMP	MISC. HOSE CLAMP/TENDER	GEN	11	EA	New	
KAR	14W	FLAT WASHER	GEN	24	EA	New	
KAR	516W	FLAT WASHER	GEN	6	EA		
KAR	516LN	LOCK NUT	GEN	3	EA		
KAR	516X1	BOLT	GEN	3	EA		
KAR	14N	NUT	GEN	6	EA		
KAR	14X34	BOLT	GEN	6	EA		
KAR	84610	5/16 X 1 1/4 FENDER WASHER	GEN	4	EA		
-	HE1060	EXPANSION BRACKET	GEN	1	EA	New	
WH	48X10	CONNECTOR	GEN	1	EA		
AC	EA1090	EXPANSION VALVE	GEN	1	EA		
KW	7605131	N/O SWITCH	ELC	1	EA	New	

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
7/29/10	Invoice	37727		\$3,193.83	8/10/10	546017	546027
<b>Parts</b>							
Mfg	Item	Description	Category	Qty	UOM	Condition	
BEL	735310	2-WIRE LOOM	ELC	1	FT	New	
DYN	17611	BELT	ENG	2			
KW	K27565162R	CONDENSER BRACKET	GEN	1	EA	New	
KW	K2756519	CONDENSER BRACKET	GEN	1	EA	New	
KW	K066422	CONDENSOR MOUNT	GEN	4	EA	New	
-	FREIGHT	FREIGHT OUT		1	EA		
-	K27565162	CONDENSER BRACKET	GEN	1	EA	New	
-	K3161209	RECEIVER DRYER BRACKET	GEN	1	EA	New	
-	D90134018	FREON HOSE	GEN	1	EA	New	
-	K2756552	CONDENSER BRACKET	GEN	2	EA	New	
KW	K2756519R	CONDENSER BRACKET	GEN	1	EA	New	
DYN	D20583171	A/C FITTING	A/C	1	EA	New	
CT	KA1040	A/C CLUTCH	A/C	1	EA	New	
KW	GD1135	DRYER	A/C	1	EA	New	
-	868028	PLATE ASSY	GEN	1	EA	New	
KW	BD1355	THERMO STAT SWITCH ASSY.	A/C	1	EA	New	

Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
5/28/10	Invoice	37344		\$480.62	6/24/10	54514	54514

Labor		Category	Tech	Description
Item				
GEN		GEN	MQ	GENERAL OUTSIDE REPAIR WORK.

REPAIR AIR LINE, LOOK AT LIGHTS NEED MORE TIME.

DATE 5/25/2010

GEN	GEN	MQ	GENERAL OUTSIDE REPAIR WORK.
TRUCK CAME INTO SHOP FOR AN AIR LEAK. FOUND LINE LEAKING AND REMOVED AIR LINE AS NEEDED, WAS NOT BEING USED. TIGHTEN CLEVIS JAM NUT ON RIGHT PUSHER AXLE AND REPLACED LEAKING AIR BRAKE HOSE END. R@R LEVELING VALVE WITH NEW AS NEEDED TO REPAIR PROBLEM.			

## Vehicle Service History Report

KEIM, GARY

2000 KENWORTH W-900 Fleet#:2, Vin:852449

Original (continued)		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
5/28/10	Invoice	37344		\$480.62	6/24/10	54514	54514
Parts							
Mfg	Item	Description		Category	Qty	UOM	Condition
SLN	431402	QUICK FIX AIR FITTING KIT		BRK	1	EA	New
KAR	ZT	ZIP TIES		GEN	6	EA	
WH	1461X4	1/4 NUT		GEN	1	EA	
NEW	90054007	LEVELING VALVE		SUS	1	EA	
WH	1460X4	1/4 SLEEVE		GEN	1	EA	
INT	C604100	AIR LINE 1/4		GEN	4.5	FT	
WH	1462X4	1/4 UNION		GEN	1	EA	
KW	Q211043622	FUEL SENDER		ELC	1	EA	New
CARRY-OUT							
Original		Repair Order		Invoice		Odometer	
Date	Type	Number	Reference	Amount	Date	In	Out
5/21/10	Invoice	37290		\$150.33	5/21/10	542045	542045
Labor							
Item		Category	Tech	Description			
CLU1		DRT	MQ	CLUTCH ADJ.			
ADJUSTED CLUTCH BRAKE AND FREE TRAVEL.							
LUBED LINKAGES AS NEEDED.							
GEN		GEN	MQ	GENERAL OUTSIDE REPAIR WORK.			
TAPPED BOLT HOLES AND INSTALLED USED HAND							
HOLE COVER. REPLACED AIR COMPRESSOR INLET							
GASKET AS NEEDED.							
Parts							
Mfg	Item	Description		Category	Qty	UOM	Condition
CUM	3865195	GASKET		ENG	1	EA	New