Invoice To Account No.: 1112	Deliver To:	* * * DOCUMENT COPY	*** SER	VICE INVOICE
WITTWER FARMS LLC		WITTWER FARMS, L.L.C. 4615 W. LAKEVIEW		543749
PO BOX 1149			Invoice Date:	2/20/2013
STILLWATER OK 74076-1149	STILLWATER OR	STILLWATER OK 74075		10
			Work Order Number:	90876
	•		Payment Type:	Finance
Bus Phone: 405-372-1213	Bus Phone: 405-3	72-1213		
Prv Phone:	Prv Phone:		Page:	1 of 5

Make/Model: JOHN DEERE 9600
Meter Reading: 5889
Serial Number: 656176
Equipment Number: 9600WITF

## **GEN- Retail**

COMPLAINT:

SERVICE REQUEST: CHECK ENGINE, RUNS ROUGH, HAS FUEL IN OIL, MISSES WHEN RUNS, LOW POWER AND OIL LEAKING ON THE BACK SIDE OF THE ENGINE.

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED:

CORRECTION:

\$2,517.30

Service Accessories

SERVICE REQUEST: CHECK ENGINE, RUNS ROUGH, HAS FUEL IN OIL, MISSES WHEN RUNS, LOW POWER AND OIL LEAKING ON THE BACK SIDE OF THE ENGINE.

DIAGNOSIS: ENGINE MISSES, LEAKS AND RUNS ROUGH DUE TO FAILED INJECTION NOZZLES AND A BLOWN HEAD GASKET.  $\cdot$ 

SERVICE PERFORMED: REMOVED BIN EXTENSIONS AND TESTED ENGINE COMPONENTS AND REMOVED INJECTORS AND TESTED AND FOUND BAD. REMOVED CYLINDER HEAD AND SENT TO MACHINE SHOP TO HAVE RECONDITIONED. REINSTALLED HEAD WITH NEW GASKETS, BOLTS AND INJECTORS. ADJUSTED VALVES TO SPECS. REPLACED ENGINE OIL, OIL FILTER, FUEL FILTER, AND ANTI-FREEZE WITH NEW. CLEANED UP THE AIR FILTER HOUSING AND BRAZED BROKEN OUT PIECE. RAN MACHINE AND CHECKED OPERATION AND REINSTALLED BIN EXTENSIONS.

CYLINDER HEAD RECONDITION.

## CYLINDER HEAD RECONDITION.

Part Number	Description	<b>Quantity</b>	Unit Nett	<u>Value</u>	Taxed Ind
19H2128	Cap Screw	8.00	1.66	\$13.28	N
3750	FREIGHT	8.00	2.50	\$20.00	N
AR86745	Filter Element	1.00	20.81	\$20.81	N
R110286	Cap Screw	5.00	15.61	\$78.05	N

## Iteam # F7808

Invoice To Account No.: 1112		Deliver To:	* * * DOCUI	MENT COPY * * *		SERVI	<b>CE INVO</b>	ICE
WITTWER FARMS LLC		WITTWER FARMS	3, L.L.C.		nvoice Nun	nber:	54	3749
PO BOX 1149		4615 W. LAKEVIE			Invoice I	Date:	2/20	/2013
STILLWATER OK 74076-1	149	STILLWATER OK	. 74075		Loca	ation:		10
				Wo	rk Order Nur	nber:		90876
`					Payment <sup>-</sup>	Гуре:	Fi	nance
Bus Phone: 405-372-1213		Bus Phone: 405-3	72-1213			5		
Prv Phone:		Prv Phone:			F	age:		2 of 5
					Make/M	odel:	JOHN DEERE	9600
					Meter Rea	ding:		5889
					Serial Nur	nber:	. 6	56176
				Eq	uipment Nur	nber:	9600	WITF
GEN- Retail				<u> </u>				
R110288	Cap Screw				8.00	17.30	\$138.40	N
R110289	Cap Screw		•		7.00	19.35	\$135.45	N
R121320	Cap Screw				6.00	6.06	\$36.36	N
R63845	Washer				8.00	1.24	\$9.92	Ν
R76337	Washer				1.00	2.11	\$2.11	Ν
R86062	GASKET				1.00	3.54	\$3.54	N
RE526730 <sup>^</sup>	Gasket Kit				1.00	230.30	\$230.30	N
RE57394	OIL FILTER				1.00	16.20	\$16.20	N
SE501140	Injection Noz	zle Reman			6.00	111.91	\$671.46	N
SE501140-CR	CORE for:Inje	ection Nozzle Reman	1		-6.00	10.00	(\$60.00)	N
TY26576	COOL-GARD	)	•		3.00	33.72	\$101.16	N
TY26673	Plus-50 II Oil	15W40 CJ4/SN			2.00	17.75	\$35.50	Ν
TY26675	Plus-50 II Oil	15W40 CJ4/SN			2.00	43.64	\$87.28	N
Labor: \$2,250.00	Parts: \$1,5	19.82 OL&	M: \$267.30	Misc: \$	20.00	Sub-To	tal: \$4,057.12	

/Pick Up & Deliver Retail COMPLAINT:

Pick Up & Deliver

CORRECTION:

PICKUP COMBINE AND HAUL TO SHOP. CUSTOMER TOOK MACHINE HOME WHEN REPAIRS WERE COMPLETED.

<u>Part Number</u>	<u>Description</u> 40HP+ TRANSPORT FEE, ZONE 3		Quantity	<u>Unit Nett</u>	<u>Value</u>	Taxed Ind
5230			1.00	165.00	\$165.00	N
Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$165.00	Sub-Tota	ıl: \$165.00	

**GEN-1 Retail** COMPLAINT:

Invoice To Account No.: 1112	Deliver To:	* * * DOCUMENT CO	<u> </u>	ERVICE INVOICE
WITTWER FARMS LLC PO BOX 1149 STILLWATER OK 74076-1149	WITTWER FARMS, L.L.C. 4615 W. LAKEVIEW STILLWATER OK 74075		Invoice Number: Invoice Date:	<b>543749</b> 2/20/2013
	·		Location: Work Order Number:	10 90876
	_		Payment Type:	Finance
Bus Phone: 405-372-1213	Bus Phone: 405-37	72-1213		
Prv Phone:	Prv Phone:		Page:	3 of 5
			Make/Model:	JOHN DEERE 9600
			Meter Reading:	5889
	(		Serial Number:	, 656176
		•	Equipment Number:	9600WITF

GEN-1 Retail

SERVICE REQUEST: Check and repair the leaking feederhouse lift cylinder.

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED:

CORRECTION:

SERVICE REQUEST: Check and repair the leaking feederhouse lift cylinder.

DIAGNOSIS: CYLINDER LEAKING DUE TO FAILED SEALS.

SERVICE PERFORMED: RECONDITIONED BOTH FEEDER HOUSE LIFT CYLINDERS AND RAN AND CHECKED OPERATION AND FOR LEAKS.

Labor: \$270.00	Parts: \$119.31	OL&M: \$0.00	Misc: \$0.00	Sub-T	otal: \$389.31	
TY26101	Cleaning Solvent		2.00	4.92	\$9.84	N
AH139756	Hydraulic Cylinder Kit		1.00	57.35	\$57.35	N
Part Number AH139755	<u>Description</u> Hydraulic Cylinder Kit	,	<u>Quantity</u> 1.00		<u>Value</u> \$52.12	<u>Taxed Ind</u> N

**GEN-2 Retail** COMPLAINT:

SERVICE REQUEST: CHECK AND REPAIR OIL LEAK FROM UNDER CAB.

DIAGNOSIS:

SERVICE QUOTE:

SERVICE PERFORMED:

CORRECTION:

\$540.00

\$270.00

**SERVICE INVOICE** \* \* \* DOCUMENT COPY \* \* \* Invoice To Account No.: 1112 Deliver To: WITTWER FARMS LLC WITTWER FARMS, L.L.C. 543749 **Invoice Number:** PO BOX 1149 4615 W. LAKEVIEW Invoice Date: 2/20/2013 STILLWATER OK 74076-1149 STILLWATER OK 74075 Location: 10 Work Order Number: 90876 Payment Type: Finance Bus Phone: 405-372-1213 Bus Phone: 405-372-1213 5 of 5 Prv Phone: Prv Phone: Page: JOHN DEERE 9600 Make/Model: Meter Reading: 5889 Serial Number: 656176 Equipment Number: 9600WITF Gen-3 Retail Misc: \$0.00 Sub-Total: \$270.00 Labor: \$270.00 Parts: \$0.00 OL&M: \$0.00 Miscellaneous Charges: \$70.00 Service Accessories **Finance Information** Labor: \$3,330.00 \$1,789.71 Customer PO No: Type: Multi-use Acct US 508065 Parts: Auth. No: \$267.30 OL&M: Merchant No: 57000231 Tax Exempt No: SMX 669691 \$255.00 **BARRY DENNEY** Misc: Advisor: Card No: xxxxxxxxxxx5192 \$0.00 Sales Tax: Bill Code: 705 - JD COMBINE PARTS/SERVICE Credit Plan: 249 - PURCHASE \$5,642.01 Total: