

SERVICE INVOICE

Claas Financial Services LLC
475 Sansome Street, 19th Floor
San Francisco CA 94111 US

Ship To:
Claas Financial Services LLC

Opened: 11/6/2015
Work Order No: 04-35230
My Reference: 740 C4800338

Responsible Tech: JBrown
Pickup Date:
Delivery Date:

Shop					
Item/Tag	Type	Description/Model/Serial Number	Quantity	Tax	Price
01-inspect					
Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours					
01-inspect					
3120M	PA	OTH - OIL SAMPLE MAILER	2.00	N	
	SL	Customer - In Shop		N	
Total 01-inspect					
01- SERVICE					
Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours					
complete service of all oils and filters					
	SL	Customer - In Shop		N	
1R-1808	PA	OTH - Oil Filter	1.00	N	
423-8524	PA	OTH - FUEL FILTER	1.00	N	
1R-0749	PA	OTH - Fuel Filter TIER 4	2.00	N	
0773672	PA	CLA - FILTER ELEMENT	1.00	N	
0773821	PA	CLA - FILTER SAFTEY CAR	1.00	N	
1474370	PA	CLA - AGRIGREASE EP 2 - (24	12.00	N	
1474450	PA	CLA - AGRHYD HV 46 Multigrade	2.00	N	
1474830	PA	CLA - AGRIMOT ULTRATEC 10W-40	2.00	N	
5100541	PA	CLA - FILTER ELEMENT	1.00	N	
1474300	PA	CLA - AGRISHIFT MT 80W-90	3.00	N	
5596460	PA	CLA - POCKET FILTER	2.00	N	
Total 01- SERVICE					
02-chopper					
Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours					
replace all chopper knives					
	SL	Customer - In Shop		N	
3531950	PA	CLA - KNIFE SECTION	72.00	N	

SERVICE INVOICE

Claas Financial Services LLC
475 Sansome Street, 19th Floor
San Francisco CA 94111 US

Ship To:
Claas Financial Services LLC

Opened: 11/6/2015
Work Order No: 04-35230
My Reference: 740 C4800338

Responsible Tech: JBrown
Pickup Date:
Delivery Date:

Shop

Total 02-chopper

08- belts

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

replace bubble up chain and radiator suction fan belt tension all other belts and chains

	SL	Customer - In Shop		N
7952661	PA	CLA - ROLLER CHAIN	1.00	N
6707241	PA	CLA - POWER BAND BELT	1.00	N
6609611	PA	CLA - V-BELT	1.00	N

Total 08- belts

04-yield meter

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

replace yield meter photo eye covers

	SL	Customer - In Shop		N
0116160	PA	CLA - SENSOR	2.00	N

Total 04-yield meter

05 Front Panel

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

replace front panel and sticker

	SL	Customer - In Shop		N
5063570	PA	CLA - FRONT PANEL	1.00	N
1141160	PA	CLA - STICKER	1.00	N

Total 05 Front Panel

06-Concave

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

06-Concave adjust and level and clean out

	SL	Customer - In Shop		N
--	----	--------------------	--	---

Total 06-Concave

SERVICE INVOICE

Claas Financial Services LLC
475 Sansome Street, 19th Floor
San Francisco CA 94111 US

Ship To:
Claas Financial Services LLC

Opened:	11/6/2015	Responsible Tech:	JBrown
Work Order No:	04-35230	Pickup Date:	
My Reference:	740 C4800338	Delivery Date:	

Work Ok'd per Kirby Fiegel by email

Shop

07- Wash/Detail

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

07- Wash/Detail Wash and detail machine and cab

SL Customer - In Shop N

Total 07- Wash/Detail

14Feild Ready

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

14Feild Ready

SL Customer - In Shop N

CLFRR700 PA CLA - FRR KIT - 700 SERIES 1.00 N

Total 14Feild Ready

02 Blow off

Unit:653 740, NN11-116, C4800338, 740 C48/200, New 1,031.0 Hours

Machine was very dirty when it was received from Customer blow off to inspect

SL Customer - In Shop N

Total 02 Blow off

Labor

Parts

Sub Total

Total Tax

Invoice Total

Cust Open Acct

Customer Id: CLAAS FINANCIAL

ON Account

Signature:_____

\$9,386.23

\$9,386.23